





report date: 2024-03-28

### General information

Make	FORD
Model	ESCORT GTI 115PS 16V
Colour	Blue
Year of manufacture	1997
Top speed	122 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	114 BHP
Max. torque 160 Nm at 4.500 rpr	
Engine capacity	1.796 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

### Internet history

#### Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/15



R580CH report date: 2024-03-28

MOT history

MOT expiry date	2022-02-28
MOT pass rate	52 %
MOT passed	14
Failed MOT tests	13
Total advice items	20
Total items failed	55

MOT #27		2021-03-01 15:59
MOT test	number	347636906932
Result		✓ Passed
Next expi	ry date	2022-02-28
Advice	All under vehicle heavily undersealed	
Advice Brake pipe corroded, covered in grease or other material all pipes undersealed (1.1.11 (c))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #26		2021-02-25 15:48
MOT test	number	561437651822
Result		🗙 Failed
Advice	Coolant leak	
Advice Brake pipe corroded, covered in grease or other material all pipes undersealed (1.1.11 (c))		
Advice	All under vehicle heavily undersealed	
Fail Ex	haust carbon monoxide content after 2nd fast idle exceeds default limits	(8.2.1.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #25** 2019-11-04 16:48 **MOT test number** 651367617806 Result ✓ Passed Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Nearside Front Subframe mounting prescribed area is corroded but not considered excessive **Advice** (5.3.6 (a) (i)) Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Washers weak **Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #24	2018-04-06 07:20	
MOT test number	832300960456	
Result	✓ Passed	
MOT #23	2017-04-11 13:43	
MOT test number	637808142654	
Result	✓ Passed	
MOT #22	2017-04-11 13:43	
MOT test number	300674710897	
Result	<b>★</b> Failed	
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Pass with rectification	Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	

MOT #21	2016-04-04 08:22
MOT test number	754066875422
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/15



R58OCH

report date: 2024-03-28

MOT test number

Result

Nearside Front Suspension arm has excessive play in a pin/bush front (2.4.G.2)

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Suspension arm has excessive play in a pin/bush rear (2.4.G.2)

Fail Centre Exhaust has a major leak of exhaust gases clamp missing (7.1.2)

MOT #19

MOT test number

Result

Advice Nearside Front Front wheel bearing has slight play (2.5.A.3c)

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

2015-04-04 10:59 **MOT #18 MOT** test number 776194795034 Result × Failed Pass with rectification Nearside Rear Shock absorber has a serious fluid leak (2.7.3) Pass with rectification Offside Rear Tyre has ply or cords exposed (4.1.D.1b) **Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c) Pass with rectification Offside Front Track rod end ball joint has excessive play (2.2.B.1f) Pass with rectification Nearside Front Tyre has ply or cords exposed (4.1.D.1b) **Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

 MOT #17
 2014-04-02 09:19

 MOT test number
 165752294409

 Result
 ✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #16

MOT test number

965902094031

Result

Pass with rectification

Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

Pass with rectification

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #15 2013-04-10 11:30 **MOT** test number 487310103184 Result ✓ Passed MOT #14 2013-04-10 11:30 588330503173 **MOT test number** Result × Failed **Pass with rectification** Offside Front Side repeater not working (1.4.A.2c) **Pass with rectification** Nearside Front Side repeater not working (1.4.A.2c) **Pass with rectification** Offside Front Brake hose excessively damaged (3.6.B.4d)

CarCheck.co.uk page 6/15



R58OCH

report date: 2024-03-28

MOT #13 2013-03-25 10:03

**MOT test number** 657674983014

**Result** X Failed

**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside Seat belt anchorage prescribed area is excessively corroded (5.2.6)

**Fail** Registration plate lamp not working (1.1.C.1d)

**Fail** Offside front brake binding (3.7.B.1)

**Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Fail** Front brakes release unevenly (3.7.B.4)

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Fail** Brakes imbalanced across an axle (3.7.B.5b)

**Fail** Nearside Seat belt anchorage prescribed area is excessively corroded (5.2.6)

**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**Fail** Offside Front coil spring fractured (2.4.C.1a)

**Fail** Front brake application uneven (3.7.B.2)

Fail Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #12** 2011-07-13 15:39

**MOT test number** 117634891187

**Result** ✓ Passed

CarCheck.co.uk page 7/15



R58OCH

report date: 2024-03-28

**MOT #11** 2011-07-08 11:21 **MOT** test number 267429181172 Result × Failed Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Pass with rectification Nearside Headlamp aim too low (1.8) Nearside Brake cable has restricted free movement (3.5.1k) Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Pass with rectification Offside Headlamp aim too high and too far to the left. (1.8) Fail Nearside Front Brake pipe fouled by moving parts (3.6.B.2a) Fail Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #10 2010-07-07 14:49

MOT test number 980268880159

Result ✓ Passed

**MOT #9** 2010-07-06 16:03 820897580195 **MOT** test number Result × Failed Notice Back box corroded Fail Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)Fail Offside Front Front constant velocity joint gaiter split (2.5.C.1a) Notice Rear chassis Fail Nearside Front Brake pipe fouled by moving parts (3.6.B.2a) Fuel system component leaking (7.2.3) Fail

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT #8	2009-07-07 12:43
MOT test number	742158389120
Result	✓ Passed
MOT #7	2009-07-06 09:31
MOT test number	760137989103
Result	<b>×</b> Failed
Fail Offside Front coil spring fractured (2.4.C.1a)	
Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)	

MOT #6	2008-07-09 11:33
MOT test number	934271598125
Result	✓ Passed
MOT #5	2008-07-08 10:33
MOT test number	471500098194
Result	<b>X</b> Failed
Notice O/s/f fog not working	
Fail Nearside Front Brake pipe excessively corroded (3.6.B.2c)	

MOT #4	2007-07-04 15:47
MOT test number	272965787469
Result	✓ Passed

CarCheck.co.uk page 9/15



report date: 2024-03-28

MOT #	3	2007-07-03 16:14
MOT te	st number	723694787182
Result		<b>×</b> Failed
Fail	Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Offside Front brake disc excessively scored (3.5.1h)	
Fail	Offside Front Rear fog lamp not working (1.3.2b)	
Fail	Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail	Nearside Rear Rear wheel bearing rough when rotated (2.6.1)	

MOT #2	2006-07-12 10:25
MOT test number	354443696150
Result	<b>✓</b> Passed
MOT #1	2006-07-10 10:41
MOT test number	241831496156

Result

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)

Fail Nearside Front coil spring incomplete (2.4.C.1a)

CarCheck.co.uk page 10/15



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

### Owner history

,	
For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NE STE
Plate since	
	More info

CarCheck.co.uk page 12/15



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	1997-08-01
Last registration	2021-03-01
Complete history	See info



Registration #1	1997-08-01	26 mi
Registration #2	2006-07-10	87.089 mi
Registration #3	2006-07-12	87.089 mi
Registration #4	2007-07-03	91.942 mi
Registration #5	2007-07-04	91.942 mi
Registration #6	2008-07-08	96.272 mi
Registration #7	2008-07-09	96.272 mi
Registration #8	2009-07-06	582 mi
Registration #9	2009-07-07	582 mi
Registration #10	2010-07-06	4.135 mi
Registration #11	2010-07-07	4.135 mi
Registration #12	2011-07-08	7.424 mi
Registration #13	2011-07-13	7.455 mi
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 esi
Registration #24		71.777 es
Registration #25		11.777 es
Registration #26		77.777 au

CarCheck.co.uk page 14/15



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1875 mm
Height	1346 mm
Length	4138 mm

### Additional information

Number of axles	2
Engine number	VB82597

CarCheck.co.uk page 15/15