



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDI
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	44.8 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-11-11
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-12-08
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	75
Total items failed	25

**MOT #21**

2023-02-27 16:59

MOT test number

363192342670

Result**✗ Failed**

- Fail** Rear Brakes imbalanced across an axle o/s (1.2.1 (b) (i))
- Fail** Offside Rear Brake disc significantly and obviously worn outer disc face (1.1.14 (a) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Poor (1.1.14 (a) (ii))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Integral body structure is corroded but structural rigidity is not significantly reduced corrosion to inner sill's (6.1.1 (c) (i))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Poor (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake hose slightly deteriorated both, x2 (1.1.12 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner tyre worn smooth near cord's, tread 4mm (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords more than one (5.2.3 (d) (i))
- Advice** Nearside Front Inner Integral body structure is corroded but structural rigidity is not significantly reduced wheel arch (6.1.1 (c) (i))
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside corrosion to outer sill
- Fail** Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt hub to lower arm (5.3.4 (b) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner tyre worn smooth near cord's, tread 3mm (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Fail** Offside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill to outer sill and inner lower wheel arch sill end (5.3.6 (a) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Parking brake Poor

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Fail Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced inner mid front sill (6.1.1 (c) (i))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced Heavy under body corrosion all over, under body in Poor condition (6.1.1 (c) (i))

Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Inner Steering linkage ball joint has excessive play inner Tie Rod end, steering rack (2.1.3 (b) (i))

Advice Offside Integral body structure is corroded but structural rigidity is not significantly reduced corrosion to inner sill's (6.1.1 (c) (i))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside corrosion to outer sill

Advice Offside Rear Brake hose slightly deteriorated both, x2 (1.1.12 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner tyre worn smooth near cord's, tread 4mm (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced Inner wheel arch (6.1.1 (c) (i))

Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

Fail Nearside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill to outer sill and inner lower wheel arch sill end (5.3.6 (a) (i))

Fail Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Rear 3ed Row seat's not fitted,

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #20** 2021-12-09 14:25**MOT test number** 192874116793**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #19** 2021-01-26 14:38**MOT test number** 167800729611**Result** ✓ Passed**MOT #18** 2020-02-11 13:03**MOT test number** 400145493266**Result** ✓ Passed**MOT #17** 2019-02-25 13:09**MOT test number** 793027616968**Result** ✓ Passed**MOT #16** 2019-02-25 13:09**MOT test number** 966140373513**Result** ✗ Failed**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #15** 2018-05-31 13:19**MOT test number** 237244374929**Result** ✓ Passed

**MOT #14** 2018-05-29 14:33**MOT test number** 460902788572**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**MOT #13** 2017-06-12 11:23**MOT test number** 541283919516**Result** ✓ Passed**Advice** Nearside door mirror been resecured with tape**MOT #12** 2016-06-07 10:15**MOT test number** 526771670267**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** NSF mirror damaged**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)



MOT #11	2015-06-05 15:47
MOT test number	368276155160
Result	✓ Passed
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Notice	Under-trays fitted obscuring some underside components

MOT #10	2015-06-05 10:57
MOT test number	849646255124
Result	✗ Failed
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Notice	Under-trays fitted obscuring some underside components
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #9** 2014-06-09 10:15**MOT test number** 237320664470**Result** ✓ Passed

- Notice** Chips in screen
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seats fitted not allowing full inspection of adult belts

MOT #8 2014-06-06 11:09**MOT test number** 508037954182**Result** ✗ Failed

- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Chips in screen
- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Fail** Nearside Front suspension retaining device ineffective (2.5.A.4)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seats fitted not allowing full inspection of adult belts

MOT #7 2013-05-29 08:55**MOT test number** 416309743195**Result** ✓ Passed

**MOT #6** 2012-05-30 11:41**MOT test number** 926141452152**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** OSR tyre perished**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** NSR tyre perished**Notice** Front brake discs wearing thin**MOT #5** 2011-06-03 12:34**MOT test number** 886834351109**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Both rear tyres perished**MOT #4** 2010-06-15 09:45**MOT test number** 291666860112**Result** ✓ Passed**Notice** One n/s/r lamp n/w**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Rear exhaust tailbox crusty

**MOT #3** 2010-06-14 14:49**MOT test number** 111755260109**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Rear exhaust tailbox crusty**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** One n/s/r lamp n/w**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2009-06-16 12:06**MOT test number** 672837469196**Result** ✓ Passed**Notice** Front brake pads wearing thin**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2008-06-16 11:51**MOT test number** 132798968140**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/r seat removed from vehicle at time of test



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2023

✕
MOT

Expired:
8 December 2022

Tax status	Expired at 1 February 2023
Days left	453 days too late
MOT expiry date	8 December 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-06-16
Last registration	2023-02-27
Complete history	See info



Registration #1	2005-06-16	11 mi
Registration #2	2008-06-16	36.108 mi
Registration #3	2009-06-16	48.155 mi
Registration #4	2010-06-14	62.362 mi
Registration #5	2010-06-15	62.381 mi
Registration #6	2011-06-03	74.192 mi
Registration #7	2012-05-30	84.234 mi
Registration #8	2013-05-29	96.037 mi
Registration #9	2014-06-06	105.718 mi
Registration #10	2014-06-09	105.718 mi
Registration #11	2015-06-05	115.503 mi
Registration #12	2015-06-05	115.503 mi
Registration #13	2016-06-05	125.287 mi
Registration #14	2016-06-05	125.287 mi
Registration #15	2016-06-05	125.287 mi
Registration #16	2016-06-05	125.287 mi
Registration #17	2016-06-05	125.287 mi
Registration #18	2016-06-05	125.287 mi
Registration #19	2016-06-05	125.287 mi
Registration #20	2016-06-05	125.287 mi
Registration #21	2016-06-05	125.287 mi
Registration #22	2016-06-05	125.287 mi
Registration #23	2016-06-05	125.287 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2142 mm
Height	1759 mm
Length	4642 mm
Wheel base	2835 mm
Kerb weight	1666 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	4S30549