





General informationMakeLAND ROVERModelDEFENDER HARD-TOP TD5ColourWhiteYear of manufacture2002Gearbox5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel







Internet history

Entry 1	
Date	2021-10-15
Pictures	27
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2023-02-22
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	15
Total items failed	11

MOT #16		2022-02-23 11:19
MOT test	number	519007508014
Result		✓ Passed
Next expi	ry date	2023-02-22
Advice	Offside Front ball swivel seal slightly leaking	
Advice	Nearside Front ball swivel seal leaking slightly	
Advice	Protective layer of underseal on underside of vehicle	

MOT #15	2021-06-17 11:54
MOT test number	584239254400
Result	✓ Passed
MOT #14	2016-09-09 11:04
MOT test number	76/00/810000

MOT test number	764904819000
Result	✓ Passed





MOT #13		2015-09-14 13:36
MOT test	number	930952820655
Result		✓ Passed
Advice	Nearside and offside front tractor joint seals damp	
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Oil leak	
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)	

MOT #12	2014-10-15 13:59
MOT test number	955588984247
Result	✓ Passed

MOT #11	2014-10-14 11:07
MOT test number	515577484277
Result	🗙 Failed
Fail Offside Front Trailing arm rubber bush deteriorated resulting in excessive movement	nt (2.4.G.2)
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach t (4.1.D.1a)	he ply or cords
Advice Offside Rear Shock absorber has a slightly worn bush (2.7.4)	
Fail Offside Headlamp aim too low (1.8)	
Fail Nearside Front Trailing arm rubber bush deteriorated resulting in excessive movement	ent (2.4.G.2)
Fail Offside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive model	ovement (2.4.G.2)
Fail Nearside Rear Shock absorber has an excessively worn bush (2.7.4)	
Fail Nearside Headlamp aim too low (1.8)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	





MOT #10	2013-10-09 11:34
MOT test	number 566072683292
Result	✓ Passed
Advice (2.2.C.1c)	Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt
Notice	O/s/f suspension arm has slight play at bush
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Notice	Oil leak
Advice (2.2.C.1c)	Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt
Notice	Chassi railings (service rust)
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #9	2012-09-24 10:31
MOT test number	529468762294
Result	✓ Passed

MOT #8	2011-10-04 12:17
MOT test number	469057371288
Result	✓ Passed

MOT #7	2010-10-12 12:19
MOT test number	912025380279
Result	✓ Passed

MOT #6	2009-09-18 14:11
MOT test number	850011669253
Result	✓ Passed





MOT #5	2008-09-11 09:07
MOT test number	842445158296
Result	✓ Passed
MOT #4	2008-09-09 16:15
MOT test number	691633358273
Result	× Failed
Fail Exhaust tailpipe not capable of allowing the emission probe to be inserted (7	.4.B.1)
Fail Parking brake: efficiency below requirements (3.7.C.1b)	
Fail Service brake: efficiency below requirements (3.7.C.1a)	

МОТ #3	2007-10-01 14:23
MOT test number	804854377266
Result	✓ Passed
MOT #2	2006-09-26 09.34

MOT #2	2006-09-26 09:34
MOT test number	542969766219
Result	✓ Passed
MOT #1	2005-10-06 11:58
MOT test number	253769375296

Result

🗸 Passed





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	
Category	 AMPLI
Туре	W CON

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	

Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2002-01-24
Last registration	2022-02-23
Complete history	See info



Registration #1	2002-01-24	18 mi
Registration #2	2005-10-06	55.812 mi
Registration #3	2006-09-26	72.324 mi
Registration #4	2007-10-01	84.753 mi
Registration #5	2008-09-09	860.609 mi
Registration #6	2008-09-11	86.091 mi
Registration #7	2009-09-18	93.116 mi
Registration #8	2010-10-12	100.904 mi
Registration #9	2011-10-04	110.136 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.117 mi

More info \rightarrow





Dimensions & weight

Width	1790 mm
Height	2076 mm
Length	4599 mm
Kerb weight	1920 kg
Max. allowed weight	3050 kg
Additional information	

Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of axles	2
Engine number	1SP26459A