



**MF59LUZ**


report date: 2024-03-29

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption



Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg





Internet history

Entry 1	
Date	2021-10-23
Pictures	57
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2021-11-17 16:03
<b>MOT test number</b>	564339359319
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-11-16
<b>Minor</b>	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #15</b>	2021-11-12 09:15
<b>MOT test number</b>	531017755930
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
<b>Advice</b>	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
<b>Minor</b>	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>MAJOR</b>	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14** 2021-09-15 10:56**MOT test number** 715918888692**Result** ✗ Failed**MAJOR** Offside Front Suspension unit leaking (5.3.5 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2020-09-17 10:57**MOT test number** 854104948553**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12** 2019-09-25 10:19**MOT test number** 233704611782**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2019-09-25 09:07**MOT test number** 659103396240**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #10** 2018-09-18 09:47**MOT test number** 899423514869**Result** ✓ Passed**MOT #9** 2017-09-15 16:21**MOT test number** 253473334316**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine under tray insecure**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-09-14 09:33**MOT test number** 377859390195**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine under tray insecure**Fail** Offside Rear Fluid suspension unit leaking shock absorber (2.4.D.2)**Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #7</b>	2016-09-27 16:02
<b>MOT test number</b>	402863474460
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)

<b>MOT #6</b>	2016-09-27 10:22
<b>MOT test number</b>	923608627409
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Headlamp not working on dipped beam (1.7.5a)
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Fail</b>	Offside Rear Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
<b>Fail</b>	Offside Headlamp not working on dipped beam (1.7.5a)
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Fail</b>	Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

<b>MOT #5</b>	2015-09-17 10:32
<b>MOT test number</b>	399612241076
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2014-09-09 12:27
<b>MOT test number</b>	158562454222
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2013-09-10 11:52
<b>MOT test number</b>	695833753216
<b>Result</b>	✓ Passed
<b>Notice</b>	Cannot inspect brake pipes or engine mounting under tray fitted

**MOT #2**

2012-09-27 15:06

**MOT test number**

765111372201

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #1**

2012-09-26 11:04

**MOT test number**

696420372236

**Result**

✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-30
Last registration	2021-11-17
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	14 mi
Registration #2	2012-09-26	28.638 mi
Registration #3	2012-09-27	28.661 mi
Registration #4	2013-09-10	40.241 mi
Registration #5	2014-09-09	48.140 mi
Registration #6	2015-09-17	57.209 mi
Registration #7	2016-09-27	63.734 mi
Registration #8	2016-09-27	63.734 mi
Registration #9	2017-09-14	69.802 mi
Registration #10	2018-09-20	75.877 mi
Registration #11	2019-09-20	81.952 mi
Registration #12	2020-09-20	88.027 mi
Registration #13	2021-09-20	94.102 mi
Registration #14	2022-09-20	100.177 mi
Registration #15	2023-09-20	106.252 mi
Registration #16	2024-09-20	112.327 mi
Registration #17	2025-09-20	118.402 mi
Registration #18	2026-09-20	124.477 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1521 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DYVQ4010392