



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Silver
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-24
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-02-02
MOT pass rate	58 %
MOT passed	15
Failed MOT tests	11
Total advice items	96
Total items failed	34

MOT #26	2023-01-20 12:32
MOT test number	339104768478
Result	✓ Passed
Next expiry date	2024-02-02
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #25	2023-01-20 12:32
MOT test number	822391173862
Result	✗ Failed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #24**

2022-01-29 10:18

**MOT test number**

277538002563

**Result**

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #23**

2022-01-29 10:18

**MOT test number**

875576875589

**Result**

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #22**

2021-02-03 11:45

**MOT test number**

335437752054

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Minor** Nearside Side repeater lens defective which has no effect on emitted light condensation inside lens (4.4.1 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn close to the legal limit and worn on edges (5.2.3 (e))

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** All brake disc back plates corroded

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

**Minor** Offside Side repeater lens defective which has no effect on emitted light condensation inside lens (4.4.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge slightly worn on inner edge (5.2.3 (e))

**Advice** Both rear shock absorber dust covers deteriorated

**Advice** Brake hose slightly deteriorated all brake hoses slightly perished (1.1.12 (b) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21**

2021-01-18 12:27

**MOT test number**

161843233117

**Result****✗ Failed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Headlamp insecure (4.1.1 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Brake operation has insufficient reserve pressure/vacuum to provide assistance for at least two more brake applications after the warning device has operated (or gauge shows an unsafe reading) (1.1.3 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2019-05-14 12:47

**MOT test number**

368556906239

**Result**

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear nearside and offside brake disc backing plates corroded
- Advice** Tow bar damaged
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Engine cover and undertray fitted obscuring some components

**MOT #19**

2019-05-10 06:52

**MOT test number**

927972915269

**Result**

✗ Failed

- Fail** Nearside Rear Position lamp not working second from bottom (4.2.1 (a))
- Advice** Rear nearside and offside brake disc backing plates corroded
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn inner front bush (5.3.4 (a) (i))
- Advice** Tow bar damaged
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Windscreen in an unacceptable condition cracked (3.2 (c) (i))
- Fail** Offside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- Advice** Engine cover and undertray fitted obscuring some components



MOT #18	2018-05-17 10:02
MOT test number	756762631047
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #17	2018-05-15 11:25
MOT test number	355065102696
Result	✗ Failed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Rear brake application uneven offside lazy (3.7.B.2)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Rear position lamp(s) not working (1.1.A.3b)





MOT #162017-06-29 17:08

MOT test number783544187575

Result✓ Passed

- Advice Nearside Rear Nail in tyre
- Advice Offside Rear TYRE WORN ON INNER EDGE
- Advice Rear Brake hose slightly deteriorated BOTH (3.6.B.4d)
- Advice Rear Inner Brake pad(s) wearing thin (3.5.1g)
- Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice EML light on
- Advice Offside Rear Nail in tyre
- Advice Front Brake hose slightly deteriorated BOTH (3.6.B.4d)
- Advice Front brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (3.5.1i)

**MOT #15**

2017-06-24 13:31

**MOT test number**

859260405724

**Result****✗ Failed****Advice** Offside Rear Nail in tyre**Fail** Nearside Front Headlamp insecure (1.7.3)**Advice** Front Brake hose slightly deteriorated BOTH (3.6.B.4d)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** EML light on**Fail** Engine mounting deteriorated resulting in excessive movement Gearbox side? (6.1.D.1a)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement REAR & FRONT BUSH (2.4.G.2)**Advice** Nearside Rear Nail in tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH SIDES (3.5.1i)**Advice** Rear Brake hose slightly deteriorated BOTH (3.6.B.4d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear TYRE WORN ON INNER EDGE**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement REAR & FRONT BUSH (2.4.G.2)**MOT #14**

2016-06-15 13:30

**MOT test number**

656212013633

**Result****✓ Passed****Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #13** 2016-06-15 10:32**MOT test number** 166073023600**Result** ✗ Failed

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #12** 2015-06-10 14:15**MOT test number** 306121765126**Result** ✓ Passed**MOT #11** 2014-05-28 09:22**MOT test number** 935058844109**Result** ✓ Passed

**Notice** Under-trays fitted obscuring some underside components

**MOT #10** 2013-07-03 15:54**MOT test number** 335314783106**Result** ✓ Passed

**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)



MOT #9 2013-07-01 11:13

MOT test number 719972483141

Result ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Electronic stability system warning lamp does not illuminate (3.4.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #8 2012-06-20 16:27

MOT test number 405402472114

Result ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** ESP light staying on indicating a fault
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Nearside side repeater damaged

**MOT #7** 2012-06-20 10:56**MOT test number** 589222072100**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** ESP light staying on indicating a fault**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside side repeater damaged**MOT #6** 2011-06-30 10:02**MOT test number** 729121381114**Result** ✓ Passed**MOT #5** 2010-07-14 11:32**MOT test number** 681935390141**Result** ✓ Passed**MOT #4** 2010-07-14 11:32**MOT test number** 324395790107**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)



MOT #3	2009-07-10 11:27
MOT test number	253701799476
Result	✓ Passed
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	

MOT #2	2008-07-02 12:59
MOT test number	602704288155
Result	✓ Passed

MOT #1	2008-07-02 12:45
MOT test number	513384888134
Result	✗ Failed
<div>Fail</div> Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

X

Untaxed

Tax expired:  
31 January 2024

X

MOT

Expired:  
2 February 2024

Tax status	Expired at 31 January 2024
Days left	89 days too late
MOT expiry date	2 February 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>HN05BFE</b>
Plate since	2019-03-28
Current registration	<b>HN05BFE</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2005-06-28
Last registration	2023-01-20
Complete history	<a href="#">See info</a>



Registration #1	2005-06-28	18 mi
Registration #2	2008-07-02	30.035 mi
Registration #3	2008-07-02	30.035 mi
Registration #4	2009-07-10	45.889 mi
Registration #5	2010-07-14	66.126 mi
Registration #6	2011-06-30	84.440 mi
Registration #7	2012-06-20	108.896 mi
Registration #8	2012-06-20	108.896 mi
Registration #9	2013-07-01	134.634 mi
Registration #10	2013-07-03	134.634 mi
Registration #11	2014-05-28	155.631 mi
Registration #12	2015-06-10	164.504 mi
Registration #13	2016-06-15	173.936 mi
Registration #14	2016-06-15	173.940 mi
Registration #15	2016-06-15	173.940 mi
Registration #16	2016-06-15	173.940 mi
Registration #17	2016-06-15	173.940 mi
Registration #18	2016-06-15	173.940 mi
Registration #19	2016-06-15	173.940 mi
Registration #20	2016-06-15	173.940 mi
Registration #21	2016-06-15	173.940 mi
Registration #22	2016-06-15	173.940 mi
Registration #23	2016-06-15	173.940 mi
Registration #24	2016-06-15	173.940 mi
Registration #25	2016-06-15	173.940 mi
Registration #26	2016-06-15	173.940 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958