



SHI2MXW

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 X-EC
Colour	Black
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	53 %
MOT passed	9
Failed MOT tests	8
Total advice items	32
Total items failed	17

MOT #172024-01-17 13:24

MOT test number760066095890

Result✓ Passed

Next expiry date2025-01-16

- Advice** Front Brake pad(s) wearing thin 30% (1.1.13 (a) (ii))
- Advice** Front Macpherson strut corroded but not seriously weakened Both sides (5.3.3 (b) (i))
- Advice** Rear Shock absorbers has light misting of oil Both sides (5.3.2 (b))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Nail in tyre
- Advice** Front Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**MOT #16**

2024-01-10 13:34

**MOT test number**

521149819057

**Result****✗ Failed****Advice** Front Macpherson strut corroded but not seriously weakened Both sides (5.3.3 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Nail in tyre**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin 30% (1.1.13 (a) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Rear Shock absorbers has light misting of oil Both sides (5.3.2 (b))**Advice** Front Anti-roll bar linkage ball joint has slight play Both sides (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**MOT #15**

2023-01-09 09:21

**MOT test number**

393863995049

**Result****✓ Passed****MOT #14**

2023-01-06 17:42

**MOT test number**

487047558657

**Result****✗ Failed****Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #13** 2022-01-12 14:06**MOT test number** 235679192372**Result** ✓ Passed**MOT #12** 2021-01-13 17:18**MOT test number** 949796147268**Result** ✓ Passed**MOT #11** 2021-01-11 18:52**MOT test number** 217472102338**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2019-06-25 13:43**MOT test number** 923982859102**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2019-06-25 13:05**MOT test number** 410553428521**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Obligatory indirect vision device insecure (3.3 (b) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2018-06-18 11:31**MOT test number** 596907674180**Result** ✓ Passed**MOT #7** 2018-06-18 09:29**MOT test number** 477819230373**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Obligatory mirror insecure (3.3 (b) (ii))**MOT #6** 2017-06-23 13:31**MOT test number** 768381199590**Result** ✓ Passed

**MOT #5** 2017-06-23 10:56**MOT test number** 131753300517**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Obligatory mirror insecure (8.1.1)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2016-06-28 12:26**MOT test number** 819978958042**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2016-06-28 10:27**MOT test number** 749161505657**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2015-06-11 12:19**MOT test number** 298162265414**Result** ✓ Passed



MOT #1	2015-04-20 11:12
MOT test number	206320415430
Result	✗ Failed
Fail	Offside Side repeater not working (1.4.A.2c)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)





Tax & MOT check

X

Untaxed

Tax expired:  
20 April 2024

✓

MOT

Expires:  
16 January 2025

Tax status	Expired at 20 April 2024
Days left	9 days too late
MOT expiry date	16 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>SH12MXW</b>
Plate since	2019-03-28
Current registration	<b>SH12MXW</b>
Plate since	2019-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-04-30
Last registration	2024-01-17
Complete history	<a href="#">See info</a>



Registration #1	2012-04-30	16 mi
Registration #2	2015-04-20	11.979 mi
Registration #3	2015-06-11	12.469 mi
Registration #4	2016-06-28	16.847 mi
Registration #5	2016-06-28	16.847 mi
Registration #6	2017-06-23	20.573 mi
Registration #7	2017-06-23	20.573 mi
Registration #8	2018-06-18	23.665 mi
Registration #9	2018-06-18	23.666 mi
Registration #10	2019-06-25	28.019 mi
Registration #11	2019-06-25	28.019 mi
Registration #12	2019-06-25	28.019 mi
Registration #13	2019-06-25	28.019 mi
Registration #14	2019-06-25	28.019 mi
Registration #15	2019-06-25	28.019 mi
Registration #16	2019-06-25	28.019 mi
Registration #17	2019-06-25	28.019 mi
Registration #18	2019-06-25	28.019 mi
Registration #19	2019-06-25	28.019 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1730 mm
Height	1555 mm
Length	4120 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1651017