



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Brown
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 3

Date 2021-06-18

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-06-07

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-05-21

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2022-09-03 08:33
<b>MOT test number</b>	939765559789
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-09-11

<b>MOT #17</b>	2021-09-06 13:41
<b>MOT test number</b>	350142398146
<b>Result</b>	✓ Passed

**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))

<b>MOT #16</b>	2021-09-02 09:47
<b>MOT test number</b>	930173731174

<b>Result</b>	✗ Failed
---------------	----------

**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Items removed from driver's view prior to test

**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))

**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Fail** Central Rear Passenger's seat insecure (6.2.6 (a) (ii))

**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

**MOT #15**

2020-09-11 15:09

**MOT test number**

824850827767

**Result**

✓ Passed

**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**Advice** Offside Rear Nail in tyre**MOT #14**

2020-09-04 10:27

**MOT test number**

166125184095

**Result**

✗ Failed

**Advice** Offside Rear Nail in tyre**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))**MOT #13**

2019-09-11 13:14

**MOT test number**

359788916060

**Result**

✓ Passed

**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2019-09-11 09:53**MOT test number** 888762914810**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2018-09-07 09:55**MOT test number** 479153113521**Result** ✓ Passed**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Power steering component has slight seepage from a component steering rack damp (2.1.5 (a))**MOT #10** 2018-09-07 09:55**MOT test number** 579597372879**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Power steering component has slight seepage from a component steering rack damp (2.1.5 (a))**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #9** 2017-09-06 09:07**MOT test number** 468268398363**Result** ✓ Passed**MOT #8** 2016-09-06 10:51**MOT test number** 804571669741**Result** ✓ Passed**Advice** Front brake pads low.

**MOT #7** 2015-09-02 09:23**MOT test number** 103609181997**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-09-12 09:22**MOT test number** 476805454278**Result** ✓ Passed**Notice** Nearside rear tyre aged and perished 7yrs old**Notice** Rear exhaust silencer support bracket corroded**MOT #5** 2013-08-13 10:13**MOT test number** 738755723278**Result** ✓ Passed**MOT #4** 2012-08-22 08:49**MOT test number** 315925932447**Result** ✓ Passed**Notice** Spare tyre below limits req new for road use**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-21 17:01**MOT test number** 916854732272**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-08-22 10:42
MOT test number	346344031462
Result	✓ Passed
MOT #1	2010-08-27 13:33
MOT test number	352039630256
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-11
Last registration	2022-09-03
Complete history	<a href="#">See info</a>



Registration #1	2007-09-11	11 mi
Registration #2	2010-08-27	18.479 mi
Registration #3	2011-08-22	24.172 mi
Registration #4	2012-08-21	32.069 mi
Registration #5	2012-08-22	32.069 mi
Registration #6	2013-08-13	43.215 mi
Registration #7	2014-09-12	54.270 mi
Registration #8	2015-09-02	59.424 mi
Registration #9	2016-09-06	65.534 mi
Registration #10	2017-09-06	72.994 mi
Registration #11	2018-09-07	79.580 mi
Registration #12	2019-09-07	86.166 mi
Registration #13	2020-09-07	92.752 mi
Registration #14	2021-09-07	99.338 mi
Registration #15	2022-09-03	105.924 mi
Registration #16	2023-09-03	112.510 mi
Registration #17	2024-03-28	119.096 mi
Registration #18	2024-03-28	125.682 mi
Registration #19	2024-03-28	132.268 mi
Registration #20	2024-03-28	138.854 mi
Registration #21	2024-03-28	145.440 mi
Registration #22	2024-03-28	152.026 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3271964