



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | LAND ROVER |
| Model | FREELANDER TD4 XS |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 112 mph |
| 0 - 100 km/h | 11.7 seconds |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 110 kW / 150 HP / 150 BHP |
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-14 |
| Pictures | 18 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-30 |
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 25 |
| Total items failed | 10 |

| | |
|------------------|------------------|
| MOT #14 | 2023-09-27 15:35 |
| MOT test number | 841906238391 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-30 |

| | |
|-----------------|---|
| MOT #13 | 2023-09-21 13:38 |
| MOT test number | 200558036001 |
| Result | ✗ Failed |
| Fail | Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| Fail | Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |
| Fail | Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |

| | |
|-----------------|------------------|
| MOT #12 | 2022-09-27 15:02 |
| MOT test number | 129388721018 |
| Result | ✓ Passed |

| | |
|-----------------|----------------------------|
| MOT #11 | 2021-10-01 14:11 |
| MOT test number | 175642871580 |
| Result | ✓ Passed |
| Advice | Engine trays firmly fitted |

**MOT #10**

2021-09-28 08:49

MOT test number

177233426306

Result**✗ Failed**

- Fail** Central Seat belt webbing significantly weakened rear (7.1.2 (b) (ii))
- Fail** Nearside Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Rear Nail in tyre
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Engine trays firmly fitted

MOT #9

2021-03-08 14:26

MOT test number

243519404361

Result**✓ Passed**

- Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Central Rear Seat belt slightly damaged (7.1.2 (b) (i))

MOT #8

2020-03-27 09:29

MOT test number

682944421323

Result**✓ Passed**

- Advice** Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Front Lower Suspension arm front bushes slightly deteriorated.
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #7** 2020-03-27 09:29**MOT test number** 210107308389**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Front Lower Suspension arm front bushes slightly deteriorated.**Advice** Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #6** 2019-03-27 10:27**MOT test number** 731600701458**Result** ✓ Passed**Advice** Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #5** 2018-03-14 12:20**MOT test number** 483431043484**Result** ✓ Passed**Advice** Offside Front Nail in tyre**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement Front bush (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement Front bush (2.4.G.2)**MOT #4** 2017-03-27 15:57**MOT test number** 579097887589**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2016-02-17 11:05**MOT test number** 988465686138**Result** ✓ Passed**Advice** Nearside Rear Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**Advice** Nearside Rear Rear fog lamp slightly discoloured due to crack (1.3.2e)**MOT #2** 2014-09-06 11:18**MOT test number** 966259744246**Result** ✓ Passed**Notice** Emissions too low to obtain a reading**Notice** Nearside rear fog lamp lens cracked**MOT #1** 2014-09-05 15:27**MOT test number** 415218744200**Result** ✗ Failed**Notice** Emissions too clean unable to meter**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Notice** Nearside rear fog lamp lens cracked**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | YF11XHS |
| Plate since | 2019-03-29 |
| Current registration | YF11XHS |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-08-17 |
| Last registration | 2023-09-27 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2011-08-17 | 19 mi |
| Registration #2 | 2014-09-05 | 44.160 mi |
| Registration #3 | 2014-09-06 | 44.160 mi |
| Registration #4 | 2016-02-17 | 60.370 mi |
| Registration #5 | 2017-03-27 | 72.487 mi |
| Registration #6 | 2018-03-14 | 88.051 mi |
| Registration #7 | 2019-03-27 | 107.024 mi |
| Registration #8 | 2020-03-27 | 126.900 mi |
| Registration #9 | 2020-03-27 | 126.900 mi |
| Registration #10 | 2020-03-27 | 126.900 mi |
| Registration #11 | 2020-03-27 | 126.900 mi |
| Registration #12 | 2020-03-27 | 126.900 mi |
| Registration #13 | 2020-03-27 | 126.900 mi |
| Registration #14 | 2020-03-27 | 126.900 mi |
| Registration #15 | 2020-03-27 | 126.900 mi |
| Registration #16 | 2020-03-27 | 126.900 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 2180 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1770 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DZ794013534224DT |