





### General information

Make	ΤΟΥΟΤΑ
Model	LAND CRUISER D-4D LC4 8 SEATS
Colour	Green
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	343 Nm at 1.600 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.6 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.2 mpg
CO2 emission	277 g/km
CO2 label	Μ







# Internet history

Entry	1
Date	

Pictures

2022-02-02

13

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-22
MOT pass rate	64 %
MOT passed	18
Failed MOT tests	10
Total advice items	57
Total items failed	22

MOT #28		2024-03-23 17:01
MOT test	number	922731318679
Result		✓ Passed
<b>Next expiry date</b> 2025-03-22		2025-03-22
Advice Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))		
Advice	Front All direction indicators slightly discoloured both (4.4.3 (a))	

MOT #27	2022-10-17 16:14
MOT test number	756061982617
Result	✓ Passed
Advice Offside Front Vehicles internal headlight adjuster altered to recheck lights	





MOT #26	2022-10-17 14:3
MOT test	number 66307201123
Result	🗙 Faile
<b>MAJOR</b> (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b
MAJOR	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front Vehicles internal headlight adjuster altered to recheck lights
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
MAJOR (b) (ii))	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1
MAJOR	Offside Front Headlamp aim too high (4.1.2 (a))
MAJOR	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #25	2022-02-11 18:45
MOT test number	596905510147
Result	✓ Passed

MOT #24	2022-02-11 18:45
MOT test number	729845956018
Result	× Failed
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification (b) (ii))	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4



SO53YLT
report date: 2024-03-29

MOT #23		2021-09-06 13:51
MOT test	number	431733215801
Result		🗙 Failed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
MAJOR reduced S	Offside Vehicle structure corroded to the extent that the rigidity of the assembly Il holed (marked in yellow) (6.1.1 (c) (i))	is significantly
MAJOR reduced W	Integral body structure corroded to the extent that the rigidity of the assembly is /hole vehicle body holed, front to rear (marked in yellow) (6.1.1 (c) (i))	significantly
MAJOR reduced S	Nearside Vehicle structure corroded to the extent that the rigidity of the assemb Il holed (marked in yellow) (6.1.1 (c) (i))	y is significantly
MAJOR Whole veh	Vehicle structure corroded to the extent that the rigidity of the assembly is significle chassis holed, front to rear (marked in yellow) $(6.1.1 (c) (i))$	icantly reduced
MOT #22		2020-09-16 10:02
MOT test	number	204724256035
Result		🗸 Passed
Advice	Exhaust has a minor leak of exhaust gases silencer in poor condition (6.1.2 (a))	
MOT #21		2020-09-15 09:50
	number	126655002045
MOT test		136655892045
MOT test Result		136655892045 X Failed
	Horn not working (7.7 (a) (ii))	

**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))

**MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #20	2019-09-10 14:41
MOT test number	985695118516
Result	✓ Passed



SO53YLT
report date: 2024-03-29

MOT #19	2019-08-29 08:2
MOT test numb	ber 24944877196
Result	× Faile
MAJOR Nea	rside Headlamp aim too low (4.1.2 (a))
	tral Rear Integral body structure is corroded but structural rigidity is not significantly reduced Vallance ) (6.1.1 (c) (i))
MAJOR Regi	istration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
-	rside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its 30cm of a body mounting rear crossmember (Vallance) (6.2.2 (d) (i))
MOT #18	2018-09-28 12:4
MOT test numb	ber 16381106379
Result	✓ Passe
MOT #17	2018-09-21 10:5
MOT test numb	ber 15131624745
Result	× Faile
Minor Offsic (i))	de Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)
DANGEROUS	Offside Front Upper Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
<b>MAJOR</b> Nea the ingress of di	rside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents irt (6.1.7 (g) (ii))
DANGEROUS	Nearside Front Upper Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

MAJORFront Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Both (5.3.4(b) (ii))

MOT #16	2017-10-02 11:54
MOT test number	615439332918
Result	✓ Passed





MOT #2	MOT #15 2017-09-27 15:3	
MOT te	st number	448757108859
Result		🗙 Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Rear Brake pipe leaking (3.6.A.1)	
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #14		2017-02-14 11:53
MOT test	number	953414000738
Result		✓ Passed
Advice	Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)	
Advice	Advise vehicle underside is very heavily coated throughout	





<b>10T #13</b> 2017-02-07 14:16
<b>10T test number</b> 873247223495
Result Xesult
<b>Fail</b> Suspension component mounting prescribed area is excessively corroded nearside inner sill rear section (2.4.A.3)
<b>Fail</b> Suspension component mounting prescribed area is excessively corroded offside inner sill rear section (2.4.A.3)
Fail Brake pipe excessively corroded brake pipe from flexible hose at rear to offside rear flexible hose   (3.6.B.2c)
Fail Offside Registration plate lamp not working (1.1.C.1d)
Advice Advise vehicle underside is very heavily coated throughout
<b>Fail</b> Exhaust has a major leak of exhaust gases rear pipe missing (7.1.2)
<b>Fail</b> Suspension component mounting prescribed area is excessively corroded nearside inner sill rear section (2.4.A.3)
<b>Fail</b> Brake pipe excessively corroded both brake pipes from from to flexible hoses at rear (3.6.B.2c)
Advice Vehicle structure slightly corroded within 30cm of towbar mounting (6.6.6)
<b>Fail</b> Brake pipe excessively corroded brake pipe from flexible hose at rear to nearside rear flexible hose (3.6.B.2c)
<b>Fail</b> Exhaust has a major leak of exhaust gases rear pipe missing (7.1.2)

MOT #12 2016-02-03 1		2016-02-03 18:07
MOT test	number	831253078111
Result		✓ Passed
Advice	Advise front lower guard plate heavily corroded	
Advice	Advise vehicle underside has some corrosion present throughout	
Advice	Advise trim mounting brackets at rear of vehicle corroded	





MOT #11	2015-02-06 17:10
MOT test number	117237935017
Result	✓ Passed
Advice Offside Front Upper Front suspension ball joint dust cover damaged, but dirt (2.4.G.2)	preventing the ingress of
Notice Advise oil leak at gearbox	
<b>Advice</b> Nearside Front Upper Front suspension ball joint dust cover damaged, bu of dirt (2.4.G.2)	ut preventing the ingress
MOT #10	2014-02-07 14:05
MOT test number	538508834062

Result		✓ Passed
Advice	Brake pipe slightly corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	

## MOT #9

### **MOT test number**

Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in offside front tyre	
Advice	Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Brake pipe slightly corroded (3.6.B.2c)	

MOT #8	2012-01-25 11:20
MOT test number	279745722081
Result	✓ Passed

2013-01-31 12:56

579691233056





MOT #7	2011-02-12 10:56
MOT test number	148013841044
Result	✓ Passed
МОТ #6	2010-02-08 09:21
MOT #6 MOT test number	2010-02-08 09:21 552179330067

MOT #5	2010-02-04 14:17
MOT test number	844255830069
Result	🗙 Failed
Fail Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
<b>Fail</b> Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #4	2009-01-13 10:32
MOT test number	590283919008
Result	✓ Passed

MOT #3		2008-01-11 12:24
MOT test	number	101141918413
Result		🗸 Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Offside front tyre worn on outside of tread	
Notice	Nearside rear tyre worn on outside of tread	





MOT #2		2008-01-11 12:24
MOT test number		413521118033
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Notice Nearside rear tyre worn on outside of tread		
<b>Pass with rectification</b> Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Notice Child seat fitted not allowing full inspection of adult belt		
Notice Offside front tyre worn on outside of tread		

MOT #1	2007-01-16 11:16
MOT test number	100656017453
Result	✓ Passed
Notice Nearside rear tyre worn on edges	
Notice Spare tyre flat	





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	Lesn.
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

In miles
29
2004-01-13
2024-03-23
See info



Registration #1	2004-01-13	25 mi
Registration #2	2007-01-16	22.385 mi
Registration #3	2008-01-11	36.703 mi
Registration #4	2009-01-13	43.244 mi
Registration #5	2010-02-04	57.919 mi
Registration #6	2010-02-08	57.929 mi
Registration #7	2011-02-12	68.237 mi
Registration #8	2012-01-25	77.951 mi
Registration #9	2013-01-31	88.075 mi
Registration #10	2014-02-07	97.234 mi
Registration #11	2015-02-06	107.212 mi
Registration #12	2016-02-03	117.560 mi
Registration #13	2017-02-07	128.524 mi
Registration #14	2017-02-14	128.674 mi
Registration #15	2017-09-27	134.525 mi
Registration #16		11.777 est
Registration #17		11.227 mi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 mi
Registration #24		10.377 est
Registration #25		11.777 mi
Registration #26		11.777 mi
CarCheck.co.uk		page 16/17

Registration #27	10.317 esi
Registration #28	11.777 est
Registration #29	11.777 esi





### Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

## Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	1990 kg

## Additional information

Fuel tank capacity	87
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Engine number	1KD1121289