



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Red
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-05
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	65
Total items failed	23

MOT #18	2023-05-12 11:48
MOT test number	401104833808
Result	✓ Passed
Next expiry date	2024-05-11
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2023-05-12 11:48

**MOT test number**

993265609458

**Result****✗ Failed**

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2022-02-14 12:52

**MOT test number**

432657880463

**Result****✓ Passed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2021-11-11 09:51

**MOT test number**

371022590942

**Result****✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension unit leaking (5.3.5 (c))
- Advice** Engine mounts deteriorated
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Suspension unit leaking (5.3.5 (c))
- Fail** Windscreen washer not working (3.5 (a))

**MOT #14**

2020-11-11 13:17

**MOT test number**

468729789253

**Result****✓ Passed**

- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2020-11-09 16:10**MOT test number** 349670032369**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Undertray likely to become detached (6.2.1 (a) (ii))**Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12** 2019-11-14 10:34**MOT test number** 252782197577**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #11** 2018-12-04 13:58**MOT test number** 492270268161**Result** ✓ Passed

**MOT #10**

2018-12-03 16:10

**MOT test number**

246766625824

**Result****✗ Failed**

- Fail** Offside Front Suspension unit leaking (5.3.5 (c))
- Fail** Nearside Front Suspension unit leaking (5.3.5 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9**

2017-12-05 17:00

**MOT test number**

178697806105

**Result****✓ Passed**

- Advice** Central Rear Fluid suspension unit supply pipe corroded but not seriously weakened ferral corroded, marked in yellow (2.4.D.3)
- Advice** Offside front tyre worn smooth on inner edge
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #8**

2017-12-04 17:17

**MOT test number**

123112180906

**Result****✗ Failed**

- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)



MOT #7	2016-12-05 16:55
MOT test number	982089887184
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)

MOT #6	2016-12-05 16:55
MOT test number	387436344462
Result	✗ Failed
Pass with rectification	Front position lamp(s) not working both fronts (1.1.A.3b)
Advice	Nearside Front Tyre worn close to the legal limit worn on outer edge (4.1.E.1)
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #5	2015-12-08 15:00
MOT test number	937957622820
Result	✓ Passed

MOT #4	2014-12-01 10:10
MOT test number	995595534356
Result	✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Oil leak
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Front brake discs worn/corroded



**MOT #3**

2014-12-01 10:10

**MOT test number**

388665034357

**Result****✗ Failed****Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Oil leak**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs worn/corroded**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2**

2013-12-09 14:32

**MOT test number**

307753243363

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #1**

2012-09-05 09:53

**MOT test number**

916209442227

**Result****✓ Passed**



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-30
Last registration	2023-05-12
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	22 mi
Registration #2	2012-09-05	56.403 mi
Registration #3	2013-12-09	64.640 mi
Registration #4	2014-12-01	71.664 mi
Registration #5	2015-12-08	78.356 mi
Registration #6	2016-12-05	83.049 mi
Registration #7	2016-12-05	83.049 mi
Registration #8	2017-12-04	87.950 mi
Registration #9	2017-12-05	87.973 mi
Registration #10	2018-12-03	92.963 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1608 kg
Max. allowed weight	2155 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DYXH4043189