



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	SL SL 500
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	460 Nm at 2.700 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.4 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.3 mpg
CO2 emission	292 g/km
CO2 label	M





MOT history

MOT expiry date	2020-09-02
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	58
Total items failed	17

MOT #18	2019-09-03 14:22
MOT test number	404116692508
Result	✓ Passed
Next expiry date	2020-09-02
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside front suspension unit has slight leak
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2019-08-21 11:26

**MOT test number**

104112578577

**Result****✗ Failed**

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside front suspension unit has slight leak
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Unable to gain access to fuel filler cap
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #16**

2017-11-02 16:09

**MOT test number**

520762869214

**Result****✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front suspension has slight play in a lower suspension ball joint shock absorber to lower arm (2.5.B.1a)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Fault in sbc braking system visit workshop (instrument cluster)
- Advice** Nearside Front suspension has slight play in a lower suspension ball joint shock absorber to lower arm (2.5.B.1a)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #15**

2017-11-02 16:09

**MOT test number**

591546472645

**Result**

✗ Failed

**Advice** Fault in sbc braking system visit workshop (instrument cluster)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Front Lower Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Front suspension has slight play in a lower suspension ball joint shock absorber to lower arm (2.5.B.1a)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint shock absorber to lower arm (2.5.B.1a)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #14**

2016-11-25 15:25

**MOT test number**

287836858672

**Result**

✓ Passed

**Advice** Nearside Front Lower Shock absorber has a slightly worn shock absorber pivot connection between shock and lower arm (2.7.4)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Lower Shock absorber has a slightly worn shock absorber pivot connection between shock and lower arm (2.7.4)**Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**MOT #13**

2016-11-23 14:01

**MOT test number**

314235742430

**Result**

✗ Failed

**Advice** Offside Front Lower Shock absorber has a slightly worn shock absorber pivot connection between shock and lower arm (2.7.4)

**Fail** Offside Front Inner Track rod end ball joint has excessive play tie rod to rack (2.2.B.1f)

**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

**Advice** Nearside Front Lower Shock absorber has a slightly worn shock absorber pivot connection between shock and lower arm (2.7.4)

**Fail** Nearside Front Inner Track rod end ball joint has excessive play tie rod to rack (2.2.B.1f)

**Advice** Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**Fail** Nearside Rear Outer Suspension arm attachment bracket/mounting insecure arm to hub connection (2.4.G.1)

**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #12**

2015-11-10 09:37

**MOT test number**

814017849648

**Result**

✓ Passed

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Advice** ABC light on

**Advice** Nearside and offside front shock absorber lower ball joints have slight play

**Advice** Eye level stop lamp some lights not working

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Service brake light on

**Advice** Offside steering arm inner joint has slight play

**MOT #11** 2014-11-06 16:39**MOT test number** 165230114324**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Nearside front shock absorber bottom mount has slight movement**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #10** 2014-11-06 09:43**MOT test number** 337470314334**Result** ✗ Failed**Notice** Service brake warning lamp on**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Nearside front shock absorber bottom mount has slight movement**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2013-11-02 11:36**MOT test number** 966856303312**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Play in steering rack inner joint(s)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2012-11-01 11:42**MOT test number** 549196802389**Result** ✓ Passed**MOT #7** 2012-10-25 09:44**MOT test number** 295949392220**Result** ✗ Failed**Fail** Rear Parking brake lever has no reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2011-10-25 17:00**MOT test number** 466168791277**Result** ✓ Passed**MOT #5** 2010-10-19 11:32**MOT test number** 364952190243**Result** ✓ Passed**Advice** Nearside Front Ball joint has slight play (2.2.B.1f)**Notice** Strong advise on nsf and osf strut ball joints have movement**MOT #4** 2009-10-20 11:48**MOT test number** 733103499296**Result** ✓ Passed**Advice** Offside Front Lower Front suspension has slight movement at a suspension ball joint (2.5.A.1c)**Advice** Nearside Front Front suspension has slight movement at a suspension ball joint (2.5.A.1c)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #3	2008-10-30 09:34
MOT test number	404024308425
Result	✓ Passed
MOT #2	2007-10-12 11:14
MOT test number	991925587292
Result	✓ Passed
MOT #1	2006-10-16 12:03
MOT test number	363479786410
Result	✓ Passed
<div><div>Notice</div>Rubber boot split on n/s/f bottom balljoint. â€</div> <div><div>Notice</div>Slight play in both sides of steering rack</div> <div><div>Notice</div>Rubber boot split on o/s/f torque control arm balljoint</div>	





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2003-10-31
Last registration	2019-09-03
Complete history	<a href="#">See info</a>



Registration #1	2003-10-31	28 mi
Registration #2	2006-10-16	51.047 mi
Registration #3	2007-10-12	65.948 mi
Registration #4	2008-10-30	78.530 mi
Registration #5	2009-10-20	86.379 mi
Registration #6	2010-10-19	96.518 mi
Registration #7	2011-10-25	100.866 mi
Registration #8	2012-10-25	110.045 mi
Registration #9	2012-11-01	110.191 mi
Registration #10	2013-11-02	119.534 mi
Registration #11	2014-10-20	129.877 mi
Registration #12	2015-10-20	139.220 mi
Registration #13	2016-10-20	148.563 mi
Registration #14	2017-10-20	157.906 mi
Registration #15	2018-10-20	167.249 mi
Registration #16	2019-09-03	176.592 mi
Registration #17	2019-09-03	176.592 mi
Registration #18	2019-09-03	176.592 mi
Registration #19	2019-09-03	176.592 mi

More info >



Dimensions & weight

Width	2045 mm
Height	1317 mm
Length	4535 mm
Wheel base	2515 mm
Kerb weight	1845 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11396330534456