





report date: 2024-03-28

## General information

Make	VOLVO
Model	V70 S 170 V70
Colour	Gold
Year of manufacture	2002
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	170 BHP
Max. torque	170 Nm at 5.900 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	30.1 mpg
CO2 emission	231 g/km
CO2 label	L



CarCheck.co.uk page 1/18



report date: 2024-03-28

## Internet history

### Entry 2

Date 2021-10-02

Pictures 41

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-06-13
Pictures	5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/18



report date: 2024-03-28

## MOT history

MOT expiry date	2025-03-03
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	56
Total items failed	24

MOT #27	2024-03-04 13:22
MOT test number	717880265660
Result	<b>✓</b> Passed
Next expiry date	2025-03-03

MOT #26	2024-03-04 13:22
MOT test number	555934349816
Result	<b>X</b> Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 3/18



report date: 2024-03-28

MOT test number

Result

Advice Front wishbone bushes splitting

Advice Both outer sills covered by plastic trims

Advice Oil leak engine

Advice Exhaust corroded

MOT #24 2023-04-04 16:39
MOT test number 714314299493
Result × Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Front wishbone bushes splitting

Rear discs corroded

**Advice** 

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Both outer sills covered by plastic trims

**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))

**Advice** Oil leak engine

**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Exhaust corroded

Advice Rear discs corroded

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/18



report date: 2024-03-28

MOT test number

345964645925


Result

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))




CarCheck.co.uk page 5/18



report date: 2024-03-28

**MOT #21** 2021-04-13 14:29 **MOT** test number 463115817813 ✓ Passed Result **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Windscreen damaged but not adversely affecting driver's view Stone chips (3.2 (a) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



CarCheck.co.uk page 6/18



report date: 2024-03-28

MOT #19		2020-02-06 09:31
MOT test	number	827189484135
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Corrodeo	d (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing And worn on edge	es (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view Stone chips (3	.2 (a) (i))

MOT #18	2018-05-14 13:27
MOT test number	176217868017
Result	✓ Passed
MOT #17	2017-06-08 11:44
MOT test number	197788873190
Result	<b>✓</b> Passed
Advice Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)	

MOT #16	2016-07-11 08:33
MOT test number	786759133500
Result	✓ Passed

Rear Brake pad(s) wearing thin (3.5.1g)

Advice

Result		✓ Passed
MOT #15		2016-07-11 08:33
MOT test number		484737365737
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Wheel bolt(s) missing (4.2.A.1e)	

CarCheck.co.uk page 7/18



report date: 2024-03-28

MOT #14		2015-07-20 09:21
MOT test	number	729771105243
Result		✓ Passed
MOT #13		2014-07-16 09:24
MOT test	number	877177594199
Result		✓ Passed
MOT #12		2013-07-10 09:10
MOT test	number	276911693194
Result		✓ Passed
MOT #11		2012-07-18 10:09
MOT test	number	416060802252
Result		✓ Passed
MOT #10		2011-02-01 10:14
MOT test	number	146852431446
Result		✓ Passed
MOT #9		2010-01-04 11:50
MOT test	number	652694900034
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		

CarCheck.co.uk page 8/18



report date: 2024-03-28

MOT #8 2010-01-04 10:32

**MOT test number** 991374900071

**Result** X Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #7** 2009-05-21 10:25

MOT test number 560771649133

**Result** ✓ Passed

MOT #6 2008-05-13 15:54

MOT test number 240334338192

Result 

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** Condensation in nearside headlamp

MOT #5 2008-05-13 12:53

**MOT test number** 914744938199

**Result** X Failed

**Fail** Nearside Registration plate lamp not working (1.1.5c)

**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Condensation in nearside headlamp

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 9/18



report date: 2024-03-28

MOT #4 2007-05-14 10:51

**MOT test number** 473534437185

**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #3 2007-05-14 10:51

MOT test number 462764237106

Result × Failed

Advice Centre Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)

MOT #2 2006-05-12 09:25

MOT test number 570402436180

Result 

Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A'

(8.3.1d)

CarCheck.co.uk page 10/18



report date: 2024-03-28

MOT #1 2006-05-12 09:25

**MOT test number** 483522636144

Result X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.B2)

Advice Offside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Headlamp aim too low when the centre of the headlamp is below 850mm

from the ground (1.6.B2)

CarCheck.co.uk page 11/18





report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 12/18



report date: 2024-03-28

## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 14/18



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO	
have? Check it in the premium report and see all owner registrations. Download the full r	eport <u>here</u> .
**********	
***************************************	
MANAGEMENT CONTRACTOR	
***************************************	
	More info >
<u> </u>	
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 15/18



report date: 2024-03-28

### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 16/18






report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2002-05-15
Last registration	2024-03-04
Complete history	See info



Registration #1	2002-05-15	21 mi
Registration #2	2006-05-12	33.282 mi
Registration #3	2007-05-14	39.638 mi
Registration #4	2008-05-13	44.900 mi
Registration #5	2008-05-13	44.900 mi
Registration #6	2009-05-21	49.117 mi
Registration #7	2010-01-04	51.379 mi
Registration #8	2010-01-04	51.379 mi
Registration #9	2011-02-01	65.784 mi
Registration #10	2012-07-18	85.585 mi
Registration #11	2013-07-10	95.852 mi
Registration #12	2014-07-16	107.081 mi
Registration #13	2015-07-20	117.553 mi
Registration #14	2016-07-11	128.064 mi
Registration #15		11.777 es
Registration #16		11.777 mg
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 17/18

Registration #27

Registration #28

More info >

mn.n.n



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1483 kg

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	2824023

CarCheck.co.uk page 18/18