





General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	2003
Top speed	109 mph
0 - 60 mph	9.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	104 BHP
Max. torque	143 Nm at 3.200 rpm
Engine capacity	1.599 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.1 mpg
CO2 emission	183 g/km
CO2 label	l







Internet history

Entry 1

Date Pictures 2021-07-09

9

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-20
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	75
Total items failed	4

MOT #22	2023-06-21 10:23
MOT test number	497272981506
Result	✓ Passed
Next expiry date	2024-06-20
Advice Central Front Upper Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Inner Drive belt worn, but not excessively (6.1.7 (c) (i))	

MOT #21	2022-06-15 16:50
MOT test number	463677562419
Result	✓ Passed
MinorOffside Headlamp lens slightly defective (4.1.1 (b) (i))AdviceRear exhaust has corrosion but no leak	





MOT #20	2022-06-15 10:17
MOT test	number 848494704329
Result	× Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
DANGER	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR (b) (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Headlamp lens slightly defective both (4.1.1 (b) (i))
Advice	Rear exhaust has corrosion but no leak
MAJOR (5.3.4 (b)	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (ii))

MOT #19		2021-06-21 14:20
MOT test	number	481790238156
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #18	2020-09-10 09:09
MOT test number	146897143962
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor Front Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice Rear Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear exhaust corroded	

MOT #17		2019-09-30 10:57
MOT test	number	607924324104
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in excess (i))	ive movement
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated	(6.1.7 (g) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 ((c))
Advice	Front Registration plate deteriorated but not likely to be misread $(0.1 (b))$	





40T #16 2018-09-18 13:22
179579593276
Result V Passed
Advice Oil leak, but not excessive From oil filter area (8.4.1 (a) (i))
Minor Offside Front Headlamp lens slightly defective Beam pattern slightly affected (4.1.1 (b) (i))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush deteriorated (5.3.4 (a) (i))
Advice Offside Front Washer requires adjustment
Advice Offside Rear Brake pipe corroded, covered in grease or other material From brake hose to drum (1.1.11 (c))
Advice Rear Service brake fluctuating, but not excessively Both sides (1.2.1 (e))
Advice Rear Registration plate deteriorated but not likely to be misread Excessively deteriorated (0.1 (b))
Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor Front Outer Drive shaft joint constant velocity boot severely deteriorated Both (6.1.7 (g) (i))
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe (1.1.11 (c))
Advice Offside Rear Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii))
Advice Front Registration plate deteriorated but not likely to be misread Excessively deteriorated (0.1 (b))





MOT #15	2018-09-18 11:05
MOT test	number 296999381624
Result	× Failed
MAJOR	Offside Front Steering locking device missing Track rod end nut locking pin missing (2.1.3 (d))
Advice (1.1.11 (c	Offside Rear Brake pipe corroded, covered in grease or other material From brake hose to drum))
Advice (b))	Front Registration plate deteriorated but not likely to be misread Excessively deteriorated (0.1
Advice	Offside Rear Tyre slightly damaged/cracking or perishing On outer edge (5.2.3 (d) (ii))
Advice	Rear Service brake fluctuating, but not excessively Both sides (1.2.1 (e))
Advice	Oil leak, but not excessive From oil filter area (8.4.1 (a) (i))
Minor	Offside Front Headlamp lens slightly defective Beam pattern slightly affected (4.1.1 (b) (i))
Advice Rear bush	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement deteriorated (5.3.4 (a) (i))
Advice	Offside Front Washer requires adjustment
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice (c))	Nearside Rear Brake pipe corroded, covered in grease or other material Front to rear pipe (1.1.11
Advice	Rear Registration plate deteriorated but not likely to be misread Excessively deteriorated (0.1 (b))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Minor	Front Outer Drive shaft joint constant velocity boot severely deteriorated Both (6.1.7 (g) (i))

MOT #14		2017-09-11 10:00
MOT test	number	520285584027
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	





MOT #13	2017-09-05 16:09
MOT test number	348983113833
Result	🗙 Failed
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged prevents the ingress of dirt (2.4.G.2)	so that it no longer
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Fail Offside Stop lamp not working (1.2.1b)	
Advice Child Seat fitted not allowing full inspection of adult belt	

MOT #12		2016-09-08 11:15
MOT test	number	412073599060
Result		✓ Passed
Advice	Rear registration plate delaminated but not likely to be misread (6.3.1d)	
Advice	Child Seat fitted not allowing full inspection of adult belt	

MOT #11	2015-09-02 12:30
MOT test number	535801438128
Result	✓ Passed

MOT #10		2014-09-04 11:57
MOT test	number	197127944275
Result		✓ Passed
Notice	OFFSIDE TYRE STARTING TO WEAR ON INNER EDGE	
Notice	PASSENGER WIPER STARTING TO SPLIT AND PERISH	

MOT #9	2013-09-09 14:53
MOT test number	608662353221
Result	✓ Passed





MOT test number 435229242274 Result Passed Notice Vehicle's internal headlight adjuster altered to recheck lights Notice Items removed from driver's view prior to test
Notice Vehicle's internal headlight adjuster altered to recheck lights
Notice Items removed from driver's view prior to test
MOT #7 2011-09-12 15:03
MOT test number 936345951225
Result V Passed
MOT #6 2010-09-17 14:25
MOT test number 903270760273
Result V Passed
MOT #5 2009-09-08 12:03
MOT #5 2009-09-08 12:03 MOT test number 823661159285
Result V Passed
MOT #4 2008-09-17 12:32
MOT test number 972171968279
Result Verseo
MOT #3 2007-09-07 16:06
MOT test number 333820257470
Result V Passed
MOT #2 2006-08-29 14:34
MOT test number 930171946248
Result V Passed





MOT #1		2006-08-29 11:39
MOT test number	r	384591846433
Result		🗙 Failed
Fail Nearside F	Front Windscreen wiper blade deteriorated (8.2.2)	
Fail Front Wind	dscreen washer provides insufficient washer liquid (8.2.3)	



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 June 2024	Expires: 20 June 2024
Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	*
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Number of plates Carnet registration	
Number of plates Carrent registration Plate since	
Romber of plates Correct registration Flats since Correct registration	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-03
Last registration	2023-06-21
Complete history	See info



Registration #1	2003-09-03	6 mi
Registration #2	2006-08-29	3.775 mi
Registration #3	2006-08-29	3.775 mi
Registration #4	2007-09-07	4.052 mi
Registration #5	2008-09-17	4.179 mi
Registration #6	2009-09-08	9.030 mi
Registration #7	2010-09-17	16.055 mi
Registration #8	2011-09-12	23.321 mi
Registration #9	2012-09-05	26.388 mi
Registration #10	2013-09-09	29.775 mi
Registration #11	2014-09-04	32.667 mi
Registration #12	2015-09-02	35.222 mi
Registration #13		11.707 esi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.707 esi
Registration #18		11.777 esi
Registration #19		11.707 esi
Registration #20		11.777 esi
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 esi
Registration #24		11.177 esi







Car features

S0225	Air conditionin
S0295	
50482	
\$0501	
\$0566	
\$0567	
\$0569	

Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1138 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	G4ED3464222