



report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Maroon
Year of manufacture	2008
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-28
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	72
Total items failed	29

MOT #22	2023-08-29 12:36
MOT test number	251952696504
Result	✓ Passed
Next expiry date	2024-08-28
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	General under body rust under sealed
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Rear Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #21**

2023-08-29 09:03

MOT test number

698672745002

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** General under body rust under sealed
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Front Anti-roll bar ball joint has slight play both (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Brake performance unable to be tested due to pads (1.2.1 (g))

MOT #20

2022-05-09 13:51

MOT test number

728670394633

Result**✓ Passed**

- Advice** General under body rust
- Advice** Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #19** 2022-05-09 13:51**MOT test number** 935820680067**Result** ✗ Failed**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** General under body rust**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2021-05-07 13:30**MOT test number** 669746131311**Result** ✓ Passed**MOT #17** 2021-05-06 14:33**MOT test number** 876822368600**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #16** 2020-10-01 09:40**MOT test number** 227187769050**Result** ✓ Passed



MOT #15	2020-09-22 12:05
MOT test number	889951033169
Result	✗ Failed
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Rear Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
Fail	Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Fail	Hazard warning switch inoperative (4.4.2 (a) (ii))
Fail	Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Brake pad(s) less than 1.5 mm thick both rear (1.1.13 (a) (ii))
Fail	Offside Rear Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
Fail	Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
Fail	Front Registration plate inscription illegible (0.1 (b))



MOT #14

2019-08-09 13:49

MOT test number

173809380872

Result		✓ Passed
Advice	Oil leak, but not excessive transmission (8.4.1 (a) (i))	
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice	Sill covers fitted & under trays	
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	



MOT #13

2019-08-08 12:42

MOT test number

103224365345

Result

✗ Failed

- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive transmission (8.4.1 (a) (i))
- Fail

Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Sill covers fitted & under trays
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2018-07-31 07:58

MOT test number

239274178506

Result

✓ Passed

- Advice** Offside Outer driveshaft gaiter , slightly deteriorated
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2017-08-02 13:26

MOT test number

696210604594

Result

✓ Passed

- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #10

2017-08-02 10:16

MOT test number

482014367535

Result

✗ Failed

- Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Rear Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition box missing (7.1.4)

**MOT #9** 2016-08-09 06:33**MOT test number** 650437440018**Result** ✓ Passed**MOT #8** 2015-07-09 15:30**MOT test number** 167770295147**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #7** 2015-07-08 10:10**MOT test number** 547539885125**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp aim too low (1.8)**MOT #6** 2014-07-09 11:47**MOT test number** 876960694104**Result** ✓ Passed**Notice** Exhaust heat shield at rear insecure**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-07-10 09:51**MOT test number** 358031193140**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2013-07-10 09:51**MOT test number** 736181193142**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Offside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2012-08-02 11:06**MOT test number** 326705112203**Result** ✓ Passed**Notice** Offside rear tyre cracking between tread**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Engine oil close to minimum**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2012-08-02 11:06**MOT test number** 717725112205**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Engine oil close to minimum**Notice** Under-trays fitted obscuring some underside components**Notice** Offside rear tyre cracking between tread



MOT #1	2011-08-30 09:47
MOT test number	938272241266
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-13
Last registration	2023-08-29
Complete history	See info



Registration #1	2008-10-13	24 mi
Registration #2	2011-08-30	21.237 mi
Registration #3	2012-08-02	27.768 mi
Registration #4	2013-07-10	32.619 mi
Registration #5	2014-07-09	43.181 mi
Registration #6	2015-07-08	53.565 mi
Registration #7	2015-07-09	53.565 mi
Registration #8	2016-08-09	65.774 mi
Registration #9	2017-08-02	74.692 mi
Registration #10	2017-08-02	74.692 mi
Registration #11	2018-07-31	84.588 mi
Registration #12	2019-08-02	95.237 mi
Registration #13	2020-08-02	105.237 mi
Registration #14	2021-08-02	115.237 mi
Registration #15	2022-08-02	125.237 mi
Registration #16	2023-08-02	135.237 mi
Registration #17	2024-08-02	145.237 mi
Registration #18	2025-08-02	155.237 mi
Registration #19	2026-08-02	165.237 mi
Registration #20	2027-08-02	175.237 mi
Registration #21	2028-08-02	185.237 mi
Registration #22	2029-08-02	195.237 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20254322