





### General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Blue
Year of manufacture	2010
Top speed	82 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	121 BHP	0 < 101 A
Max. torque	360 Nm at 2.000 rpm	101 - 120 B
Engine capacity	2.402 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185
Consumption city	22.6 mpg	186 - 225
Consumption extra urban	32.8 mpg	225+ L
Consumption combined	28.3 mpg	





## Internet history

Entry 1

Date

2022-01-03

Pictures

3

Listing price

View report







source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-06
MOT pass rate	56 %
MOT passed	10
Failed MOT tests	8
Total advice items	20
Total items failed	36

MOT #18	2023-07-04 15:14
MOT test number	391984601900
Result	✓ Passed
Next expiry date	2024-07-06

MOT #1	7	2023-07-04 10:32
MOT tes	st number	132484862392
Result		🗙 Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Reversing lamp inoperative (4.6.1 (a))	
Fail	Rear fog lamp not working (4.5.1 (a) (ii))	
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))	

MOT #16	2022-07-05 13:42
MOT test number	133903783319
Result	✓ Passed



MOT #3	15	2022-07-04 11:51
MOT te	st number	965381515753
Result		🗙 Failed
Fail	Nearside Rear reflector missing (4.8.2 (a) (ii))	
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Windscreen washer not working (3.5 (a))	
Fail	Offside Rear reflector missing (4.8.2 (a) (ii))	
Fail	Front Brakes imbalanced across an axle (1.2.1 (b) (i))	

MOT #14	2021-07-07 08:58
MOT test number	140582851378
Result	✓ Passed

MOT #13		2021-07-07 08:58
MOT test number		289710502356
Result		🗙 Failed
Pass with rectification	Central Front Registration plate missing (0.1 (a))	

MOT #12	2019-06-07 15:42
MOT test number	319251945777
Result	✓ Passed

**CE600DH** 

report date: 2024-03-29





MOT #1	20	19-06-06 15:47
MOT te	st number	480900963757
Result		🗙 Failed
Fail	Offside Front Suspension arm pin or bush excessively worn panard bush (5.3.4 (a) (i))	
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (i	i))
Fail	Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))	
Fail	Nearside Front Position lamp not working (4.2.1 (a))	

MOT #10	2018-01-22 12:00
MOT test number	874933400448
Result	✓ Passed
<b>Advice</b> Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #9	2018-01-19 09:28	
MOT test number	286897938817	
Result	🗙 Failed	
<b>Pass with rectification</b> Nearside Headlamp aim too high (1.8)		
Fail Windscreen washer provides insufficient washer liquid (8.2.3)		
<b>Advice</b> Front registration plate deteriorated but not likely to be misread (6.3.1d)		
Fail Parking brake efficiency below requirements (3.7.E.1)		
Pass with rectificationOffside Headlamp aim too high (1.8)		
Fail Offside Rear position lamp(s) not working (1.1.A.3b)		
Fail Parking brake lever has no reserve travel (3.1.6b)		





		2017-01-06 11:14
MOT tes	t number	756745339517
Result		✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)	
MOT #7		2017-01-04 12:12
MOT tes	t number	286689024155
Result		🗙 Failed
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)	
Fail	Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)	
Fail	Nearside Stop lamp not working (1.2.1b)	
Result Advice Fail	Nearside Track rod end ball joint has slight play (2.2.B.1f) Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)	

МОТ #6	2016-04-13 15:07
MOT test number	732677493109
Result	✓ Passed





MOT #5	<b>5</b> 2016-04-05 10:54
MOT te	est number 295078829806
Result	× Failed
Fail	Front Windscreen wiper not operating automatically when switched on (8.2.1b)
Advic	Nearside Rear Trailing arm has slight play in a pin/bush front bush (2.4.G.2)
Fail	Nearside Front Drag link end ball joint has excessive play (2.2.B.1f)
Fail	Nearside Front wheel bearing has excessive play (2.5.A.3c)
Fail	Offside Front Steering damper damaged and unserviceable bush badly worn (2.2.C.1d)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Advic	Offside Rear Brake pipe slightly corroded to cylinder (3.6.B.2c)
Advic	Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
Fail	Rear Registration plate lamp not working (1.1.C.1d)
Fail	Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)
Advic	Parking brake lever has little reserve travel (3.1.6b)
Advic	Offside Rear Trailing arm has slight play in a pin/bush front bush (2.4.G.2)
<b>Fail</b> the ing	Offside Front Drag link end ball joint dust cover excessively damaged so that it no longer prevents ress of dirt drop arm (2.2.C.1c)
Advic	Brake pipe slightly corroded main front to rear (3.6.B.2c)
Fail	Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)
Advic	Engine management light on
Fail	Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)





MOT #4		2015-06-16 10:35
MOT test	number	957607865100
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Nail in offside front tyre	
Advice	Offside Rear wheel bearing has slight play (2.6.2)	
Notice	Oil leak	


МОТ #3	2015-06-15 11:40
MOT test number	249506865173
Result	🗙 Failed
Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)	
Notice Nail in offside front tyre	
Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice Offside Rear wheel bearing has slight play (2.6.2)	
Notice Oil leak	
Fail Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)	
Fail Offside Front position lamp(s) not working (1.1.A.3b)	

MOT #2	2015-01-05 15:53
MOT test number	946305405084
Result	✓ Passed

MOT #1	2013-12-09 14:20
MOT test number	427783743386
Result	✓ Passed



Tax & MOT check







#### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info >





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
******	
**********	
********	
	More info >
	,
Plate changes	
See in this check if this LAND ROVER had different number plates.	

Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-12-23
Last registration	2023-07-04
Complete history	See info



Registration #1	2010-12-23	25 mi
Registration #2	2013-12-09	31.732 mi
Registration #3	2015-01-05	42.126 mi
Registration #4	2015-06-15	47.360 mi
Registration #5	2015-06-16	47.365 mi
Registration #6	2016-04-05	55.076 mi
Registration #7	2016-04-13	55.083 mi
Registration #8	2017-01-04	63.139 mi
Registration #9	2017-01-06	63.139 mi
Registration #10	2018-01-19	71.330 mi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		11.117 est





## Dimensions & weight

Additional information	
Max. allowed weight	2505 kg
Kerb weight	1759 kg
Length	4040 mm
Height	2128 mm
Width	1790 mm

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	100713031244244DT