





General information

Make	MAZDA
Model	5 TS2
Colour	Silver
Year of manufacture	2008
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I







2021-12-18
0
View report
2021-12-16
0
View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	81
Total items failed	3

MOT #20		2024-01-25 13:12
MOT test	number	246465241282
Result		✓ Passed
Next expi	ry date	2025-01-24
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Items removed from driver's view prior to test	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Vehicles internal headlight adjuster altered to recheck lights 3	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))		novement Lower
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e	2))



MOT #19	2024-01-23 12:34
MOT test ı	number 326325524282
Result	× Failed
Advice	Items removed from driver's view prior to test
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Advice	Vehicles internal headlight adjuster altered to recheck lights 3
MAJOR (5.3.4 (b) (Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt ii))
Advice arm rear b	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Lower ush (5.3.4 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
MAJOR	Nearside Headlamp aim unable to be tested (4.1.2 (b))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn Lower arm rear bush (5.3.4 (a) (i))
MAJOR Lambda to	Rear Exhaust emissions likely to be affected by an exhaust leak Exhaust emissions are affected o high 1.685 (8.2.1.1 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm (5.2.3 (e))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #18	2023-01-17 14:06
MOT test number	661036854636
Result	✓ Passed

MOT #17	2022-01-24 09:42
MOT test number	312219427531
Result	✓ Passed

FY08AZR

report date: 2024-03-28





MOT #16		2022-01-18 09:55
MOT test	number	779916260955
Result		🗙 Failed
MAJOR	Offside Rear Suspension arm pin or bush excessively worn trailing (5.3.4 (a) (i))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
DANGER	OUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Nearside Rear Suspension arm pin or bush excessively worn trailing (5.3.4 (a) (i))	
MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))		
DANGER	OUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #15		2021-02-12 14:57
MOT test	number	383967973777
Result		✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #14		2021-02-12 14:57
MOT test number		428954436302
Result		🗙 Failed
Advice Nearside Front	Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Rear	Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Child Seat fitte	d not allowing full inspection of adult belt	
Advice Offside Front A	nti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor Windscreen dan	naged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #13	2020-02-07 11:48
MOT test number	376120129971
Result	✓ Passed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in ex (a) (i))	xcessive movement (5.3.4

MOT #12		2020-02-07 09:28
MOT test	number	215405067237
Result		🗙 Failed
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in exce	ssive movement (5.3.4
MAJOR (4.8.1 (a) (Nearside Rear Rear reflector defective or damaged by more than 50% of ii))	the reflecting surface

MOT #11		2019-02-16 09:59
MOT test	number	517054910033
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #10		2018-02-17 11:15
MOT test	number	597096645225
Result		✓ Passed
MOT #9		2017-02-08 16:46
MOT test	number	659587813862
Result		Passed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt centre	row

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #8		2017-02-08 11:43
MOT test	number	110718095695
Result		🗙 Failed
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in ex	cessive movement
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt centre	e row
Fail O	ffside Front Suspension arm rubber bush deteriorated resulting in excessive mo	ovement (2.4.G.2)

MOT #7	2016-02-10 12:07
MOT test number	447977374260
Result	✓ Passed
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)	
Advice Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Rear tyre cut in tread	



FY08AZR
report date: 2024-03-28

MOT #6		2015-02-09 12:16
MOT test	number	859570245036
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Heat sheild on fuel tank loose	
Advice (2.4.G.2)	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in exc	essive movement
Notice	Offside rear tyre bald on shoulders and tread on 2.3mm	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Notice	Front brake pads getting low	
Advice (2.4.G.2)	Offside Rear Trailing arm rubber bush deteriorated but not resulting in exces	ssive movement

MOT #5		2014-02-07 14:04
MOT test number		467698134013
Result		✓ Passed
Notice Engine cove	ers fitted obscuring some components in the engine bay	
Advice Offside Rear	r Tyre worn close to the legal limit (4.1.E.1)	
Notice Under-trays	fitted obscuring some underside components	





MOT #4		2014-02-07 10:12
MOT test	number	867028634000
Result		🗙 Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in nearside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Fail N	earside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #3		2013-02-09 11:48
MOT test	number	846670643046
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Side sills with covers not fully checked	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #2		2012-02-25 11:22
MOT test	number	505296552067
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Notice	Child seat n/s/r	





MOT #1	2011-02-25 11:30
MOT test number	917706251079
Result	✓ Passed
Notice Both front tyres worn on inner and outer edges	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 24 January 2025
Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	E CUT D
Date	1.4
Category	ame
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate sition	





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-03-04
Last registration	2024-01-25
Complete history	See info



2008-03-04	8 mi
2011-02-25	17.163 mi
2012-02-25	23.752 mi
2013-02-09	32.478 mi
2014-02-07	41.573 mi
2014-02-07	41.573 mi
2015-02-09	50.318 mi
2016-02-10	55.154 mi
2017-02-08	62.148 mi
2017 02 00	62.148 mi
2017-02-08	02.140 111
2017-02-08	74.468 mi
2018-02-17	74.468 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
2018-02-17 2019-02-16	74.468 mi 81.700 mi
	2011-02-25 2012-02-25 2013-02-09 2014-02-07 2014-02-07 2015-02-09 2016-02-10

More info >



FY08AZR report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5