





General informationMakeLAND ROVERModelDEFENDER HARD-TOP TD5ColourGreenYear of manufacture2000Gearbox5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel







Internet history

Entry 1

Date

2021-10-20

7

Pictures

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-07-19
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	20
Total items failed	30

MOT #23	2022-07-14 15:11
MOT test number	273898419032
Result	✓ Passed
Next expiry date	2023-07-19
Advice Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material	l (1.1.11 (c))
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Outer Brake pipe corroded, covered in grease or other ma	aterial (1.1.11 (c))

MOT #22 2022-07-13 07:08 **MOT test number** 960920094128 Result × Failed Advice Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Offside Front Direction indicator not working (4.4.1 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))





MOT #21		2021-07-13 07:48
MOT test	number	447072882530
Result		✓ Passed
MOT #20		2020-07-20 14:01
MOT test	number	196614021929
Result		✓ Passed
Advice Front Outer Brake pipe corroded, covered in grease or other material both (1.1.11 (c))		
Advice	Rear Brake pipe corroded, covered in grease or other material both (1.1.)	11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #19	2020-07-01 09:54
MOT test number	331740186906
Result	🗙 Failed
Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))	
Advice Front Outer Brake pipe corroded, covered in grease or other material both (1.1.1)	1 (c))
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the (5.2.3 (d) (i))	ply or cords
Fail Offside Front Lower Suspension arm pin or bush excessively worn both front bushes	(5.3.4 (a) (i))
Fail Offside Front Axle swivel pins and bushes swivel pin and/or bush excessively worn ex (5.1.2 (b) (i))	xcessive play
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach th (5.2.3 (d) (i))	ne ply or cords
Fail Nearside Front Lower Suspension arm pin or bush excessively worn both front bushe	es (5.3.4 (a) (i))
Fail Central Rear Upper Suspension arm ball joint dust cover no longer prevents the ingra joint onto axle (5.3.4 (b) (ii))	ess of dirt ball
Advice Oil leak, but not excessive transmission (8.4.1 (a) (i))	





МОТ #18	2019-06-24 12:40	
MOT test number	170356430917	
Result	✓ Passed	
Advice Rear Shock absorbers has a slightly worn bush both (5.3.2 (c))		
MOT #17	2019-06-11 11:16	
MOT test number	191718316672	
Result	🗙 Failed	
Fail Rear Prop shaft joint excessively worn (6.1.7 (c) (i))		
Fail Front Tyre fouling a part of the vehicle both (5.2.3 (f))		
Fail Fuel system component leaking excessively or a risk of fire fuel filter (6.1.3 (b) (ii))	
Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced crossmember (6.1.1 (c) (i))		
Fail Nearside Front Body component damaged and likely to cause injury side light lense	5 (6.2.1 (a) (i))	
Fail Nearside Rear Tyre fouling a part of the vehicle (5.2.3 (f))		
Advice Rear Shock absorbers has a slightly worn bush both (5.3.2 (c))		
Fail Nearside Front Position lamp not working (4.2.1 (a))		

MOT #16	2018-06-28 13:56
MOT test number	388856908982
Result	✓ Passed

MOT #:	15 2018-0	6-27 11:59
MOT te	est number 5542	207982341
Result		🗙 Failed
Fail Nearside Vehicle structure is fractured and structural rigidity is significantly reduced (6.1.1 (a) (i))		a) (i))
Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))		





MOT #14	2017-08-08 15:30
MOT test number	402779973945
Result	✓ Passed
MOT #13	2016-07-28 12:02
MOT test number	645535534521
Result	✓ Passed
MOT #12	2015-07-07 08:10
MOT test number	588488685176
Result	✓ Passed
MOT #11	2015-07-01 13:06
MOT test number	575902485113
Result	🗙 Failed
Fail Offside Rear fog lamp not working (1.3.2b)	
Fail Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)	
Fail Rear Vehicle structure excessively corroded within 30cm of towbar mountine	g (6.6.6)
Fail Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)	

MOT #10		2014-08-01 13:30
MOT test	number	116753514254
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)	





MOT #	9	2014-07-29 14:54
MOT te	est number	158560714216
Result		🗙 Failed
Fail	Nearside Front Seat belt damaged sufficient to significantly weakened the webbing	(5.2.2a)
Fail	Nearside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)	
Fail	Steering system fouling (2.2.D.2a)	
Advie	Rear Brake pad(s) wearing thin (3.5.1g)	
Fail	Rear registration plate insecure (6.3.1b)	
Fail	Offside Front position lamp(s) not working (1.1.A.3b)	
Fail	Offside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)	
Advid	Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)
Fail	Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4	.B.3b)

MOT #8	2013-02-13 11:38
MOT test number	757184943075
Result	✓ Passed
MOT #7	2012-02-06 14:35
MOT test number	437777132054
Result	✓ Passed
МОТ #6	2011-01-20 13:04
MOT test number	239920621013
Result	✓ Passed
MOT #5	2010-01-18 12:57
MOT test number	134828710497

Result

✓ Passed





MOT #4	2009-01-09 12:56
MOT test number	593609609049
Result	✓ Passed
MOT #3	2008-01-15 10:21
MOT test number	924225118006
Result	✓ Passed
MOT #2	2007-01-18 12:59
MOT test number	491538617000
Result	✓ Passed
MOT #1	2006-01-26 09:13
MOT test number	184406726408
Result	✓ Passed





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
	MP1E
Category	ter .
Туре	

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info	>
Plate changes		
See in this check if this LAND ROVER had different number plates.		

Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2000-02-18
Last registration	2022-07-14
Complete history	See info



Registration #1	2000-02-18	17 mi
Registration #2	2006-01-26	52.744 mi
Registration #3	2007-01-18	61.334 mi
Registration #4	2008-01-15	70.917 mi
Registration #5	2009-01-09	79.129 mi
Registration #6	2010-01-18	87.308 mi
Registration #7	2011-01-20	91.655 mi
Registration #8	2012-02-06	95.195 mi
Registration #9	2013-02-13	98.642 mi
Registration #10	2014-07-29	105.772 mi
Registration #11	2014-08-01	105.814 mi
Registration #12	2015-07-01	110.078 mi
Registration #13	2015-07-07	110.165 mi
Registration #14		11.117 esi
Registration #15		11.117 esi
Registration #16		11.117 esi
Registration #17		11.222 esi
Registration #18		11.117 esi
Registration #19		11.117 esi
Registration #20		11.777 est
Registration #21		11.777 est
Registration #22		11.117 est
Registration #23		11.117 est
Registration #24		11.117 est
Registration #25		

CarCheck.co.uk



Dimensions & weight

Width	1790 mm
Height	2076 mm
Length	4599 mm
Kerb weight	1920 kg
Max. allowed weight	3050 kg
Additional information	

Fuel tank capacity	75
Fuel delivery	Direct Injection
Number of axles	2
Engine number	10PA52036