



PX59RJZ

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Black
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-07
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	46
Total items failed	10

MOT #162023-10-18 09:53

MOT test number594780001512

Result✔ Passed

Next expiry date2024-10-17

- Advice

Both outer sills corroded
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor

Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Rear chassis legs corroded
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Play in steering rack inner joint(s)
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Steering rack has slight free play detected at steering wheel (2.3 (a) (i))



MOT #15

2023-10-16 13:47

MOT test number

769100004221

Result		✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Play in steering rack inner joint(s)	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Both outer sills corroded	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
Minor	Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear chassis legs corroded	



MOT #14

2022-10-15 11:31

MOT test number

395589984705

Result

✓ Passed

- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor

Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice

Both outer sills corroded
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Play in steering rack inner joint(s)
- Advice

Rear chassis legs corroded

**MOT #13**

2022-10-14 11:22

MOT test number

177755799841

Result**✗ Failed**

- Advice** Both outer sills corroded
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Front Brake hose excessively stretched (1.1.12 (b) (ii))
- Advice** Rear chassis legs corroded
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
- Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

MOT #12

2021-10-15 10:47

MOT test number

219130105419

Result**✓ Passed**

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill area from front to rear (5.3.6 (a) (i))
- Advice** Rear axle corroded but structural integrity not reduced
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2021-10-11 08:55

MOT test number

570697968924

Result**✗ Failed****Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill area from front to rear (5.3.6 (a) (i))**Fail** Offside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength slightly holed in center of sill area (5.3.6 (a) (i))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill area holed and corroded (5.3.6 (a) (i))**Advice** Rear axle corroded but structural integrity not reduced**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #10**

2020-09-10 08:12

MOT test number

839835971126

Result**✓ Passed****Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9**

2020-09-04 12:36

MOT test number

664126495560

Result**✗ Failed****Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**MOT #8**

2019-09-17 07:58

MOT test number

351675385614

Result**✓ Passed**



MOT #7	2018-08-21 09:43
MOT test number	918452247242
Result	✓ Passed
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MOT #6	2017-09-12 11:11
MOT test number	800096324224
Result	✓ Passed
MOT #5	2016-08-23 09:51
MOT test number	953628577059
Result	✓ Passed
MOT #4	2015-09-17 10:09
MOT test number	987022485362
Result	✓ Passed
MOT #3	2014-09-19 11:00
MOT test number	817752264228
Result	✓ Passed
MOT #2	2013-08-20 16:31
MOT test number	398332333234
Result	✓ Passed
MOT #1	2012-09-12 11:05
MOT test number	717106952280
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
17 October 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-18
Last registration	2023-10-18
Complete history	See info



Registration #1	2009-09-18	29 mi
Registration #2	2012-09-12	36.879 mi
Registration #3	2013-08-20	46.987 mi
Registration #4	2014-09-19	59.312 mi
Registration #5	2015-09-17	68.351 mi
Registration #6	2016-08-23	74.644 mi
Registration #7	2017-09-12	83.082 mi
Registration #8	2018-08-21	88.559 mi
Registration #9	2019-09-17	95.171 mi
Registration #10	2020-09-17	101.783 mi
Registration #11	2021-09-17	108.395 mi
Registration #12	2022-09-17	115.007 mi
Registration #13	2023-09-17	121.619 mi
Registration #14	2024-09-17	128.231 mi
Registration #15	2025-09-17	134.843 mi
Registration #16	2026-09-17	141.455 mi
Registration #17	2027-09-17	148.067 mi
Registration #18	2028-09-17	154.679 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	081126043850BG