



R3ISFH

report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | MAZDA |
| Model | BONGO FRIENDEE |
| Colour | White |
| Year of manufacture | 1997 |
| Gearbox | - |

Engine & fuel consumption

| | |
|-----------------|----------|
| Engine capacity | 2.490 cc |
| Fuel type | Diesel |



LABEL UNKNOWN



Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-06-27 |
| Pictures | 38 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-01 |
| Pictures | 8 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-06 |
| MOT pass rate | 61 % |
| MOT passed | 11 |
| Failed MOT tests | 7 |
| Total advice items | 87 |
| Total items failed | 36 |

MOT #18 2023-08-07 16:14

MOT test number 729143448150

Result ✓ Passed

Next expiry date 2024-08-06

- Advice** Spare tyre defective spacesaver tyre is flat
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill/chassis leg (6.1.1 (c) (i))
- Advice** Rear park brake efficiency 17% - just passed
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material both sides corroded (1.1.11 (c))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Front Coil spring corroded both springs (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive rear of engine (8.4.1 (a) (i))
- Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened both subframes corroded (5.3.3 (b) (i))
- Minor** Front Headlamp lens slightly defective both headlamps - lens dull (4.1.1 (b) (i))
- Advice** Rear Coil spring corroded both springs (5.3.1 (b) (i))

**MOT #17**

2023-08-01 13:03

MOT test number

802865682423

Result**✗ Failed**

- Advice** Oil leak, but not excessive rear of engine (8.4.1 (a) (i))
- Advice** Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
- Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis leg has a large hole(suspension arm rear mount) (5.3.6 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened both subframes corroded (5.3.3 (b) (i))
- Minor** Front Headlamp lens slightly defective both headlamps - lens dull (4.1.1 (b) (i))
- Advice** Spare tyre defective spacesaver tyre is flat
- Advice** Rear Coil spring corroded both springs (5.3.1 (b) (i))
- Advice** Rear park brake efficiency 17% - just passed
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill/chassis leg (6.1.1 (c) (i))
- Advice** Front Brake pipe corroded, covered in grease or other material both sides corroded (1.1.11 (c))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Fail** Offside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength 2 separate subframes at front - problem is with rear subframe - mount. chassis leg has a large hole (5.3.6 (a) (i))
- Advice** Front Coil spring corroded both springs (5.3.1 (b) (i))



| | |
|-----------------|------------------|
| MOT #16 | 2023-03-15 10:18 |
| MOT test number | 116337791541 |
| Result | ✗ Failed |

Minor Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

Advice Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))

Fail Front Windscreen in an unacceptable condition (3.2 (c) (i))

Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush worn (5.3.4 (a) (i))

Advice Rear Coil spring corroded both sides (5.3.1 (b) (i))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Fail Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced hole in sill (6.1.1 (c) (i))

Fail Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt boot split (2.1.3 (g) (ii))

Fail Offside Front Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced hole in body mounting (6.1.1 (c) (i))

Fail Offside Front Headlamp aim unable to be tested no dipped beam (4.1.2 (b))

Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush worn (5.3.4 (a) (i))

Fail Offside Rear Floor excessively deteriorated hole in floor (6.2.4 (a) (i))

Minor Front Battery insecure but not likely to fall from carrier both sides (4.13 (a) (i))

Fail Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt boot split (2.1.3 (g) (ii))

Fail Offside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced hole in inner wing (6.1.1 (c) (i))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Front Brake pipe corroded, covered in grease or other material pipe corroded both sides (1.1.11 (c))

**MOT #15**

2021-12-06 16:31

MOT test number

251330442080

Result

✓ Passed

- Advice** Front Service brake binding but not excessively both sides (1.2.1 (f))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre perished (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing tyre perished (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material pipe corroded (1.1.11 (c))

MOT #14

2021-12-03 17:04

MOT test number

672236860125

Result

✗ Failed

- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material pipe corroded (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre perished (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Front Service brake binding but not excessively both sides (1.2.1 (f))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing tyre perished (5.2.3 (d) (ii))

**MOT #13**

2021-11-09 09:17

MOT test number

409280352489

Result**✗ Failed****Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting out rigger corroded (6.2.2 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre perished (5.2.3 (d) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Offside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Fail** Rear Brake pipe excessively corroded corroded both sides (1.1.11 (c))**Fail** Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced holes in sills both sides (6.1.1 (c) (i))**Advice** Front Tyre slightly damaged/cracking or perishing tyres perished both sides (5.2.3 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material pipe corroded (1.1.11 (c))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arms front bush perished both sides (5.3.4 (a) (i))**Minor** Nearside Front Windscreen wiper blade defective smearing screen (3.4 (b) (i))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #12**

2020-11-03 13:15

MOT test number

348643702333

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))**MOT #11**

2020-11-02 14:23

MOT test number

592546368448

Result

✗ Failed

Advice Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))**Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**Fail** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**MOT #10**

2019-09-03 17:53

MOT test number

590281641440

Result

✓ Passed

MOT #9

2017-07-26 09:09

MOT test number

250730719154

Result

✓ Passed

**MOT #8**

2016-07-08 14:10

MOT test number

957470816045

Result

✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Front spotlights inop
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Vehicle structure has slight corrosion front cross member (6.1.B.2)
- Advice** Slight corrosion on brake pipes

MOT #7

2014-11-26 09:38

MOT test number

359280834358

Result

✓ Passed

- Advice** Body has slight corrosion (6.1.B.2)

MOT #6

2013-11-28 14:02

MOT test number

806102733358

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both front brake discs badly corroded on inner faces
- Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Very poor dip beam image
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Auto transmission fluid leaking from corroded oil cooler pipe
- Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #5** 2013-11-28 12:01**MOT test number** 288572533302**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)**Notice** Very poor dip beam image**Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Notice** Auto transmission fluid leaking from corroded oil cooler pipe**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Anti-roll bar linkage insecure (2.4.G.1)**Notice** Both front brake discs badly corroded on inner faces**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**MOT #4** 2012-07-10 16:35**MOT test number** 148682992159**Result** ✓ Passed**MOT #3** 2012-06-27 15:30**MOT test number** 466329272199**Result** ✗ Failed**Fail** Offside Front Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)



| | |
|-----------------|--|
| MOT #2 | 2011-08-10 10:28 |
| MOT test number | 617432321232 |
| Result | ✓ Passed |
| Notice | Both rear anti roll bar link rod bushes worn |
| Notice | Headlamp dip beam pattern poor |

| | |
|-----------------|------------------|
| MOT #1 | 2010-08-02 11:26 |
| MOT test number | 132104610253 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
6 August 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 August |
| Days left | | 95 |
| MOT expiry date | | 6 August 2024 |
| Full MOT history | | See MOT history |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2010-08-02 |
| Last registration | 2023-08-07 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-08-02 | 67.494 mi |
| Registration #2 | 2011-08-10 | 124.729 mi |
| Registration #3 | 2012-06-27 | 86.300 mi |
| Registration #4 | 2012-07-10 | 86.300 mi |
| Registration #5 | 2013-11-28 | 166.062 mi |
| Registration #6 | 2013-11-28 | 166.062 mi |
| Registration #7 | 2014-11-26 | 173.965 mi |
| Registration #8 | 2016-07-08 | 179.453 mi |
| Registration #9 | 2017-07-26 | 113.756 mi |
| Registration #10 | 2019-09-03 | 114.420 mi |
| Registration #11 | 2019-09-03 | 114.420 mi |
| Registration #12 | 2019-09-03 | 114.420 mi |
| Registration #13 | 2019-09-03 | 114.420 mi |
| Registration #14 | 2019-09-03 | 114.420 mi |
| Registration #15 | 2019-09-03 | 114.420 mi |
| Registration #16 | 2019-09-03 | 114.420 mi |
| Registration #17 | 2019-09-03 | 114.420 mi |
| Registration #18 | 2019-09-03 | 114.420 mi |
| Registration #19 | 2019-09-03 | 114.420 mi |
| Registration #20 | 2019-09-03 | 114.420 mi |

More info >



Additional information

| | |
|-----------------|-----------|
| Number of seats | 8 |
| Engine number | NOT KNOWN |