



report date: 2024-03-28

General information

Make	MAZDA
Model	5 FURANO
Colour	Maroon
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-20
Pictures	24
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT #14	2022-11-12 12:37
MOT test number	975418077466
Result	✓ Passed
Next expiry date	2023-11-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-11-18 15:52
MOT test number	535470687102
Result	✓ Passed

MOT #12	2020-12-16 16:32
MOT test number	113056045270
Result	✓ Passed

MOT #11	2019-12-19 16:52
MOT test number	197989774490
Result	✓ Passed

- Advice** Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sills / both sides (6.1.1 (c) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-12-16 17:00
MOT test number	243969439067
Result	✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sills / both sides (6.1.1 (c) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #9** 2018-12-17 17:13**MOT test number** 804483711989**Result** ✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2018-12-17 17:13**MOT test number** 512524295351**Result** ✗ Failed

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect bulb fitted incorrectly (4.1.2 (c))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect bulb fitted incorrectly (4.1.2 (c))

**MOT #7** 2017-12-13 16:54**MOT test number** 682478555389**Result** ✓ Passed

**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front lower arms, rear bushes (2.4.G.2)

**MOT #6** 2016-12-21 16:22**MOT test number** 848527000189**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2015-12-16 15:41**MOT test number** 104328331292**Result** ✓ Passed**MOT #4** 2014-12-18 16:28**MOT test number** 479142854318**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2014-01-02 09:48**MOT test number** 658132804032**Result** ✓ Passed**MOT #2** 2013-08-17 11:55**MOT test number** 435809023213**Result** ✓ Passed**Notice** Offside rear tyre bold on inner edge almost to cords**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-08-17 11:07**MOT test number** 359379423281**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Offside rear tyre bold on inner edge almost to cords**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-14
Last registration	2022-11-12
Complete history	<a href="#">See info</a>



Registration #1	2010-09-14	28 mi
Registration #2	2013-08-17	37.359 mi
Registration #3	2013-08-17	37.359 mi
Registration #4	2014-01-02	40.608 mi
Registration #5	2014-12-18	45.783 mi
Registration #6	2015-12-16	50.711 mi
Registration #7	2016-12-21	55.504 mi
Registration #8	2017-12-13	60.728 mi
Registration #9	2018-05-29	65.277 mi
Registration #10	2018-05-29	65.277 mi
Registration #11	2018-05-29	65.277 mi
Registration #12	2018-05-29	65.277 mi
Registration #13	2018-05-29	65.277 mi
Registration #14	2018-05-29	65.277 mi
Registration #15	2018-05-29	65.277 mi
Registration #16	2018-05-29	65.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1410 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	LF 10895894