



HONDA




report date: 2024-11-08

General information

Make	HONDA
Model	INTEGRA 16V
Colour	Black
Year of manufacture	2000
Top speed	145 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	178 Nm at 7.300 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.7 mpg





Internet history

Entry 2

Date	2024-09-28
Pictures	19
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2023-07-22
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2013-03-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	4

MOT #5	2012-02-17 11:43
MOT test number	745078042025
Result	✓ Passed
Next expiry date	2013-03-01
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2011-03-02 09:48
MOT test number	496411061028
Result	✓ Passed

MOT #3	2007-08-14 12:11
MOT test number	542786127257
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Water in offside rear light lens
Advice	Front brake disc slightly pitted (3.5.1h)



MOT #2 2007-08-02 10:14

MOT test number 373514717462

Result ✗ Failed

- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Driver's seat insecure (6.2.A.1)
- Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
- Notice** Water in offside rear light lens
- Advice** Front brake disc slightly pitted (3.5.1h)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Shock absorber has negligible damping effect (2.7.5)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2006-05-31 09:35

MOT test number 381441356151

Result ✓ Passed

- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Front brakes pull slightly to nearside



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	V827ELW
Plate since	2019-09-29
Current registration	V827ELW
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled. If not, and you buy this HONDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this HONDA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2000-01-13
Last registration	2012-02-17
Complete history	See info



Registration #1	2000-01-13	10 mi
Registration #2	2006-05-31	56.374 mi
Registration #3	2007-08-02	59.471 mi
Registration #4	2007-08-14	60.183 mi
Registration #5	2009-05-20	61.277 mi
Registration #6	2009-05-20	61.277 mi
Registration #7	2009-05-20	61.277 mi
Registration #8	2009-05-20	61.277 mi

More info >



Safety ratings

NCAP rating ★★☆☆

Video [see crash video](#)



Dimensions & weight

Width	1705 mm
Height	1335 mm
Length	4400 mm
Kerb weight	1165 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	B18C61101079