





report date: 2024-03-29

General information

| Make | JAGUAR |
|---------------------|-------------------|
| Model | S-TYPE V6 SE |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 141 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 205 BHP |
|-------------------------|---------------------|
| Max. torque | 435 Nm at 1.900 rpm |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 25.9 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 36.2 mpg |



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1


Date 2021-08-30

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT #19 2022-08-12 14:32

MOT test number 532644937308

Result ✓ Passed

Next expiry date 2023-08-27

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))

MOT #18 2022-08-09 11:28

MOT test number 116646737584

Result X Failed

MAJOR Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

MAJOR Nearside Rear Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

DANGEROUS Front Inner Brake pad(s) less than 1.5 mm thick Low (1.1.13 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))

MAJOR Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MAJOR Offside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

MAJOR Offside Rear Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Rear Service brake excessively fluctuating (1.2.1 (e))

MOT #17 2021-08-28 11:11

MOT test number 108227857596

Advice Both sills covered with plastic cover and suspension components corroded

MOT #16 2021-08-28 11:11

MOT test number 579447048611

Result X Failed

CarCheck.co.uk page 3/14

Pass with rectification

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Both sills covered with plastic cover and suspension components corroded



report date: 2024-03-29

MOT #15 2020-10-14 13:18

MOT test number 223755668415

Result ✓ Passed

MOT #14 2019-03-30 14:04

MOT test number 351244878378

Result ✓ Passed

MOT #13 2019-03-27 10:15

MOT test number 709007818611

Result X Failed

Advice Nearside rear wheel binding

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Seat belt anchorage prescribed area strength or continuity significantly reduced nearside sill (7.1.1 (a) (i))

Advice Offside sill very corroded

MOT #12 2018-04-27 15:04

MOT test number 203453623024

Result \rightarrow Passed

Advice Full under body tray fitted not allowing full inspection

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2018-04-25 08:53

MOT test number 355525193930

Result X Failed

Advice Full under body tray fitted not allowing full inspection

Fail Offside Rear Inner Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Rear Inner Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Inner Front suspension has excessive play in a track control arm inner bush (2.5.B.2b)

MOT #10 2017-04-18 09:51

MOT test number 511943358966

Result
✓ Passed

Advice Tie bar/rod rubber bush deteriorated but not resulting in excessive movement Both front (2.4.G.2)

Advice Tyre worn close to the legal limit Both rear (4.1.E.1)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Covers fitted to underside

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement

Both front bushes (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Oil leak

MOT #9 2016-06-03 08:06

MOT test number 623605043764

Result ✓ Passed

Advice Offside Suspension component mounting prescribed area is corroded but not considered excessive outer sill but has plastic cover (2.4.A.3)

Advice Nearside Suspension component mounting prescribed area is corroded but not considered excessive outer sill but has plastic cover (2.4.A.3)

CarCheck.co.uk page 5/14



report date: 2024-03-29

| MOT #8 | | 2015-06-03 16:20 |
|----------|--|------------------|
| MOT test | number | 159234055192 |
| Result | | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Notice | Under-trays fitted obscuring some underside components | |

| MOT #7 | | 2014-05-22 11:12 |
|----------|--|------------------|
| MOT test | number | 545462144139 |
| Result | | ✓ Passed |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Notice | Child seat fitted not allowing full inspection of adult belt | |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Advice | Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Under-trays fitted obscuring some underside components | |

| MOT #6 | | 2014-05-22 10:00 |
|----------------|--|------------------|
| MOT test | number | 298022344143 |
| Result | | × Failed |
| Notice | Child seat fitted not allowing full inspection of adult belt | |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Advice | Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Under-trays fitted obscuring some underside components | |
| Fail Su | applementary Restraint System warning lamp indicates a fault (5.4.2) | |

CarCheck.co.uk page 6/14



report date: 2024-03-29

| MOT #5 | | 2013-05-22 10:59 |
|----------|--|------------------|
| MOT test | number | 447212943156 |
| Result | | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Notice | Under-trays fitted obscuring some underside components | |
| Notice | NS wiper slightly worn | |

| MOT #4 | | 2012-05-24 14:48 |
|----------|--|------------------|
| MOT test | number | 328595142139 |
| Result | | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Advice | Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2) | |
| Advice | Offside Rear Shock absorber has a slightly worn bush (2.7.4) | |
| Notice | Under-trays fitted obscuring some underside components | |
| Advice | Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2) | |
| Advice | Nearside Rear Shock absorber has a slightly worn bush (2.7.4) | |

| MOT #3 | 2011-06-14 16:04 |
|-----------------|------------------|
| MOT test number | 876775961178 |
| Result | ✓ Passed |

| MOT #2 | 2010-09-01 11:15 |
|-----------------|------------------|
| MOT test number | 281874940241 |
| Result | ✓ Passed |

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #1 2009-09-01 11:28

MOT test number 810564649261

Result ✓ Passed

Notice Both front tyres wearing low on inner tread edges

Notice Both wiper blades starting to split

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this JAGUAR had different number plates. door of plates furthe scinors

CarCheck.co.uk page 11/14



BV56EHK report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 21 |
| First mileage registration | 2006-09-07 |
| Last registration | 2022-08-12 |
| Complete history | See info |



| Registration #1 | 2006-09-07 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2009-09-01 | 21.387 mi |
| Registration #3 | 2010-09-01 | 26.229 mi |
| Registration #4 | 2011-06-14 | 29.740 mi |
| Registration #5 | 2012-05-24 | 38.711 mi |
| Registration #6 | 2013-05-22 | 47.958 mi |
| Registration #7 | 2014-05-22 | 62.176 mi |
| Registration #8 | 2014-05-22 | 62.176 mi |
| Registration #9 | 2015-06-03 | 74.778 mi |
| Registration #10 | 2016-06-03 | 88.722 mi |
| Registration #11 | 2017-04-18 | 93.615 mi |
| Registration #12 | | 71.777 es |
| Registration #13 | | 71.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 71.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 11.777 mi |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 es |

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1818 mm |
|---------------------|---------|
| Height | 1447 mm |
| Length | 4905 mm |
| Wheel base | 2909 mm |
| Kerb weight | 1790 kg |
| Max. allowed weight | 2255 kg |

Additional information

| Fuel tank capacity | 69 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 01372827G |

CarCheck.co.uk page 14/14