



Mercedes-Benz

**SD58WDG**

report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB P/V
Colour	Silver
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	280 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-21
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	77
Total items failed	23

MOT #22	2023-11-16 15:07
MOT test number	758985311430
Result	✓ Passed
Next expiry date	2024-11-21
Minor	Trailer electrical socket insecure (4.10 (a) (i))
Advice	Parking brake poor 16%

MOT #21	2022-11-04 14:20
MOT test number	674323580152
Result	✓ Passed
Minor	Rear Position lamp with a multiple light source up to 1/2 not functioning both sides (4.2.1 (a) (i))

MOT #20	2022-11-04 13:34
MOT test number	852076720902
Result	✗ Failed
Minor	Rear Position lamp with a multiple light source up to 1/2 not functioning both sides (4.2.1 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #19	2021-11-05 10:01
MOT test number	129827768220
Result	✓ Passed



MOT #18

2020-11-18 11:37

MOT test number

344660945454

Result

✓ Passed

- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Front Plastic shock shroud damaged.
- Advice

Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Front Both plastic inner wings insecure on front edges.
- Advice

Nearside Rear Metal shock shroud rusted away.
- Minor

Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning Black tape over part of lens. (4.3.1 (a) (i))
- Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Nearside Rear Reflector damaged/cracked.
- Advice

Offside Front Nail in tyre screw in tread.

**MOT #17**

2020-11-16 15:26

**MOT test number**

876207887966

**Result****✗ Failed****Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning Black tape over part of lens. (4.3.1 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Both plastic inner wings insecure on front edges.**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Metal shock shroud rusted away.**Advice** Offside Front Nail in tyre screw in tread.**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Reflector damaged/cracked.**Fail** Steering column has excessive movement up and down Excessive movement inside rack worm and pinion allowing column to move up and down. (2.2.2 (a))**Advice** Offside Front Plastic shock shroud damaged.

**MOT #16**

2019-11-18 17:14

**MOT test number**

299982318005

**Result**

✓ Passed

- Advice** Offside Front Inner Wing loose.
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Reflector cracked/broken.
- Advice** Nearside Rear Shock shroud corroded away.
- Advice** Nearside Front Inner Wing loose.
- Advice** Slight dampness around steering rack pinion area.
- Advice** Nearside Front Shock shroud split.
- Advice** Offside Front Shock shroud damaged/krinkled.

**MOT #15**

2019-11-18 16:40

**MOT test number**

695471867876

**Result**

✗ Failed

- Advice** Nearside Front Inner Wing loose.
- Advice** Nearside Rear Reflector cracked/broken.
- Advice** Nearside Rear Shock shroud corroded away.
- Advice** Offside Front Shock shroud damaged/krinkled.
- Fail** Exhaust system insecure Rear bracket corroded away and detached from exhaust. (6.1.2 (a))
- Advice** Offside Front Inner Wing loose.
- Advice** Slight dampness around steering rack pinion area.
- Advice** Nearside Front Shock shroud split.
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))



MOT #14

2019-11-12 17:09

MOT test number

904520312545

Result

✗ Failed

- Advice

Nearside Rear reflector damaged.
- Advice

Rear exhaust mount corroded.
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Front head lamp slightly condensated inside.
- Advice

Nearside Rear shock shroud corroded away.
- Advice

Both front arch covers adrift/loose on front corners.
- Fail

Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice

Brake lamp amber warning lamp on.

**MOT #13**

2019-11-11 13:16

**MOT test number**

256465192352

**Result****✗ Failed**

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect condensated inside. (4.1.2 (c))

**Advice** Offside Front head lamp slightly condensated inside.

**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Nearside Rear shock shroud corroded away.

**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn drop link lower bush worn. (5.3.4 (a) (i))

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Both front arch covers adrift/loose on front corners.

**Fail** Offside Position lamp not working middle marker lamp. (4.2.1 (a) (ii))

**Advice** Brake lamp amber warning lamp on.

**Fail** Offside Rear reflector missing (4.8.2 (a) (ii))

**Advice** Nearside Rear reflector damaged.

**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn axle bush (5.3.4 (a) (i))

**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**Advice** Rear exhaust mount corroded.

**Fail** Trailer electrical socket wiring insulation damaged or deteriorated and likely to cause a short-circuit (4.10 (b) (ii))



**MOT #12**

2018-11-19 12:31

**MOT test number**

717651453379

**Result**

✓ Passed

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11**

2018-11-17 09:55

**MOT test number**

499149955465

**Result**

✗ Failed

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10**

2017-11-06 11:13

**MOT test number**

541729950127

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #9**

2017-11-06 11:13

**MOT test number**

982759728928

**Result****✗ Failed**

- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Trailer electrical socket damaged so that lead cannot be securely connected (1.9.3b)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Pass with rectification** Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #8**

2016-11-21 11:27

**MOT test number**

177161030923

**Result****✓ Passed**

- Advice** N/s/r indicator slightly discoloured
- Advice** O/s/f tyre slightly worn on outer edge
- Advice** Wiper blades slightly deteriorated
- Advice** Slight play in both rear anti roll bar D bushes

**MOT #7**

2015-11-03 08:05

**MOT test number**

881413148200

**Result****✓ Passed**

- Advice** N/s seat belt buckle casing deteriorated
- Advice** N/s/r handbrake effort only just met requirements
- Advice** Slight play in both rear anti roll bar D bushes

**MOT #6** 2014-11-22 09:20**MOT test number** 356176524373**Result** ✓ Passed**Notice** O/s centre side marker light lens insecure**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**MOT #5** 2014-11-22 07:39**MOT test number** 125776624323**Result** ✗ Failed**Notice** O/s centre side marker light lens insecure**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**MOT #4** 2013-11-04 17:13**MOT test number** 879368003352**Result** ✓ Passed**MOT #3** 2012-11-09 15:29**MOT test number** 547894612370**Result** ✓ Passed**MOT #2** 2011-12-05 15:14**MOT test number** 427609631347**Result** ✓ Passed



MOT #1		2011-12-05 15:14
MOT test number		738559131329
Result		✗ Failed
Pass with rectification	Rear fog lamp not working (1.3.2b)	
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Body has a sharp edge caused by damage (6.1.C.1)	



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2024

✓  
**MOT**

**Expires:**  
21 November 2024

Tax status		Valid until 1 September
Days left		125
MOT expiry date		21 November 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>SD58WDG</b>
Plate since	2019-06-29
Current registration	 <b>SD58WDG</b>
Plate since	2019-06-29

More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-01-06
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2009-01-06	27 mi
Registration #2	2011-12-05	44.302 mi
Registration #3	2012-11-09	63.067 mi
Registration #4	2013-11-04	79.491 mi
Registration #5	2014-11-22	88.496 mi
Registration #6	2014-11-22	88.497 mi
Registration #7	2015-11-03	95.050 mi
Registration #8	2016-11-21	107.926 mi
Registration #9	2017-11-06	118.550 mi
Registration #10	2017-11-06	118.550 mi
Registration #11	2018-11-17	135.792 mi
Registration #12	2018-11-19	135.794 mi
Registration #13	2019-11-19	152.557 mi
Registration #14	2019-11-19	152.557 mi
Registration #15	2019-11-19	152.557 mi
Registration #16	2019-11-19	152.557 mi
Registration #17	2019-11-19	152.557 mi
Registration #18	2019-11-19	152.557 mi
Registration #19	2019-11-19	152.557 mi
Registration #20	2019-11-19	152.557 mi
Registration #21	2019-11-19	152.557 mi
Registration #22	2019-11-19	152.557 mi
Registration #23	2019-11-19	152.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1960 mm
Height	3050 mm
Length	6940 mm
Kerb weight	2280 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	64698551773317