



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.4 mpg
CO2 emission	221 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-08-31
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-04-03
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	56
Total items failed	10

**MOT #24**

2023-03-10 16:07

MOT test number

984733063557

Result**✗ Failed**

MAJOR Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Advice Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened slightly corroded (1.1.14 (a) (ii))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn wishbone rear bush split (5.3.4 (a) (i))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn wishbone rear bush split (5.3.4 (a) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MAJOR Nearside Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

MOT #23

2022-04-04 15:25

MOT test number

104877166958

Result**✓ Passed**

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #22

2022-04-02 12:06

MOT test number

373784772325

Result

✗ Failed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

MOT #21

2021-03-10 16:21

MOT test number

938953552418

Result

✓ Passed

Minor Stop lamp(s) with a multiple light source up to 1/2 not functioning high level. (4.3.1 (a) (i))**Advice** Nearside Rear tyre has surface cracking through tread areas.

MOT #20

2021-03-09 15:28

MOT test number

448278986684

Result

✗ Failed

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear tyre has surface cracking through tread areas.**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt inner boot split. (6.1.7 (g) (ii))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Stop lamp(s) with a multiple light source up to 1/2 not functioning high level. (4.3.1 (a) (i))**MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**MAJOR** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

**MOT #19** 2020-01-07 09:31**MOT test number** 955332365579**Result** ✓ Passed**MOT #18** 2020-01-03 15:41**MOT test number** 655725210320**Result** ✗ Failed

- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #17 2019-01-09 16:13**MOT test number** 887834688431**Result** ✓ Passed

- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Engine MIL illuminated

MOT #16 2018-01-31 09:43**MOT test number** 807013724183**Result** ✓ Passed**MOT #15** 2017-01-17 18:05**MOT test number** 840416960288**Result** ✓ Passed

**MOT #14**

2017-01-17 11:25

MOT test number

903817831646

Result**✗ Failed**

Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

MOT #13

2016-05-18 14:16

MOT test number

467507802463

Result**✓ Passed****MOT #12**

2016-03-11 09:59

MOT test number

833478962620

Result**✗ Failed**

Fail Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Fail Centre Front Lower Exhaust system not adequately supported (7.1.1)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Centre Rear Upper Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Fail Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11

2015-02-09 10:23

MOT test number

788240945010

Result**✓ Passed**

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Rear coil spring corroded (2.4.C.1b)

**MOT #10**

2015-02-09 10:23

MOT test number

596410745089

Result

✗ Failed

Pass with rectification Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Rear coil spring corroded (2.4.C.1b)

MOT #9

2013-09-02 12:24

MOT test number

147365943260

Result

✓ Passed

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Notice Front tyres worn on inner edges (tracking reqd)

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #8

2013-09-02 12:24

MOT test number

556625143205

Result

✗ Failed

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Notice Front tyres worn on inner edges (tracking reqd)

Pass with rectification Offside Outer Front constant velocity joint is insecure (2.5.C.1b)

MOT #7

2012-08-17 16:17

MOT test number

929350532288

Result

✓ Passed

Notice N/s/r body damage (sharpe edge)

Advice Offside Rear coil spring corroded (2.4.C.1b)



MOT #6	2012-08-14 16:09
---------------	------------------

MOT test number	779947922219
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Notice N/s/r body damage (sharpe edge)

Advice Offside Rear coil spring corroded (2.4.C.1b)

MOT #5	2011-08-26 11:10
---------------	------------------

MOT test number	189458831214
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-08-17 09:32
---------------	------------------

MOT test number	644449520257
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-09-24 14:58
---------------	------------------

MOT test number	411128368246
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-09-03 14:23
---------------	------------------

MOT test number	340806747207
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-06-30 14:40
---------------	------------------

MOT test number	581281486175
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
13 November 2023

✕
MOT

Expired:
3 April 2023

Tax status	Expired at 13 November 2023
Days left	167 days too late
MOT expiry date	3 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	LM03XCG
Plate since	2024-03-28
Current registration	LM03XCG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-06-24
Last registration	2023-03-10
Complete history	See info



Registration #1	2003-06-24	25 mi
Registration #2	2006-06-30	16.735 mi
Registration #3	2007-09-03	25.657 mi
Registration #4	2008-09-24	28.399 mi
Registration #5	2010-08-17	36.210 mi
Registration #6	2011-08-26	47.280 mi
Registration #7	2012-08-14	56.097 mi
Registration #8	2012-08-17	56.097 mi
Registration #9	2013-09-02	63.718 mi
Registration #10	2015-02-09	71.572 mi
Registration #11	2016-03-11	74.985 mi
Registration #12	2016-05-18	75.112 mi
Registration #13	2016-05-18	75.112 mi
Registration #14	2016-05-18	75.112 mi
Registration #15	2016-05-18	75.112 mi
Registration #16	2016-05-18	75.112 mi
Registration #17	2016-05-18	75.112 mi
Registration #18	2016-05-18	75.112 mi
Registration #19	2016-05-18	75.112 mi
Registration #20	2016-05-18	75.112 mi
Registration #21	2016-05-18	75.112 mi
Registration #22	2016-05-18	75.112 mi
Registration #23	2016-05-18	75.112 mi
Registration #24	2016-05-18	75.112 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1437 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	AZJ 720635