





General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | BEETLE 8V |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 111 mph |
| 0 - 60 mph | 12.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 102 BHP |
|-------------------------|---------------------|
| Max. torque | 147 Nm at 3.800 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 36.7 mpg |





Internet history

| Entry 1 | |
|----------|------------|
| Date | 2021-06-30 |
| Pictures | 11 |

Listing price

View report



source: autotrader.co.uk



MOT history

| МОТ #20 | 2022-07-18 15:42 |
|---|------------------|
| MOT test number | 163786382875 |
| Result | ✓ Passed |
| Next expiry date | 2023-07-17 |
| Minor Nearside Windscreen damaged but not adversely affecting driver's view | v (3.2 (a) (i)) |
| Advice Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i)) | |
| Advice Exhaust mounting defective centre (6.1.2 (a)) | |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #19 | 2022-07-13 15:34 |
|---|------------------|
| MOT test number | 525146008249 |
| Result | 🗙 Failed |
| Advice Nearside Rear Integral body structure is corroded but structural rigidity is not s reduced sill (6.1.1 (c) (i)) | ignificantly |
| Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) | |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Fail Offside Front Direction indicator not working (4.4.1 (a) (ii)) | |
| Fail Nearside Front Integral body structure corroded to the extent that the rigidity of the significantly reduced outer sill (6.1.1 (c) (i)) | ne assembly is |
| Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) | (i)) |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Advice Exhaust mounting defective centre (6.1.2 (a)) | |
| Fail Nearside Headlamp aim not tested (4.1.2 (b)) | |
| Fail Offside Rear Integral body structure corroded to the extent that the rigidity of the significantly reduced inner and outer sill (6.1.1 (c) (i)) | assembly is |





| MOT #18 | 2021-07-09 11:42 |
|-----------------|------------------|
| MOT test number | 585288921619 |
| Result | ✓ Passed |
| | |
| MOT #17 | 2020-09-23 09:36 |
| | 447010062506 |
| MOT test number | 447910963506 |

| MOT #16 | 2019-09-07 07:57 |
|--|------------------|
| MOT test number | 187387839477 |
| Result | ✓ Passed |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #15 | 2018-09-12 07:56 |
|-----------------|------------------|
| MOT test number | 411978671523 |
| Result | ✓ Passed |

| MOT #14 | | 2017-09-13 10:18 |
|----------|---|------------------|
| MOT test | number | 653086751795 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #13 | 2016-12-15 09:26 |
|-----------------|------------------|
| MOT test number | 647747668315 |
| Result | ✓ Passed |
| | |

| MOT #12 | 2015-11-20 09:28 |
|-----------------|------------------|
| MOT test number | 722756152160 |
| Result | ✓ Passed |





| MOT #11 | 2014-11-06 11:35 |
|-----------------|------------------|
| MOT test number | 327990114354 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2013-10-26 09:23 |
| MOT test number | 205599393218 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2012-10-25 08:54 |
| MOT test number | 687749892215 |
| Result | ✓ Passed |

| мот | # 0 |
|-----|------------|

| MOT #8 | | 2011-11-01 10:26 |
|----------|---|------------------|
| MOT test | number | 415015201478 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #7 | 2011-10-28 16:31 | |
|---|------------------|--|
| MOT test number | 756201901339 | |
| Result | 🗙 Failed | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | | |
| Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) | | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | | |
| Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) | | |

| МОТ #6 | 2011-03-14 09:18 |
|-----------------|------------------|
| MOT test number | 876493571011 |
| Result | ✓ Passed |





| MOT #5 | 2010-03-31 16:01 |
|---|------------------|
| MOT test number | 662190790015 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2009-02-24 13:52 |
| MOT test number | 113405359030 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2007-06-15 14:19 |
| MOT test number | 111086567166 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2007-06-15 11:58 |
| MOT test number | 292846467408 |
| Result | 🗙 Failed |
| Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) | |
| FailNearside Front Direction indicator not working (1.4.A.2c) | |
| Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) | |

| MOT #1 | | 2006-07-10 10:56 |
|----------|---|------------------|
| MOT test | number | 932861696172 |
| Result | | Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FETTOR |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE . |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | |
|--|-------------|
| ******** | |
| | |
| and a second sec | |
| *********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2003-07-02 |
| Last registration | 2022-07-18 |
| Complete history | See info |



| Registration #1 | 2003-07-02 | 27 mi |
|------------------|------------|------------|
| Registration #2 | 2006-07-10 | 25.547 mi |
| Registration #3 | 2007-06-15 | 34.009 mi |
| Registration #4 | 2007-06-15 | 34.009 mi |
| Registration #5 | 2009-02-24 | 45.684 mi |
| Registration #6 | 2010-03-31 | 53.793 mi |
| Registration #7 | 2011-03-14 | 60.375 mi |
| Registration #8 | 2011-10-28 | 64.633 mi |
| Registration #9 | 2011-11-01 | 64.633 mi |
| Registration #10 | 2012-10-25 | 76.436 mi |
| Registration #11 | 2013-10-26 | 90.693 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.707 esi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 est |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.777 est |
| Registration #18 | | 11.202 est |
| Registration #19 | | 11.777 esi |
| Registration #20 | | 11.317 est |
| Registration #21 | | 11.777 esi |
| Registration #22 | | 10.200 est |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1724 mm Height 1498 mm Length 4081 mm Wheel base 2508 mm Kerb weight 1385 kg Additional information Fuel tank capacity 55 I **Fuel delivery** Multi-Point Injection

2

2

Number of doors Number of axles