





report date: 2024-03-28

General information

| Make | JAGUAR |
|---------------------|-------------------|
| Model | X-TYPE V6 CLASSIC |
| Colour | Blue |
| Year of manufacture | 2005 |
| Top speed | 138 mph |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 194 BHP |
|-------------------------|---------------------|
| Max. torque | 244 Nm at 3.000 rpm |
| Engine capacity | 2.496 cc |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 20.5 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 29.1 mpg |
| CO2 emission | 239 g/km |
| CO2 label | L |



CarCheck.co.uk page 1/18



Internet history

Entry 1

Date 2021-07-24

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/18



MOT history

| MOT expiry date | 2024-11-05 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 16 |
| Failed MOT tests | 6 |
| Total advice items | 90 |
| Total items failed | 18 |

| MOT #22 | 2023-11-06 14:0 |)9 |
|----------------------------|---|----|
| MOT test | number 69809942633 | 7 |
| Result | ✓ Passe | d |
| Next expi | ry date 2024-11-0 |)5 |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing Tyre cracking to sidewalls (5.2.3 (d) | |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge Tyre worn on inside edge (5.2.3 (e)) | |
| Advice | Nearside Non obligatory mirror damaged Mirror glass cracked. | |
| Advice join to flex | Nearside Rear Brake pipe corroded, covered in grease or other material Brake pipe corroded at tible hose (1.1.11 (c)) | |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) | |
| Advice | Brake pedal wearing smooth (1.1.2 (c)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking to sidewalls (5.2.3 (d) (ii)) | |
| Advice corroded (| Rear Brake pipe corroded, covered in grease or other material Brake pipes above rear subframe 1.1.11 (c)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Tyre worn on inside edge (5.2.3 (e)) | |
| Advice to flexible | Offside Rear Brake pipe corroded, covered in grease or other material Brake pipe corroded at join hose $(1.1.11 \ (c))$ | |

CarCheck.co.uk page 3/18



MOT #21 2023-11-03 12:38

MOT test number 875132292751

Result **X** Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre worn on inside edge (5.2.3 (e)) Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Brake pipe corroded at join to flexible hose (1.1.11 (c)) **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking to sidewalls (5.2.3 (d) (ii)) Fail Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tyre worn on inside edge (5.2.3 (e)) **Advice** Brake pedal wearing smooth (1.1.2 (c)) Advice Rear Brake pipe corroded, covered in grease or other material Brake pipes above rear subframe corroded (1.1.11 (c)) **Advice** Nearside Non obligatory mirror damaged Mirror glass cracked. Advice Offside Rear Brake pipe corroded, covered in grease or other material Brake pipe corroded at join to flexible hose (1.1.11 (c)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Tyre cracking to sidewalls (5.2.3 (d) (ii)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/18



RJ55MXG

report date: 2024-03-28

MOT #20 2023-08-01 15:11

MOT test number 896939555821

Result X Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Coil spring with an unsafe modification EITHER FITTED INCORRECT OR WRONG SPRING TOUCHING BODY (5.3.1 (d) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Offside Rear Suspension arm pin or bush excessively worn AXLE BUSH (5.3.4 (a) (i))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Suspension arm pin or bush excessively worn AXLE BUSH (5.3.4 (a) (i))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Nearside Rear Lower Suspension arm pin or bush excessively worn ARM BUSH (5.3.4 (a) (i))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #19 2022-08-09 12:16

MOT test number 656808995501

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front signs of coil spring rubbing on inner suspension tower

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 5/18



MOT #18 2022-08-09 08:22

MOT test number 943563949756

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front signs of coil spring rubbing on inner suspension tower

MOT #17 2021-08-25 08:31

MOT test number 501855371041

Result ✓ Passed

MOT #16 2020-09-17 09:45

MOT test number 583729264844

Result
✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Rear Lower Suspension arm ball joint dust cover severely deteriorated inner joint (5.3.4 (b) (i))

Advice Nearside Play in steering rack inner joint(s)

Minor Offside Rear Lower Suspension arm ball joint dust cover severely deteriorated inner joint (5.3.4 (b)

(i))

MOT #15 2019-10-04 13:48

MOT test number 548742513605

Advice Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

CarCheck.co.uk page 6/18



MOT #14 2018-10-16 09:11

MOT test number 896897675124

Result ✓ Passed

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Exhaust slighty corroded

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #13 2018-10-04 14:50

MOT test number 496003082062

Result X Failed

Advice Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Advice Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Exhaust slighty corroded

MOT #12 2017-09-07 14:31

MOT test number 563798891969

Result

Passed

CarCheck.co.uk page 7/18



MOT #11 2016-09-08 14:00

MOT test number 843468354863


Result ✓ Passed **Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) **Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a) Oil leak **Advice** Advice Offside Front Brake hose slightly chafed has been rubbing in the past (3.6.B.4d) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Rear Upper Suspension arm corroded but not seriously weakened (2.4.G.1) Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a) Advice Advice Nearside Front Brake hose slightly chafed has been rubbing in the past (3.6.B.4d) Offside Rear Brake pipe slightly corroded front to rear pipe (3.6.B.2c) **Advice** Advice Engine bay covers obscuring the view of components Offside Rear coil spring corroded wanted soon (2.4.C.1b) Advice Advice Nearside Rear Upper Suspension arm corroded but not seriously weakened (2.4.G.1)

CarCheck.co.uk page 8/18



RJ55MXG

report date: 2024-03-28



| MOT #9 | | 2015-10-06 09:00 |
|--|--------|------------------|
| MOT test | number | 981381037868 |
| Result | | ✓ Passed |
| Advice Offside Brake pipe slightly corroded front to rear above the rear axle required soon (3.6.B.2c) | | |
| Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush required soon (2.4.G.2) | | |

CarCheck.co.uk page 9/18



MOT #8 2015-10-06 09:00

MOT test number 114839193232

Result X Failed

Pass with rectification Nearside Front Headlamp aim too high (1.8)

Advice Offside Brake pipe slightly corroded front to rear above the rear axle required soon (3.6.B.2c)

Pass with rectification Nearside Brake pipe inadequately clipped front to rear pipe un-clipped (3.6.B.1)

Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush required soon (2.4.G.2)

MOT #7 2014-10-07 11:32

MOT test number 455990184294

Result \(\sqrt{Passed} \)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice All tyres worn on edges

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice Front tyres cracking on side wall (no cords showing)

MOT #6 2013-09-26 16:02

MOT test number 445159163282

Result \(\sqrt{Passed} \)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #5 2012-09-13 10:29

MOT test number 566667252214

Result
✓ Passed

CarCheck.co.uk page 10/18



MOT #2

RJ55MXG report date: 2024-03-28

2009-09-24 15:04

| MOT #4 | 2011-09-14 14:28 |
|-----------------|------------------|
| MOT test number | 165287151202 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2010-09-16 09:55 |
| MOT test number | 541199550234 |
| Result | ✓ Passed |
| Notice Oil leak | |

| MOT test number | 314747869229 |
|-----------------|------------------|
| Result | ✓ Passed |
| | |
| MOT #1 | 2008-09-22 12:47 |
| MOT test number | 240686368241 |
| Result | ✓ Passed |

CarCheck.co.uk page 11/18



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 307 |
| MOT expiry date | 5 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 12/18



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



Owner history

| For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full reports are considered to the current and see all owner registrations. | |
|---|------------------|
| | |
| | |
| *************************************** | |
| | |
| ********** | |
| *************************************** | |
| ************** | |
| | More info > |
| Plate changes | |
| See in this check if this JAGUAR had different number plates. | |
| Number of plates | |
| Current registration | OK SIE SIE |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 15/18



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 16/18



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 24 |
| First mileage registration | 2005-09-09 |
| Last registration | 2023-11-06 |
| Complete history | See info |



| 2005-09-09 | 8 mi |
|------------|--|
| 2008-09-22 | 36.728 mi |
| 2009-09-24 | 43.976 mi |
| 2010-09-16 | 58.146 mi |
| 2011-09-14 | 65.056 mi |
| 2012-09-13 | 67.709 mi |
| 2013-09-26 | 71.015 mi |
| 2014-10-07 | 72.403 mi |
| 2015-10-06 | 73.310 mi |
| 2015-10-06 | 73.310 mi |
| 2016-09-08 | 74.776 mi |
| 2016-09-08 | 74.776 mi |
| | 11.777 es |
| | 71.777 es |
| | 11.777 es |
| | 71.777 es |
| | 11.777 es |
| | 71.777 es |
| | 11.777 es |
| | 71.777 es |
| | 2008-09-22 2009-09-24 2010-09-16 2011-09-14 2012-09-13 2013-09-26 2014-10-07 2015-10-06 2015-10-06 2016-09-08 2016-09-08 |

More info >



Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 2003 mm |
|---------------------|---------|
| Height | 1483 mm |
| Length | 4716 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1605 kg |
| Max. allowed weight | 2105 kg |

Additional information

| Fuel tank capacity | 61 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 508734419XB |

CarCheck.co.uk page 18/18