





General information

Make	MERCEDES
Model	B-CLASS B200 TURBO
Colour	Silver
Year of manufacture	2007
Top speed	135 mph
0 - 60 mph	7.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	190 BHP
Max. torque	279 Nm at 4.850 rpm
Engine capacity	2.035 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.5 mpg
CO2 emission	197 g/km
CO2 label	J







Internet history

Entry 1	
Date	2021-07-15
Pictures	21
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-13
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	13
Total items failed	22

MOT #21	2023-11-29 13:59	
MOT test number	818444636471	
Result	✓ Passed	
Next expiry date	2024-12-13	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Front Inner Tyre worn close to legal limit/worn on edge Both front tyres on legal limit at time of test. OS 1.6MM NS 1.7MM (5.2.3 (e))		
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		

МОТ #20	2022-12-14 17:13
MOT test number	444405694431
Result	✓ Passed

MOT #19		2021-12-07 16:19
MOT test	number	182980807243
Result		✓ Passed
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorate	d (6.1.7 (g) (i))

MOT #18	2020-11-16 09:52
MOT test number	402190616452
Result	✓ Passed





MOT #	17	2019-05-17 13:48
MOT te	est number	380135930455
Result		✓ Passed
Advid	Both rear tyres inner edges wearing unevenly	
Advid	e Nearside Front Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))
MOT #	16	2019-05-16 14:03
MOT te	est number	783297510035
Result		🗙 Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1	. (b) (ii))
Advid	e Nearside Front Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail ingress	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no lon of dirt (6.1.7 (g) (ii))	iger prevents the
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advid	Both rear tyres inner edges wearing unevenly	

FailNearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #15	2018-05-31 13:09
MOT test number	579830940371
Result	✓ Passed





MOT #14	2018-05-29 13:39
MOT test number	918730886691
Result	× Failed
Pass with rectification Offside Headlamp aim too low (4.1.2 (a))	
Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii))	longer prevents the
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no ingress of dirt (6.1.7 (g) (ii))	o longer prevents the
MOT #13	2017-05-23 12:59
MOT test number	938991621431
Result	✓ Passed
Advice Nearside Rear Nail in tyre	
MOT #12	2016-05-18 14:54
MOT test number	611203351130
Result	✓ Passed
MOT #11	2016-05-10 09:47
MOT test number	234644666092
Result	🗙 Failed
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Offside Front Outer Tyre worn close to the legal limit (4.1.E.1)	
Offside Holic Odder Tyle word close to the legal limit (4.1.L.1)	
Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #10	2015-05-13 14:57
MOT test number	839813835132
Result	✓ Passed





MOT #9	2015-05-12 17:33
MOT test number	288422735131
Result	🗙 Failed
Fail Direction indicator incorrect colour (1.4.A.2f)	
Fail Offside Front Tie bar/rod ball joint dust cover excessively damaged so that it no ingress of dirt (2.4.G.2)	o longer prevents the
Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail Nearside Front Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	

MOT #8	2014-05-12 13:38
MOT test number	907862834160
Result	✓ Passed

MOT #7	2014-05-07 13:40
MOT test number	236117724403
Result	🗙 Failed
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to (4.1.D.1a) Notice Nail in offside rear tyre	reach the ply or cords
МОТ #6	2013-05-03 17:29
MOT test number	119133923194

Result

✓ Passed



MOT #	5	2013-04-30 14:39
MOT te	est number	829830723101
Result		🗙 Failed
Fail	Nearside Front Wheel bolt(s) missing (4.2.A.1e)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Offside Front Wheel bolt(s) missing (4.2.A.1e)	

MOT #4	2012-08-11 09:32
MOT test number	489074722236
Result	✓ Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2011-08-10 13:44
MOT test number	699812521250
Result	✓ Passed

MOT #2	2010-08-04 16:25
MOT test number	170966510252
Result	✓ Passed

MOT #1	2010-07-30 13:49
MOT test number	574071610256
Result	🗙 Failed
Fail Offside Rear coil spring fractured (2.4.C.1a)	

FX07XYF

report date: 2024-03-29



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 13 December 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-13
Last registration	2023-11-29
Complete history	See info



2007-03-13	16 mi
2010-07-30	68.967 mi
2010-08-04	69.062 mi
2011-08-10	76.851 mi
2012-08-11	84.019 mi
2013-04-30	88.507 mi
2013-05-03	88.507 mi
2014-05-07	93.560 mi
2014-05-12	93.711 mi
2015-05-12	100.177 mi
2015-05-13	100.184 mi
2016-05-10	109.180 mi
	11.777 est
	11.777 est
	11.707 est
	11.777 est
	11.777 esi
	11.777 est
	11.777 est
	11.777 mi
	1.77 m
	2010-07-30 2010-08-04 2011-08-10 2012-08-11 2013-04-30 2013-05-03 2014-05-07 2014-05-12 2015-05-12 2015-05-13 2016-05-10

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1370 kg
Additional information	
Additional information Fuel tank capacity	54 l
	54 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5