



**RF53RYV**

report date: 2024-03-28

General information

Make	FORD
Model	KA
Colour	Red
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg






Internet history

Entry 1

Date	2021-05-23
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history****MOT #27**

2022-09-06 08:17

**MOT test number**

776331182334

**Result**

✓ Passed

**Next expiry date**

2023-09-13

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi pipe deteriorated (6.1.2 (a))

**MOT #26**

2022-09-05 12:46

**MOT test number**

285588238102

**Result****✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases flexi pipe deteriorated (6.1.2 (a))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))



MOT #25

2021-09-14 08:36

MOT test number

715583795732

Result

✓ Passed

- Advice

Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #24**

2021-09-01 10:16

**MOT test number**

838844472822

**Result****✗ Failed**

- Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis sill (5.3.6 (a) (i))
- MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis sill (5.3.6 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis sill (5.3.6 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #23**

2020-09-01 09:48

**MOT test number**

575093610233

**Result****✓ Passed****MOT #22**

2020-09-01 09:48

**MOT test number**

691966368943

**Result****✗ Failed**

- Pass with rectification** Nearside Rear Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))

**MOT #21**

2019-08-30 10:25

**MOT test number**

684317692611

**Result**

✓ Passed

**Advice**

Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #20**

2019-08-27 14:53

**MOT test number**

265900592817

**Result**

✗ Failed

**Advice**

Nearside Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MAJOR**

Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #19**

2018-09-04 11:13

**MOT test number**

640890037502

**Result**

✓ Passed

**Advice**

Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice**

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

**MOT #18**

2018-08-29 14:41

**MOT test number**

929456804577

**Result****✗ Failed**

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Vehicle structure is corroded but structural rigidity is not significantly reduced central (6.1.1 (c) (i))

**Advice** Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MAJOR** Power steering component leaking reservoir area, suspected to be over full (2.1.5 (a))

**Advice** Offside Front Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner wheel arch (6.2.2 (d) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

**Advice** Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

**Advice** Offside Vehicle structure is corroded but structural rigidity is not significantly reduced central (6.1.1 (c) (i))

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**Advice** Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #17**

2017-09-07 09:11

**MOT test number**

689841242954

**Result****✓ Passed**



**MOT #16**

2017-09-06 10:44

**MOT test number**

926128567220

**Result****✗ Failed****Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Steering rack gaiter split (2.2.D.2d)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #15**

2016-10-27 10:15

**MOT test number**

983291770501

**Result****✓ Passed****Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Rear Inner Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Inner Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Exhaust rusty**MOT #14**

2015-10-26 15:22

**MOT test number**

116996673277

**Result****✓ Passed****Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Wishbone bushes starting to split**Advice** Nearside Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Rear wiper split

**MOT #13**

2015-10-26 09:00

**MOT test number**

750678857654

**Result****✗ Failed****Advice** Wishbone bushes starting to split**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Rear wiper split**Fail** Offside Inner Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Advice** Offside Front Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)**MOT #12**

2014-10-22 08:58

**MOT test number**

938295294289

**Result****✓ Passed****Advice** Front Sub-frame attachment slightly corroded (2.4.G.1)**Notice** Exhaust rusty**MOT #11**

2013-10-21 11:31

**MOT test number**

437254793242

**Result****✓ Passed****MOT #10**

2013-10-21 09:07

**MOT test number**

456694693211

**Result****✗ Failed****Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #9** 2012-10-30 09:02**MOT test number** 598634802346**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2011-10-25 09:39**MOT test number** 867108891217**Result** ✓ Passed**MOT #7** 2010-11-02 09:43**MOT test number** 661646200335**Result** ✓ Passed**MOT #6** 2009-10-19 09:17**MOT test number** 182282599211**Result** ✓ Passed

- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)
- Notice** Os rack gaiter twisted /slight play ns rack end /

**MOT #5** 2009-10-19 09:17**MOT test number** 412712299227**Result** ✗ Failed

- Notice** Os rack gaiter twisted /slight play ns rack end /
- Pass with rectification** Offside Headlamp aim too low (1.8)
- Advice** Power steering component(s) has slight seepage from a component (2.3.3b)

**MOT #4** 2008-10-22 16:56**MOT test number** 953236698227**Result** ✓ Passed**MOT #3** 2008-10-22 13:24**MOT test number** 800486098290**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Knock and play in steering rack**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Interior mirror missing**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #2** 2007-10-26 15:31**MOT test number** 630109497290**Result** ✓ Passed**Advice** Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #1** 2006-10-23 14:46**MOT test number** 403226796203**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>RF53RYV</b>
Plate since	2019-03-28
Current registration	<b>RF53RYV</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >





Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-10-27
Last registration	2022-09-06
Complete history	<a href="#">See info</a>



Registration #1	2003-10-27	15 mi
Registration #2	2006-10-23	10.384 mi
Registration #3	2007-10-26	12.137 mi
Registration #4	2008-10-22	13.348 mi
Registration #5	2008-10-22	13.353 mi
Registration #6	2009-10-19	17.838 mi
Registration #7	2009-10-19	14.838 mi
Registration #8	2010-11-02	16.500 mi
Registration #9	2011-10-25	17.664 mi
Registration #10	2012-10-30	18.806 mi
Registration #11	2013-10-21	19.651 mi
Registration #12	2013-10-21	19.653 mi
Registration #13	2014-10-22	20.860 mi
Registration #14	2015-10-26	22.189 mi
Registration #15	2015-10-26	22.189 mi
Registration #16	2016-10-27	23.377 mi
Registration #17	2016-10-27	23.377 mi
Registration #18	2016-10-27	23.377 mi
Registration #19	2016-10-27	23.377 mi
Registration #20	2016-10-27	23.377 mi
Registration #21	2016-10-27	23.377 mi
Registration #22	2016-10-27	23.377 mi
Registration #23	2016-10-27	23.377 mi
Registration #24	2016-10-27	23.377 mi
Registration #25	2016-10-27	23.377 mi
Registration #26	2016-10-27	23.377 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	887 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	3J22326