



G824LRH

report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER 4C SW DT
Colour	Green
Year of manufacture	1989
Gearbox	-MANUAL

Engine & fuel consumption

Engine capacity	2.495 cc
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-07
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-02
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	53
Total items failed	43

**MOT #17**

2021-09-21 15:48

MOT test number

581370010847

Result**✗ Failed****MAJOR** Nearside Drag link end ball joint has excessive play (2.1.3 (b) (i))**Minor** Nearside Indicator tell-tale inoperative (4.9.1 (a) (i))**MAJOR** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Front Seat belt damaged (7.1.2 (b) (i))**Minor** Nearside Front Position lamp insecure (4.2.1 (c) (i))**MAJOR** Central Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**DANGEROUS** Offside Front Seat belt likely to become detached in the event of a collision (7.1.1 (a) (ii))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**MAJOR** Nearside Rear Body mounting fixings insecure (6.2.2 (c) (i))**MAJOR** Horn not working (7.7 (a))**MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))**MAJOR** Offside Rear Body mounting fixings insecure (6.2.2 (c) (i))**MAJOR** Exhaust system insecure (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Drag link end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Offside Indicator tell-tale inoperative (4.9.1 (a) (i))**MAJOR** Offside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))**DANGEROUS** Nearside Front Seat belt likely to become detached in the event of a collision (7.1.1 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

MAJOR Nearside Front Body mounting fixings insecure (6.2.2 (c) (i))

MAJOR Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MAJOR Front Registration plate missing (0.1 (a))

MAJOR Offside Front Body mounting fixings insecure (6.2.2 (c) (i))

MAJOR Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

MAJOR Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength radius arm bracket (5.3.6 (a) (i))



MOT #16	2020-03-07 10:41
MOT test number	433470720435
Result	✓ Passed

MOT #15	2018-06-13 09:47
MOT test number	187422572543
Result	✓ Passed

- Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Power steering component has slight seepage from a component Steering box (2.1.5 (a))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Parking brake lever has little reserve travel
- Advice** Rear Exhaust mounting defective Missing (6.1.2 (a))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer chassis rail next to arm mounting area (5.3.6 (a) (i))
- Advice** Suspected use of body filler on chassis at rear of vehicle



MOT #14

2018-06-13 09:47

MOT test number

592804359867

Result

✖ Failed

Pass with rectification

Horn not working (7.7 (a) (ii))

Advice

Power steering component has slight seepage from a component Steering box (2.1.5 (a))

Advice

Parking brake lever has little reserve travel

Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice

Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice

Steering box has slight free play detected at steering wheel (2.3 (a) (i))

Advice

Rear Exhaust mounting defective Missing (6.1.2 (a))

Advice

Suspected use of body filler on chassis at rear of vehicle

Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer chassis rail next to arm mounting area (5.3.6 (a) (i))

Advice

Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #13**

2017-10-09 09:22

MOT test number

115657687763

Result**✗ Failed**

- Fail** Offside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Power steering component(s) leaking from a failed seal box (2.3.3b)
- Fail** Offside Front Seat belt has a cut which has significantly weakened the webbing (5.2.2a)
- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded chassis (2.4.A.3)
- Fail** Nearside Front Suspension spring mounting prescribed area is excessively corroded chassis by gear box (2.4.A.3)
- Advice** Coolant leak
- Fail** Battery insecure (1.9.1)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded inner sill (5.2.6)
- Fail** Offside Brake master cylinder/servo mounting prescribed area is excessively corroded (3.6.C.3)
- Fail** Nearside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Offside Front Suspension spring mounting prescribed area is excessively corroded chassis x2 (2.4.A.3)
- Fail** Central Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Nearside Front Suspension spring mounting prescribed area is excessively corroded chassis x2 (2.4.A.3)
- Advice** Nearside Front Seat belt cut but webbing not significantly weakened (5.2.2a)
- Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded chassis (2.4.A.3)
- Fail** Nearside Front Suspension spring mounting prescribed area is excessively corroded floor (2.4.A.3)
- Advice** Oil leak
- Fail** Parking brake operation grabbing severely (3.7.C.3b)
- Fail** Nearside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Offside Front Brake master cylinder/servo mounting prescribed area is excessively corroded floor (3.6.C.3)

**MOT #12** 2016-10-04 16:20**MOT test number** 542128697819**Result** ✓ Passed**MOT #11** 2015-09-30 14:39**MOT test number** 207261321815**Result** ✓ Passed**MOT #10** 2015-09-16 11:08**MOT test number** 179686967218**Result** ✗ Failed**Fail** Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Power steering malfunctioning (2.3.3a)**Fail** Offside Headlamp not working on main beam (1.7.5a)**Fail** Offside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**MOT #9** 2014-07-30 13:25**MOT test number** 725951614260**Result** ✓ Passed**Notice** Chassis at rear corroded**MOT #8** 2013-06-26 17:10**MOT test number** 746627773199**Result** ✓ Passed

**MOT #7** 2013-06-05 11:35**MOT test number** 296576953440**Result** ✗ Failed

- Fail** Upper Steering column universal joint is excessively deteriorated (2.1.5)
- Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Offside Side repeater not working (1.4.A.2c)
- Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)

MOT #6 2012-03-22 14:08**MOT test number** 105252882490**Result** ✓ Passed**MOT #5** 2012-03-20 14:52**MOT test number** 686900282005**Result** ✗ Failed

- Fail** Horn not working (1.6.2a)
- Fail** Fuel pipe leaking (7.2.3)
- Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Nearside Rear Direction indicator not working (1.4.A.2c)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Centre Drive shaft uj which forms part of the suspension has excessive play in a universal joint (2.4.G.4b)
- Fail** Nearside Front Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Rear fog lamp not working (1.3.2b)

**MOT #4** 2011-03-16 13:57**MOT test number** 266945371085**Result** ✓ Passed**MOT #3** 2011-03-03 16:40**MOT test number** 479262261063**Result** ✗ Failed**Fail** Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)**Fail** Horn not working (1.6.2a)**Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Driver's door does not latch securely closed (6.2.B.1a)**Fail** Exhaust system not adequately supported (7.1.1)**MOT #2** 2007-11-13 16:14**MOT test number** 470127617302**Result** ✓ Passed**MOT #1** 2005-11-08 14:29**MOT test number** 884902315309**Result** ✓ Passed**Notice** Coolant leaking



Tax & MOT check

✕
Untaxed

Tax expired:
1 June 2021

✕
MOT

Expired:
2 November 2023

Tax status	Expired at 1 June 2021
Days left	1062 days too late
MOT expiry date	2 November 2023
Full MOT history	See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	1989-11-15
Last registration	2021-09-21
Complete history	See info



Registration #1	1989-11-15	24 mi
Registration #2	2005-11-08	112.922 mi
Registration #3	2007-11-13	126.474 mi
Registration #4	2011-03-03	133.803 mi
Registration #5	2011-03-16	133.808 mi
Registration #6	2012-03-20	136.911 mi
Registration #7	2012-03-22	136.916 mi
Registration #8	2013-06-05	139.191 mi
Registration #9	2013-06-26	139.207 mi
Registration #10	2014-07-30	140.308 mi
Registration #11	2015-08-01	141.410 mi
Registration #12	2016-08-02	142.512 mi
Registration #13	2017-08-03	143.614 mi
Registration #14	2018-08-04	144.716 mi
Registration #15	2019-08-05	145.818 mi
Registration #16	2020-08-06	146.920 mi
Registration #17	2021-08-07	148.022 mi
Registration #18	2022-08-08	149.124 mi
Registration #19	2023-08-09	150.226 mi

More info >



Additional information

Engine number	19J24470C
---------------	-----------