





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|----------------|
| Model | V50 D2 SE |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 121 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 6.6 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



MOT history

| MOT expiry date | 2021-09-29 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 15 |
| Total items failed | 3 |

| MOT #11 | | 2020-09-30 09:27 |
|-------------|---|-----------------------|
| MOT test | number | 902068895414 |
| Result | | ✓ Passed |
| Next expi | ry date | 2021-09-29 |
| Advice | Chips on windscreen | |
| Advice (i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessiv | e movement (5.3.4 (a) |

| MOT #10 | 2020-09-30 09:2 | 7 |
|------------------------------|---|---|
| MOT test number | 46593853917 | ō |
| Result | ★ Faile | t |
| Advice Offside Front Su (i)) | pension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) | |
| Advice Chips on windsc | een | |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |

| MOT #9 | | 2019-08-31 10:00 |
|----------|--|---------------------|
| MOT test | number | 770296113884 |
| Result | | ✓ Passed |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive | movement (5.3.4 (a) |
| Advice | Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) | |

CarCheck.co.uk page 2/11



MOT #8 2018-09-11 13:28

MOT test number 487036169905

Advice O/s/r tyre wearing on inner edge

MOT #7 2018-09-11 09:03

MOT test number 507080685577

Result X Failed

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice O/s/r tyre wearing on inner edge

MOT #6 2017-08-31 09:19

MOT test number 980357574198

Result
✓ Passed

Advice Both front tyre starting to wear inner edges

MOT #5 2016-09-07 09:13

MOT test number 517186233112

Result
✓ Passed

MOT #4 2016-09-07 09:13

MOT test number 528402470879

Result X Failed

Pass with rectification Offside Headlamp has a product on the light source so that the light output is severely reduced (1.7.5a)

MOT #3 2015-09-22 15:40

MOT test number 697039819572

Result

Passed

CarCheck.co.uk page 3/11



GF60JNU

report date: 2024-03-29

MOT #2 2015-01-15 12:34 **MOT test number** 908115915007 Result ✓ Passed MOT #1 2013-11-27 10:49 **MOT** test number 498661833345 Result ✓ Passed **Notice** Items removed from driver's view prior to test Notice Wipers worn Notice Chips in windscreen Notice Engine covers fitted obscuring some components in the engine bay Notice Vehicle's internal headlight adjuster altered to recheck lights Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 4/11



X

MOT

Tax & MOT check

Tax expired: 25 January 2021



Expired: 29 September 2021

Expired at 25 January 2021 **Tax status**

Days left 1190 days too late

MOT expiry date 29 September 2021

Full MOT history See MOT history

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



GF60JNU

report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|--|---|
| | |
| ********* | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | NIC |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2010-12-21 |
| Last registration | 2020-09-30 |
| Complete history | See info |



| 2010-12-21 | 15 mi |
|------------|--|
| 2013-11-27 | 42.185 mi |
| 2015-01-15 | 51.743 mi |
| 2015-09-22 | 57.043 mi |
| 2016-09-07 | 73.573 mi |
| 2016-09-07 | 73.573 mi |
| | 11.777 es |
| | 11.777 es |
| | 11.777 mi |
| | 11.777 es |
| | 11.177 ms |
| | |
| | 2013-11-27 2015-01-15 2015-09-22 2016-09-07 |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1457 mm |
| Length | 4522 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1420 kg |
| Max. allowed weight | 1900 kg |

Additional information

| Fuel tank capacity | 52 I | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 pa | nge 11/11 |

Number of axles2Engine number1413601