



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO TD EXCLUSIVE
Colour	White
Year of manufacture	1998
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	196 Nm at 2.250 rpm
Engine capacity	1.905 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



## MOT history

MOT expiry date	2017-08-03
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	32
Total items failed	37

MOT #20	2016-08-04 10:01
MOT test number	175528230067
Result	✓ Passed
Next expiry date	2017-08-03

MOT #19	2016-08-04 10:01
MOT test number	175408379127
Result	✗ Failed
Pass with rectification	Nearside Rear Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Braking system leaking brake pipe above axle (3.6.A.1)

MOT #18	2015-08-04 16:16
MOT test number	686046415213
Result	✓ Passed
Advice	Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Advice	Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #17** 2015-07-31 13:52**MOT test number** 825912815274**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Vehicle structure has excessive corrosion which adversely affects braking or steering (6.1.A.1)**Fail** Offside Rear Stop lamp emits other than a steady red light (1.2.1e)**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #16** 2014-07-31 14:47**MOT test number** 477972514295**Result** ✓ Passed**MOT #15** 2014-07-18 15:38**MOT test number** 787679694128**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Horn not working (1.6.2a)



<b>MOT #14</b>	2013-04-23 16:08
<b>MOT test number</b>	207603513447
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

<b>MOT #13</b>	2013-04-19 14:36
<b>MOT test number</b>	279709803153
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Fail</b>	Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)
<b>Fail</b>	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
<b>Fail</b>	Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

<b>MOT #12</b>	2012-05-01 13:43
<b>MOT test number</b>	135462322134
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

<b>MOT #11</b>	2012-04-27 15:17
<b>MOT test number</b>	496418612175
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
<b>Advice</b>	Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
<b>Fail</b>	Offside Front wheel bearing rough when rotated (2.5.A.2)



MOT #10

2011-04-05 16:42

MOT test number

105015891075

Result

✓ Passed

- Notice

Rear bumper mountings corroded
- Advice

Offside Front Valve stem slightly damaged (4.1.D.1e)
- Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)
- Notice

Rear suspension low
- Notice

Nearside rear tyre is a car tyre, should be at least reinforced
- Advice

Offside Rear Valve stem slightly damaged (4.1.D.1e)

**MOT #9**

2011-03-29 15:42

**MOT test number**

347588781030

**Result****✗ Failed**

- Advice** Offside Front Valve stem slightly damaged (4.1.D.1e)
- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Exhaust system not adequately supported (7.1.1)
- Fail** Rear Brake load sensing valve linkage seized (3.6.E.3)
- Notice** Rear bumper mountings corroded
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Nearside rear tyre is a car tyre, should be at least reinforced
- Advice** Offside Rear Valve stem slightly damaged (4.1.D.1e)
- Fail** Nearside Front Lower Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)
- Notice** Rear suspension low

**MOT #8**

2010-04-13 15:14

**MOT test number**

650473200100

**Result****✓ Passed****MOT #7**

2010-04-06 15:41

**MOT test number**

114616190067

**Result****✗ Failed**

- Fail** Offside Front coil spring incomplete (2.4.C.1a)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)

**MOT #6** 2009-04-21 16:34**MOT test number** 604611419170**Result** ✓ Passed**Notice** Rear suspension low**Notice** N/s/f bottom ball joint gaiter split**MOT #5** 2009-04-15 16:21**MOT test number** 581575909139**Result** ✗ Failed**Fail** Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Rear suspension low**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Brake hose leaking (3.6.A.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f bottom ball joint gaiter split**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Front Brake hose excessively deteriorated (3.6.B.4d)**MOT #4** 2008-04-25 16:48**MOT test number** 542516218176**Result** ✓ Passed**Notice** Non factory fitted coil spring assisters removed at time of retest

**MOT #3** 2008-04-22 16:18**MOT test number** 462793118173**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Registration plate lamp not working (1.1.5c)**Fail** Centre Power steering ram(s) leaking from a failed component (2.3.3b)**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**Fail** Nearside Registration plate lamp not working (1.1.5c)**Fail** Nearside Outer Front constant velocity joint gaiter split (2.5.C.1a)**MOT #2** 2007-04-25 14:47**MOT test number** 900935817116**Result** ✓ Passed**MOT #1** 2006-04-27 15:03**MOT test number** 274037716430**Result** ✓ Passed





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>R730LVC</b>
Plate since	2019-09-28
Current registration	<b>R730LVC</b>
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1998-05-22
Last registration	2016-08-04
Complete history	<a href="#">See info</a>



Registration #1	1998-05-22	14 mi
Registration #2	2006-04-27	45.077 mi
Registration #3	2007-04-25	49.248 mi
Registration #4	2008-04-22	54.180 mi
Registration #5	2008-04-25	54.246 mi
Registration #6	2009-04-15	59.940 mi
Registration #7	2009-04-21	60.035 mi
Registration #8	2010-04-06	66.115 mi
Registration #9	2010-04-13	66.242 mi
Registration #10	2011-03-29	72.458 mi
Registration #11	2011-04-05	72.594 mi
Registration #12	2012-04-05	72.594 mi
Registration #13	2012-04-05	72.594 mi
Registration #14	2012-04-05	72.594 mi
Registration #15	2012-04-05	72.594 mi
Registration #16	2012-04-05	72.594 mi
Registration #17	2012-04-05	72.594 mi
Registration #18	2012-04-05	72.594 mi
Registration #19	2012-04-05	72.594 mi
Registration #20	2012-04-05	72.594 mi
Registration #21	2012-04-05	72.594 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Additional information

Fuel tank capacity	54 l
Fuel delivery	Indirect Injection
Number of doors	5
Engine number	CUJW3004258