



HONDA




report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD TYPE-V
Colour	Blue
Year of manufacture	2002
Top speed	128 mph
0 - 60 mph	10.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 4.700 rpm
Engine capacity	2.254 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.7 mpg
Consumption combined	30.1 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-10-25
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2021-11-09
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	41
Total items failed	17

MOT #23	2020-11-10 12:25
MOT test number	824389155263
Result	✓ Passed
Next expiry date	2021-11-09
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #22	2020-11-06 13:26
MOT test number	884552415336
Result	✗ Failed
Fail	Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sills Both Side (5.3.6 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Wheel Arch Both Side (5.3.6 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #21**

2019-05-10 12:23

MOT test number

375381454826

Result

✓ Passed

Advice Suspension component mounting prescribed area is corroded but not considered excessive Front & Rear (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Front Headlamp lens slightly defective Both Side (4.1.1 (b) (i))

Advice Nearside Rear Wheel Arch Slightly Corroded

MOT #20

2018-05-07 12:52

MOT test number

539470863650

Result

✓ Passed

Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #19

2017-03-13 17:40

MOT test number

827792758113

Result

✓ Passed

MOT #18

2017-03-13 17:40

MOT test number

323568769179

Result

✗ Failed

Pass with rectification Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)

Pass with rectification Nearside Rear Suspension component mounting prescribed area is excessively corroded Sil (2.4.A.3)

Pass with rectification Front Suspension component mounting prescribed area is excessively corroded Both Side (2.4.A.3)

**MOT #17**

2017-02-25 12:18

MOT test number

505805601367

Result**✗ Failed**

- Fail** Offside Front Suspension component mounting prescribed area is excessively corroded Sil (2.4.A.3)
- Fail** Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded Sil (2.4.A.3)
- Fail** Rear Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #16

2016-02-13 08:36

MOT test number

637370254625

Result**✓ Passed**

- Advice** Nearside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive rear subframe mounting (2.4.A.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #15

2016-02-06 08:29

MOT test number

889233205312

Result**✗ Failed**

- Advice** Nearside Front Subframe mounting prescribed area is corroded but not considered excessive rear subframe mounting (2.4.A.3)
- Advice** Nearside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Inner Subframe mounting prescribed area is excessively corroded wheelarch, within 12 inches of subframe mounting (2.4.A.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #14**

2015-02-23 11:25

MOT test number

955844655010

Result

✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Both rear tyre side wall's cracking
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #13

2015-02-20 12:25

MOT test number

398541955010

Result

✗ Failed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Notice** Both rear tyre side wall's cracking

**MOT #12** 2014-04-12 11:09**MOT test number** 659772804147**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #11** 2014-04-12 11:09**MOT test number** 826802004152**Result** ✗ Failed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #10** 2013-04-04 11:40**MOT test number** 155004193066**Result** ✓ Passed**MOT #9** 2012-08-21 12:27**MOT test number** 659144632222**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2011-08-24 16:23**MOT test number** 375506831402**Result** ✓ Passed

**MOT #7** 2011-08-24 09:18**MOT test number** 836056231271**Result** ✗ Failed**Fail** Front Brake lining(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2010-08-17 08:49**MOT test number** 584599620264**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2009-08-20 09:12**MOT test number** 664332139250**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2008-08-01 10:25**MOT test number** 284704618244**Result** ✓ Passed**MOT #3** 2007-08-25 08:57**MOT test number** 554977437274**Result** ✓ Passed



MOT #2	2006-09-01 11:03
MOT test number	354274646481
Result	✓ Passed
Notice	O/s rear tyre has multiple splits on inner tread
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2005-05-27 13:24
MOT test number	223077045435
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
24 September 2021

✕
MOT

Expired:
9 November 2021

Tax status	Expired at 24 September
Days left	949 days too late
MOT expiry date	9 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-05-16
Last registration	2020-11-10
Complete history	See info



Registration #1	2002-05-16	26 mi
Registration #2	2005-05-27	48.819 mi
Registration #3	2006-09-01	55.523 mi
Registration #4	2007-08-25	58.922 mi
Registration #5	2008-08-01	66.620 mi
Registration #6	2009-08-20	72.041 mi
Registration #7	2010-08-17	76.981 mi
Registration #8	2011-08-24	82.315 mi
Registration #9	2011-08-24	82.315 mi
Registration #10	2012-08-21	85.176 mi
Registration #11	2013-04-04	86.541 mi
Registration #12	2014-04-12	90.901 mi
Registration #13	2015-05-20	95.277 mi
Registration #14	2016-05-20	95.277 mi
Registration #15	2017-05-20	95.277 mi
Registration #16	2018-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2020-05-20	95.277 mi
Registration #19	2021-05-20	95.277 mi
Registration #20	2022-05-20	95.277 mi
Registration #21	2023-05-20	95.277 mi
Registration #22	2024-05-20	95.277 mi
Registration #23	2025-05-20	95.277 mi
Registration #24	2026-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1580 mm
Length	4595 mm

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	F23Z5E401812