





General information

Make	MAZDA
Model	5 TS2
Colour	Silver
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg





Internet history

Entry 1

Date Pictures 2022-01-27

22

Listing price

View report









source: cargurus.co.uk



MOT history

МОТ #16	2021-10-06 14:25
MOT test number	674145554041
Result	✓ Passed
Next expiry date	2022-10-05
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15		2020-09-25 12:22
MOT test	number	513306102182
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #14	2020-09-04 09:07
MOT test number	908821126939
Result	🗙 Failed
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive mov (5.3.4 (a) (i))	ement D bush
Advice Rear inner brake pads appear to be worn advise brake check	
Fail Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))	
Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	





MOT #13	2019-09-03 08:34
MOT test number	231391439090
Result	✓ Passed
Advice Front Suspension arm pin or bush worn but not resulting in exercise (5.3.4 (a) (i))	cessive movement both rear bushes
Advice Oil leak	
Advice Front Shock absorbers light misting of oil or has limited damping	ng effect both (5.3.2 (b))
Advice Rear inner sills corroded	
Advice Rear exhaust bracket broken	

MOT #12	2018-08-18 10:56
MOT test number	422168128554
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.	1 (b))
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely	deteriorated (6.1.7 (g) (i))

MOT #11	2017-09-07 13:12
MOT test number	696790333037
Result	✓ Passed
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)	
Advice Rear Sub-frame corroded but not seriously weakened all rear suspension components slightly corroded (2.4.G.1)	





MOT #10		2017-09-07 13:12
MOT test number		116279163646
Result		🗙 Failed
Advice Rear Sub-frame co corroded (2.4.G.1)	prroded but not seriously weakened all rear	suspension components slightly
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)		
Advice Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)		
Pass with rectification	Windscreen washer provides insufficient wa	asher liquid (8.2.3)

МОТ #9	2016-05-31 15:21
MOT test number	496942211686
Result	✓ Passed

MOT #8		2015-05-26 09:48
MOT test	number	576886945105
Result		✓ Passed
Advice	Offside Rear Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice	Cut in osr tyre	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Front tyres wearing on inner edges	



NY07GOA report date: 2024-03-28

MOT #7	2015-05-26 09:48
MOT test number	406296445129
Result	× Failed
Pass with rectification Offside From	t Headlamp aim too high (1.8)
Advice Offside Rear Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice Front tyres wearing on inner edges	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Notice Cut in osr tyre	
Notice Vehicle's internal headlight adjuster altered to recheck lights	

МОТ #6	2014-05-28 10:46
MOT test number	446458744141
Result	✓ Passed
Notice Engine covers fitted obscuring some components in the engine bay	

МОТ #5	2014-05-28 08:48	
MOT test number	816958744129	
Result	🗙 Failed	
Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excest (2.4.G.2)	ssive movement	
Notice Engine covers fitted obscuring some components in the engine bay		
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)		
Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)		





MOT #4		2013-04-23 13:40
MOT test	number	448263413104
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice	Front wiperblades split	
Notice	Under-trays fitted obscuring some underside components	

MOT #3		2012-03-12 13:49
MOT test	number	876032872058
Result		✓ Passed
Notice	Rear brake discs slightly worn	
Advice	Inner Rear Brake pad(s) wearing thin (3.5.1g)	

2011-03-25 10:22
689284481042
✓ Passed

MOT #1	2010-04-06 11:49
MOT test number	150106190481
Result	✓ Passed





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-08-01
Last registration	2021-10-06
Complete history	See info



Registration #1	2007-08-01	10 mi
Registration #2	2010-04-06	23.862 mi
Registration #3	2011-03-25	30.455 mi
Registration #4	2012-03-12	37.210 mi
Registration #5	2013-04-23	45.729 mi
Registration #6	2014-05-28	53.453 mi
Registration #7	2014-05-28	53.453 mi
Registration #8	2015-05-26	61.265 mi
Registration #9	2016-05-31	67.551 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi

More info \rightarrow



NY07GOA report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg
Additional information	
Additional information Fuel tank capacity	60 I
	60 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5