





General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1		
Date	2021-07-17	
Pictures	13	
Listing price	View report	



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-22	
MOT pass rate	69 %	
MOT passed	9	
Failed MOT tests	4	
Total advice items	26	
Total items failed	4	

MOT #13		2023-05-23 12:01
MOT test	number	596699429155
Result		✓ Passed
Next expi	ry date	2024-05-22
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	11 (c))
Advice	Advice Under covers fitted	
Advice	Offside Rear tyre wearing inner edge slightly	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1	1.11 (c))
Advice	Nearside Front tyre wearing inner edge slightly	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))		

MOT #12		2022-07-19 16:24
MOT test	number	651777071632
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 ((c))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated ((5.3.4 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.1.	1 (c))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	





MOT #11	2022-0	07-09 11:58
MOT test	number 280	713500882
Result		🗙 Failed
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Offside Front Lower Suspension arm insecurely attached split pin missing (5.3.3 (a) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b)	(i))

MOT #10		2021-07-28 14:54
MOT test	number	183527230410
Result		Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited dam	pping effect (5.3.2 (b))

MOT #9	2020-09-17 09:38	
MOT test	number 881881355010	
Result	✓ Passed	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	





MOT #8		2019-04-27 10:30
MOT test	number	551262291946
Result		✓ Passed
Minor (g) (i))	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorate	d Pin holed (6.1.7
Minor clip (6.1.7	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorat 7 (g) (i))	ted Leaking past
MOT #7		2019-04-27 10:30

MOT test number	237250404047
Result	× Failed
Minor Offside Front Out	er Drive shaft joint constant velocity boot severely deteriorated Pin holed (6.1.7
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor Nearside Front Of clip (6.1.7 (g) (i))	ater Drive shaft joint constant velocity boot severely deteriorated Leaking past

MOT #6	2018-05-02 06:59
MOT test number	434266750955
Result	✓ Passed

MOT #5	2017-05-11 13:34
MOT test number	922149058019
Result	✓ Passed

MOT #4	2017-05-11 07:34
MOT test number	800699400103
Result	🗙 Failed
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #3	2016-05-09 07:41
MOT test number	955341800625
Result	✓ Passed





MOT #2	2015-05-12 16:35
MOT test number	348522135186
Result	✓ Passed
MOT #1	2015-05-12 08:52
MOT test number	358672135194
Result	× Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due:	✓ MOT Expires: 22 May 2024
1 July 2024 Tax status	22 May 2024 Valid until 1 July
Days left	62
MOT expiry date	22 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

And a second sec	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



EN12BPV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-01
Last registration	2023-05-23
Complete history	See info



Registration #1	2012-07-01	6 mi
Registration #2	2015-05-12	35.478 mi
Registration #3	2015-05-12	35.478 mi
Registration #4	2016-05-09	46.424 mi
Registration #5	2017-05-11	63.463 mi
Registration #6	2017-05-11	63.463 mi
Registration #7	2018-05-02	82.487 mi
Registration #8	2019-04-27	89.854 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 esi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13