





report date: 2024-03-29

General information

Make	FIAT
Model	DUCATO 10 MWB 1.9TD P/V
Colour	White
Year of manufacture	2002
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	1.905 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/16



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-17

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-07-14
MOT pass rate	78 %
MOT passed	21
Failed MOT tests	6
Total advice items	48
Total items failed	17

MOT #27		2023-07-06 11:52
MOT test	number	379556235452
Result		✓ Passed
Next expi	ry date	2024-07-14
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside wiper blade slightly smearing screen	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #26	2022-07-15 12:19
MOT test number	788638470252
Result	✓ Passed

MOT #25		2021-06-17 13:38
MOT test	number	569016986095
Result		✓ Passed
Advice	Nearside Brake pipe corroded, covered in grease or other material front to	rear pipe (1.1.11 (c))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping eff	fect (5.3.2 (b))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping ef	fect (5.3.2 (b))

CarCheck.co.uk page 3/16



GX020PZ report date: 2024-03-29

MOT #24 2021-06-15 09:25

MOT test number 537149347197

Result

× Failed

Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength front sub-frame mounting (5.3.6 (a) (i))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear pipe (1.1.11 (c))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #23 2021-05-18 13:36

MOT test number 875075964955

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT #22 2021-05-17 08:17

MOT test number 678150364356

Result X Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength in wheel arch (5.3.6 (a) (i))

Fail Fuel system component leaking fuel tank (6.1.3 (b) (i))

Advice Nearside Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Brake load sensing valve seized but ABS functioning (1.1.17 (c) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #21 2020-06-04 11:50

MOT test number 782903032132

Result

Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #20 2019-06-13 12:38

MOT test number 364139207061

Result

Passed

MOT #19 2018-11-01 16:42

MOT test number 340148966412

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #18 2018-10-31 09:24

MOT test number 116493686754

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice N/S brake sensor wire not connected

Advice Front All direction indicators slightly discoloured (4.4.3 (a))

Fail Nearside Front Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Wheel arch (6.1.1 (c) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Fail Rear All direction indicators incorrect colour (4.4.3 (a))

Fail Offside Front Outer All direction indicators not working (4.4.1 (a) (ii))

Fail Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Chassis leg (6.1.1 (c) (i))

MOT #17 2018-07-26 09:18

MOT test number 255721270300

MOT #16 2017-07-27 10:23

MOT test number 992993839045

Advice Corrosion; Areas at n/s/f chassis / inner wing & both front inner wheel arches

Advice Wheel trims , other areas covered , restricting views

Advice Brakes; Pipes corroded, Front to rear at n/s chassis & Rear brake load sensing valve to hose

Advice Brakes; Imbalance, Front Brakes, Rear Brakes & Parking Brakes, see printout

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT #15		2016-08-02 10:12
MOT test	number	327345025382
Result		✓ Passed
Advice	Wheel trims , various covers & mouldings fitted , restricting views	
Advice	Brakes ; imbalance on front brakes 12 %	
Advice	Steering ; P.A.S. Pipe corroded	
Advice	Lighting ; headlamp beam deflectors fitted , incorrect position	
Advice	Brakes ; imbalance on rear brakes & parking brakes	
Advice	Exhaust ; rubber mounting rings perished	

MOT #14		2015-07-21 12:29
MOT test	number	228942605206
Result		✓ Passed
Notice	N/s/f disc slightly corroded	
Notice	Rear brake pipes slightly corroded	
Notice	P.a.s pipes corroded	
Notice	Exhaust rubbers perished	

MOT #13		2014-08-01 10:32
MOT test	number	846203014231
Result		✓ Passed
Advice	Power steering pipe(s) or hose(s) slightly corroded (2.3.2)	
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT #12 2014-08-01 10:32 798963014296 **MOT** test number Result × Failed **Advice** Offside Front wheel bearing has slight play (2.5.A.3c) Pass with rectification Horn not working (1.6.2a) **Advice** Nearside Front wheel bearing has slight play (2.5.A.3c) Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)

 MOT #11
 2013-07-17 12:22

 MOT test number
 145988593169

 Result
 ✓ Passed

 MOT #10
 2012-08-14 11:57

 MOT test number
 299577722262

 Result
 ✓ Passed

Notice Exhaust system rusty

MOT #9 2012-08-14 11:57
MOT test number 117467722269

Result X Failed

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Exhaust system rusty

Pass with rectification Offside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #8 2012-04-13 09:30
MOT test number 707074402195
Result ✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-29

MOT #7	2011-03-28 09:04
MOT test number	177547181438
Result	✓ Passed
MOT #6	2010-03-12 15:04
MOT test number	561891070012
Result	✓ Passed
MOT #5	2009-03-30 16:39
MOT test number	803459789058
Result	✓ Passed
Notice See previous vt32	

MOT #4	2009-03-30 15:00
MOT test number	754949789033
Result	X Failed
Advice Rear Brake pipe slightly corroded (3.6.B.2c)	
Fail Horn not working (1.6.2a)	
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #3	2008-03-25 12:22
MOT test number	140065488057
Result	√ Passed
MOT #2	2007-03-12 14:40
MOT test number	652901477025
Result	√ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-29

MOT #1 2006-03-20 17:46

MOT test number 352999176014

Result ✓ Passed

CarCheck.co.uk page 10/16



report date: 2024-03-29

Tax & MOT check



Days left 93

MOT expiry date 14 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 11/16



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/16



GX020PZ report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2002-03-16
Last registration	2023-07-06
Complete history	See info



Registration #1	2002-03-16	9 mi
Registration #2	2006-03-20	7.088 mi
Registration #3	2007-03-12	8.950 mi
Registration #4	2008-03-25	11.257 mi
Registration #5	2009-03-30	12.671 mi
Registration #6	2009-03-30	12.671 mi
Registration #7	2010-03-12	13.851 mi
Registration #8	2011-03-28	14.707 mi
Registration #9	2012-04-13	17.576 mi
Registration #10	2012-08-14	19.008 mi
Registration #11	2013-07-17	21.844 mi
Registration #12	2014-08-01	27.724 mi
Registration #13	2015-07-21	31.678 mi
Registration #14	2016-08-02	32.670 mi
Registration #15		11.177 mi
Registration #16		71.777 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.177 mi
Registration #20		71.777 es
Registration #21		71.777 es
Registration #22		71.777 es
Registration #23		71.777 es
Registration #24		11.117 es
Registration #25		11.177 es
Registration #26		11.777 es
CarCheck.co.uk		page 15/16

More info >



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1998 mm
Kerb weight	1735 kg
Max. allowed weight	2800 kg

Additional information

Number of axles	2
Engine number	3037040

CarCheck.co.uk page 16/16