





report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2022-02-08

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-11-21
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	27
Total items failed	18

MOT #22	2023-11-07 12:53
MOT test number	535242460379
Result	✓ Passed
Next expiry date	2024-11-21

MOT #2	21	2023-10-24 09:32
MOT te	st number	708857049709
Result		X Failed
Fail	Exhaust has a major leak of exhaust gases front and rear joints (6.1.2 (a))	
Fail	Emissions unable to be completed exhaust leak (8.2.1.2 (d))	
Fail signific	Offside Outer Integral body structure corroded to the extent that the rigidity of antly reduced sill $(6.1.1\ (c)\ (i))$	the assembly is

MOT #20	2022-11-22 16:01
MOT test number	102422903775
Result	✓ Passed

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #19 2022-11-08 10:38

MOT test number 909538032407

Result X Failed

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Offside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Nearside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

MOT #18 2021-10-22 16:01

MOT test number 966608191433

Advice Power steering pipe/hose has slight seepage to rack (2.1.5 (a))

MOT #17 2021-10-22 08:39

MOT test number 558625297964

Result X Failed

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Nail in tyre

Advice Power steering pipe/hose has slight seepage to rack (2.1.5 (a))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT test number

Result

Advice Rear Exhaust mounting defective (6.1.2 (a))

Minor Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15		2019-04-27 07:59
MOT test	number	582444255692
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2018-04-14 08:23
MOT test number		832725169704
Result		✓ Passed
MOT #13		2018-04-14 08:23
MOT test number		278704048026
Result		× Failed
Pass with rectification Reg	gistration plate lamp not working (1.1.C.1d)	

MOT #12	2017-04-22 13:01
MOT test number	444006213949
Result	✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #11

MOT test number

265106224639

Result

Advice Reset internal headlamp adjuster to re-check headlamp aim

Advice Offside Front Tyre has sidewall damage but not through to cords

MOT #10

MOT test number

Result

Advice Reset internal headlamp adjuster to re-check headlamp aim

Pass with rectification Spare wheel carrier insecure (6.4.2)

Advice Offside Front Tyre has sidewall damage but not through to cords

MOT #9

MOT test number

496958995086

Result

Notice Misting of oil around power steering rack

2015-04-08 14:36

496958995086

MOT test number
729518195012

Result

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Notice Misting of oil around power steering rack

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #7

MOT test number

866768294055

Result

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)


MOT #6 2013-04-10 09:14 **MOT test number** 265530203163 Result ✓ Passed MOT #5 2012-04-28 10:13 **MOT** test number 876349812129 Result Passed **Notice** Child seat fitted not allowing full inspection of adult belt Notice Both rear tyres perished Notice Rear brakes noisey

MOT #4		2011-04-07 10:53
MOT test n	umber	587207991066
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Chip in b zone of screen	

CarCheck.co.uk page 7/15



report date: 2024-03-28



MOT #2		2010-04-28 12:54
MOT test	number	454928810126
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	N/s & o/s rear tyres worn on edges & perishing	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2009-09-22 14:26
MOT test number	292605669287
Result	✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO.	

Plate changes	More info >
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-30
Last registration	2023-11-07
Complete history	See info



Registration #1	2006-09-30	13 mi
Registration #2	2009-09-22	25.510 mi
Registration #3	2010-04-28	23.473 mi
Registration #4	2011-04-06	31.174 mi
Registration #5	2011-04-07	31.174 mi
Registration #6	2012-04-28	40.602 mi
Registration #7	2013-04-10	48.956 mi
Registration #8	2014-04-08	58.247 mi
Registration #9	2015-04-08	65.021 mi
Registration #10	2015-04-08	65.021 mi
Registration #11	2016-04-12	69.489 mi
Registration #12	2016-04-12	69.489 mi
Registration #13		11.777 es
Registration #14		
Registration #14		
Registration #15		0.074
•		11.00 m
Registration #15		11.00 mil
Registration #15 Registration #16		11.777 es
Registration #15 Registration #16 Registration #17		11.777 es 11.777 es 11.777 es 11.777 es
Registration #15 Registration #16 Registration #17 Registration #18		11,777 est 11,777 est 11,777 est 11,777 est
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 est 11,777 est 11,777 est 11,777 est 11,777 est
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 est 11,777 est 11,777 est 11,777 est 11,777 est 11,777 est
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,777 esi 11,777 esi 11,777 esi 11,777 esi 11,777 esi 11,777 esi 11,777 esi

More info >



Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3001299

CarCheck.co.uk page 15/15