



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XT
Colour	Silver
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	343 Nm at 1.850 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-08-04
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-01
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2022-06-25
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	54
Total items failed	13

MOT #20 2022-06-15 13:34

MOT test number 862103855514

Result ✗ Failed

- MAJOR** Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced near side and offside rear (6.1.1 (c) (i))
- DANGEROUS** Offside Front Shock absorbers likely to become detached ex corroded (5.3.2 (a) (ii))
- DANGEROUS** Rear Axle insecure such that stability is impaired (5.1.1 (b) (ii))
- MAJOR** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- DANGEROUS** Offside Rear Suspension component attachment bracket/mounting insecure and impairing directional stability tramp bar (5.3.3 (a) (ii))
- MAJOR** Power steering pipe/hose leaking (2.1.5 (a))
- DANGEROUS** Nearside Front Shock absorbers likely to become detached ex corroded (5.3.2 (a) (ii))
- MAJOR** Offside Rear Rear reflector missing (4.8.2 (a) (ii))
- DANGEROUS** Nearside Rear Suspension component attachment bracket/mounting fractured tramp bar mount (5.3.3 (b) (ii))

MOT #19 2021-06-26 11:34

MOT test number 763706846278

Result ✓ Passed

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play Link rod (5.3.4 (a) (i))
- Advice** [Sill trims fitted]

**MOT #18**

2021-06-26 11:34

**MOT test number**

530590747998

**Result****✗ Failed****Advice** Offside Rear Anti-roll bar linkage ball joint has slight play Link rod (5.3.4 (a) (i))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect Bulb not located correctly (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect Bulb not located correctly / New bulb fitted (4.1.2 (c))**Pass with rectification** Brake pedal anti-slip provision missing (1.1.2 (c))**Advice** [Sill trims fitted]**MOT #17**

2021-06-04 11:16

**MOT test number**

812150904648

**Result****✗ Failed****MAJOR** Nearside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced body mount corroded (6.1.1 (c) (i))**MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**DANGEROUS** Offside Rear Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Front Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced body mount corroded (6.1.1 (c) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #16**

2020-10-19 14:17

**MOT test number**

347463256040

**Result****✓ Passed**

**MOT #15** 2020-10-13 14:39**MOT test number** 274517536930**Result** ✗ Failed**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #14** 2019-10-17 15:04**MOT test number** 481320155276**Result** ✓ Passed**MOT #13** 2018-11-13 17:02**MOT test number** 293961764069**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #12** 2018-11-13 17:02**MOT test number** 174952508041**Result** ✗ Failed**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #11**

2018-01-13 08:18

**MOT test number**

756768737240

**Result**

✓ Passed

- Advice** Offside Inner Body has slight corrosion sil (6.1.B.2)
- Advice** Power steering repaired, but not inappropriately both steering rack gaitors twisted (2.3.7)
- Advice** Nearside Outer Body has slight corrosion sil (6.1.B.2)
- Advice** Offside Outer Body has slight corrosion sil (6.1.B.2)
- Advice** Nearside Inner Body has slight corrosion sil (6.1.B.2)

**MOT #10**

2017-08-24 09:03

**MOT test number**

102036967572

**Result**

✗ Failed

- Fail** Nearside Front Steering rack gaiter split (2.2.D.2d)
- Advice** Both rear shock absorber mountings corroded
- Advice** Offside Rear Upper Tie bar/rod attachment bracket/mounting corroded but its strength is not seriously reduced (2.4.G.1)
- Fail** Nearside rear brake binding (3.7.B.1)
- Fail** Offside Rear Trailing arm attachment bracket/mounting corroded and its strength is seriously reduced (2.4.G.1)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Rear axle corroded
- Advice** Towball/hitch not fitted at time of test
- Fail** Nearside Rear Upper Tie bar/rod attachment bracket/mounting corroded and its strength is seriously reduced (2.4.G.1)
- Fail** Nearside Rear Trailing arm attachment bracket/mounting corroded and its strength is seriously reduced (2.4.G.1)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside and offside sills corroded

**MOT #9** 2016-09-16 08:15**MOT test number** 633766020638**Result** ✓ Passed**MOT #8** 2015-09-09 09:31**MOT test number** 540877137817**Result** ✓ Passed**MOT #7** 2014-08-29 09:50**MOT test number** 706151444222**Result** ✓ Passed

- Notice** Advise chassis slight corrosion
- Notice** Advise outter sills slight corrosion
- Notice** Advise steering pipes slightly corroded
- Notice** Advise front subframe slight corrosion
- Notice** Advise steering rack slightly damp

**MOT #6** 2014-08-29 09:50**MOT test number** 458261444244**Result** ✗ Failed

- Pass with rectification** Offside Front Headlamp aim too low (1.8)
- Notice** Advise steering rack slightly damp
- Notice** Advise chassis slight corrosion
- Notice** Advise outter sills slight corrosion
- Pass with rectification** Nearside Front Headlamp aim too high and too far to the right. (1.8)
- Notice** Advise steering pipes slightly corroded
- Notice** Advise front subframe slight corrosion

**MOT #5** 2013-08-29 10:51**MOT test number** 765901843201**Result** ✓ Passed**Notice** Advise underbody and components corroding**MOT #4** 2012-09-10 12:06**MOT test number** 159184752264**Result** ✓ Passed**Notice** Advise front underbody shield corroded**Notice** Advise chassis and under body corroding**Advice** Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #3** 2011-09-13 09:55**MOT test number** 896056051200**Result** ✓ Passed**MOT #2** 2010-09-09 10:48**MOT test number** 642042250274**Result** ✓ Passed**MOT #1** 2009-09-07 14:44**MOT test number** 632250359269**Result** ✓ Passed





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LG56UXX
Plate since	2019-03-28
Current registration	LG56UXX
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-15
Last registration	2022-06-15
Complete history	<a href="#">See info</a>



Registration #1	2006-09-15	24 mi
Registration #2	2009-09-07	20.075 mi
Registration #3	2010-09-09	22.013 mi
Registration #4	2011-09-13	24.876 mi
Registration #5	2012-09-10	27.655 mi
Registration #6	2013-08-29	30.688 mi
Registration #7	2014-08-29	31.666 mi
Registration #8	2015-09-09	42.223 mi
Registration #9	2016-09-16	52.815 mi
Registration #10	2017-08-24	62.716 mi
Registration #11	2018-01-13	63.355 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2020-05-29	75.277 mi
Registration #14	2020-05-29	75.277 mi
Registration #15	2020-05-29	75.277 mi
Registration #16	2020-05-29	75.277 mi
Registration #17	2020-05-29	75.277 mi
Registration #18	2020-05-29	75.277 mi
Registration #19	2020-05-29	75.277 mi
Registration #20	2020-05-29	75.277 mi
Registration #21	2020-05-29	75.277 mi
Registration #22	2022-06-15	75.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1804 mm
Length	4567 mm
Wheel base	2710 mm
Kerb weight	2056 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4CB5878441