





General information

Make	VOLVO
Model	V70 V70 T5 SE
Colour	Silver
Year of manufacture	2002
Top speed	149 mph
0 - 60 mph	7.1 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	247 BHP
Max. torque	329 Nm at 2.400 rpm
Engine capacity	2.319 сс
Cylinders	5
Fuel type	Petrol
Consumption city	19.6 mpg
Consumption extra urban	34.9 mpg
Consumption combined	27.2 mpg
CO2 emission	258 g/km
CO2 label	М







Internet history

Entry 1	
Date	2021-08-14
Pictures	12
Listing price	View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	77 %
MOT passed	20
Failed MOT tests	6
Total advice items	45
Total items failed	10

MOT #26	2023-09-15 12:51
MOT test number	942988906759
Result	✓ Passed
Next expiry date	2024-09-21
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

MOT #25		2022-09-22 10:12
MOT test	number	546234122928
Result		✓ Passed
Advice	Registration plate deteriorated but not likely to be misread both front and rear (0).1 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #24		2021-09-20 08:32
MOT test	number	985306471799
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

МОТ #23	2021-09-20 08:32
MOT test number	647806039995
Result	🗙 Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #22	2021-03-26 10:02
MOT test number	721116741655
Result	✓ Passed

MOT #21	2020-02-19 15:53
MOT test number	135207168517
Result	✓ Passed
Advice Rear registration slightly delaminated unlikely to be misread	

MOT #20	2019-03-18 11:49
MOT test number	577313011927
Result	✓ Passed





MOT #19	2018-07-11 14:15
MOT test number	850598549412
Result	✓ Passed
MOT #18	2018-07-11 12:00
MOT test number	742710313705
Result	× Failed
Fail Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
MOT #17	2017-06-26 08:29

MOI #17		2017-06-26 08:29
MOT test	number	854158372582
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1	la)

МОТ #16	2016-06-29 10:12
MOT test number	382544102331
Result	✓ Passed
Advice Offside Rear NAIL IN TYRE	
Advice Front BOTH TYRE WALL CUT	

MOT #15		2015-06-23 11:04
MOT test	number	225014575197
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	



OU52UTT report date: 2024-03-29

MOT #14		2014-06-11 09:55
MOT test	number	559192564183
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	N/s/front tyre wall cut	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3	8.1a)
Notice	Under-trays fitted obscuring some underside components	
Notice	O/s/front tyre wall cut	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.	.3.1d)

MOT #13	2013-06-25 13	:36
MOT test	number 2254765734	1 23
Result	✓ Pase	sed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #12		2013-06-25 13:36
MOT test number		649616373148
Result		🗙 Failed
Pass with rectification	Offside Windscreen wiper does not clear the v	windscreen effectively (8.2.2)
Notice Engine covers fit	tted obscuring some components in the engine	bay
Pass with rectification	Offside Front position lamp(s) not working (1.	1.A.3b)
Advice Windscreen has	damage to an area less than a 40mm circle ou	tside zone 'A' (8.3.1d)
Notice Under-trays fitte	d obscuring some underside components	





MOT #11	20	012-06-25 16:53
MOT test number		895667172157
Result		✓ Passed
Notice Under-trays fitte	ed obscuring some underside components	
MOT #10	20	012-06-25 16:53
MOT test number		808987972172
Result		🗙 Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Pass with rectification	Front Direction indicator incorrect colour (1.4.A.2f)	
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.	8.A.1b)
Notice Under-trays fitted obscuring some underside components		

МОТ #9	2011-06-14 15:20
MOT test number	599125661136
Result	✓ Passed

MOT #8	2010-07-02 14:57
MOT test number	461523580149
Result	✓ Passed
Advice Nearcide Front Suspension arm rubber bush deteriorated but not	resulting in excessive movement

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7	2010-07-01 09:37
MOT test number	560172280108
Result	🗙 Failed
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2)	excessive movement
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Fail Exhaust has part of the system excessively deteriorated (7.1.1a)	





2008-07-22 17:13

950894308282

Passed

MOT #6		2009-07-16 13:07
MOT test	number	882917799165
Result		✓ Passed
Notice	Fuel cap seal starting to deteriorate	
Notice	Rear registration plate starting to deteriorate	

MOT #5

MOT test number	
Result	

Advice	Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice O/s/r tyre has a cut on side which is not deep enough to reach the cord or plys	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Notice	N/s/r tyre has a cut on side which is not deep enough to reach the cord or plys

MOT #4		2008-07-22 17:13	
MOT test number 38		384934408467	
Result		× Failed	
Advice	Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Notice O/s/r tyre has a cut on side which is not deep enough to reach the cord or plys			
Pass wit	h rectification Fuel cap/sea	ling device sealing washer deteriorated (7.2.4c)	
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)		
Notice N/s/r tyre has a cut on side which is not deep enough to reach the cord or plys		ich is not deep enough to reach the cord or plys	

MOT #3	2007-07-23 15:35
MOT test number	362544107284
Result	✓ Passed





MOT #2	2006-08-07 15:15
MOT test number	651719016286
Result	✓ Passed
MOT #1	2006-04-25 16:24
MOT test number	411553426173
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 21 September 2024
Tax status	Valid until 1 October
Days left	154
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	LAMP
Туре	
Damage 2	AMPLE
Damaye 2	e cut of
Date	*
Category	AMP
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



OU52UTT report date: 2024-03-29

Mileage check

In miles
25
2002-09-12
2023-09-15
See info



Registration #1	2002-09-12	23 mi
Registration #2	2006-04-25	23.662 mi
Registration #3	2006-08-07	25.915 mi
Registration #4	2007-07-23	32.723 mi
Registration #5	2008-07-22	39.504 mi
Registration #6	2009-07-16	46.040 mi
Registration #7	2010-07-01	54.414 mi
Registration #8	2010-07-02	54.418 mi
Registration #9	2011-06-14	59.525 mi
Registration #10	2012-06-25	65.945 mi
Registration #11	2013-06-25	71.278 mi
Registration #12	2014-06-11	77.373 mi
Registration #13	2015-06-23	81.541 mi
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.222 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.317 est
Registration #23		11.777 esi
Registration #24		11.777 esi
Registration #25		11.777 mi





Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
50566	
50567	
S0569	

Dimensions & weight

Width	2032 mm
Height	1470 mm
Length	4710 mm
Wheel base	2560 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2728667