



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D TS2 7STR
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg




LABEL UNKNOWN



Internet history

Entry 2



Date	2022-02-02
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-12
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #20</b>	2022-06-28 10:04
<b>MOT test number</b>	595378678714
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-07-05
<b>Advice</b>	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #19</b>	2021-06-08 09:37
<b>MOT test number</b>	269845861786
<b>Result</b>	✓ Passed
<b>MOT #18</b>	2020-07-06 10:36
<b>MOT test number</b>	619788601455
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect weak (5.3.2 (b))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect weak (5.3.2 (b))

<b>MOT #17</b>	2020-07-06 10:36
<b>MOT test number</b>	468907499701
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Front Position lamp not working side light (4.2.1 (a) (ii))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect weak (5.3.2 (b))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect weak (5.3.2 (b))

**MOT #16**

2019-06-18 11:27

**MOT test number**

328172732795

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #15**

2019-06-18 08:21

**MOT test number**

418849357401

**Result**

✗ Failed

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #14**

2018-06-21 10:55

**MOT test number**

600962407981

**Result**

✓ Passed

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement may require replacement soon -borderline at time of inspection (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement may require replacement soon -borderline at time of inspection (5.3.4 (a) (i))

**MOT #13**

2017-06-13 08:04

**MOT test number**

459675281838

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Offside Rear Shock absorber has little or no dampening effect

**Advice**

Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice**

Nearside Rear Shock absorber has little or no dampening effect

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #12**

2016-06-07 10:04

**MOT test number**

204787448220

**Result**

✓ Passed

**Advice**

Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**Advice**

Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #11**

2016-06-07 07:52

**MOT test number**

231806549035

**Result**

✗ Failed

**Fail**

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice**

Offside Rear Shock absorber has a light misting of oil (2.7.3)

**Fail**

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice**

Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #10** 2015-06-09 10:24**MOT test number** 627700965136**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front bumper offside insecure**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2014-06-10 11:05**MOT test number** 508661264107**Result** ✓ Passed**Advice** Offside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Advice** Nearside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**MOT #8** 2014-06-10 11:05**MOT test number** 928421764100**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Advice** Nearside Rear Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**MOT #7** 2013-06-18 10:28**MOT test number** 389309163112**Result** ✓ Passed**Notice** Both n/s tyres side wall damaged

**MOT #6** 2012-06-26 15:12**MOT test number** 489228572188**Result** ✓ Passed**MOT #5** 2012-06-26 10:42**MOT test number** 829938572164**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2011-06-21 12:28**MOT test number** 265962471482**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Advise cut nsf tyre outer wall**MOT #3** 2011-06-21 09:55**MOT test number** 938022571173**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Advise cut nsf tyre outer wall**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2010-06-22 09:11
MOT test number	301563570169
Result	✓ Passed

MOT #1	2010-06-22 09:11
MOT test number	484773470134
Result	✗ Failed

- Pass with rectification

Offside Headlamp aim too high (1.8)
- Pass with rectification

Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-30
Last registration	2022-06-28
Complete history	<a href="#">See info</a>



Registration #1	2007-06-30	13 mi
Registration #2	2010-06-22	17.932 mi
Registration #3	2011-06-21	24.143 mi
Registration #4	2011-06-21	24.143 mi
Registration #5	2012-06-26	30.648 mi
Registration #6	2012-06-26	30.648 mi
Registration #7	2013-06-18	36.004 mi
Registration #8	2014-06-10	42.874 mi
Registration #9	2015-06-09	49.742 mi
Registration #10	2016-06-07	56.142 mi
Registration #11	2016-06-07	56.142 mi
Registration #12	2016-06-07	56.142 mi
Registration #13	2016-06-07	56.142 mi
Registration #14	2016-06-07	56.142 mi
Registration #15	2016-06-07	56.142 mi
Registration #16	2016-06-07	56.142 mi
Registration #17	2016-06-07	56.142 mi
Registration #18	2016-06-07	56.142 mi
Registration #19	2016-06-07	56.142 mi
Registration #20	2016-06-07	56.142 mi
Registration #21	2016-06-07	56.142 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1645 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 261439