






report date: 2024-03-29

### General information

Make	NISSAN
Model	PATROL SE TD
Colour	Green
Year of manufacture	1999
Top speed	96 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	130 BHP
Max. torque	252 Nm at 2.000 rpm
Engine capacity	2.826 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.5 mpg
Consumption extra urban	29.7 mpg
Consumption combined	25.2 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-12-08

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



T530FFC report date: 2024-03-29

# MOT history

MOT expiry date	2025-04-26
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	56
Total items failed	9

MOT #20		2024-04-15 11:57
MOT test	number	519422252150
Result		✓ Passed
Next expi	ry date	2025-04-26
Advice	Nearside Front Inner sill corroding	
Advice	Oil leak, but not excessive engine and gearbox (8.4.1 (a) (i))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #19		2023-04-27 08:06
MOT test	number	196663362846
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Complete underside showing signs of surface corrosion	

MOT #18	2023-04-21 14:23
MOT test number	657676153950
Result	🗙 Failed
Advice Complete underside showing signs of surface corrosion	
Fail Nearside Front Shock absorbers likely to become detached (5.3.2 (a) (ii))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/15



**T530FFC**report date: 2024-03-29

**MOT #17** 2021-03-29 12:57

**MOT test number** 994261521359

**Result** ✓ Passed

**Advice** Rust/Corrosion to chassis members

**Advice** Rust/corrosion to nearside and offside front suspension components

**Advice** Rust/corrosion to rear suspension components

**MOT #16** 2021-03-16 09:57

MOT test number 834816031299

**Result** X Failed

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wheel arch inner (5.3.6 (a) (i))

**Advice** Rust/Corrosion to chassis members

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill area and inner (5.3.6 (a) (i))

**Advice** Rust/corrosion to nearside and offside front suspension components

**Advice** Rust/corrosion to rear suspension components

MOT #15 2020-03-31 15:31

**MOT test number** 747274072473

**Result** 
✓ Passed

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Rear brake readings only just met requirements

**Advice** Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** Underside of vehicle mixture of rust/corrosion and underseal

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #14** 2020-01-07 12:15

**MOT test number** 469364492698

Result

× Failed

**Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner wheel arch front (6.2.2 (d) (i))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Brake readings only just met requirements

Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

**Fail** Offside Front Shock absorbers likely to become detached has become detached (5.3.2 (a) (ii))

**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Fail** Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill area (7.1.1 (a) (i))

Advice Underside of vehicle mixture of rust/corrosion and underseal

**Fail** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting chassis member (6.2.2 (d) (i))

Fail Rear Brake load sensing valve seized but ABS functioning (1.1.17 (c) (i))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill area (7.1.1 (a) (i))

MOT #13 2019-01-08 12:22

MOT test number 470156068670

Result 

Passed

**Advice** Underside of vehicle heavily undersealed

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT test number

Result

Advice Front Brake pad(s) wearing thin o/s n/s (3.5.1g)

Advice Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice Rear Brake pad(s) wearing thin o/s n/s (3.5.1g)

Result

Advice Rear Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #11

MOT test number

Result

Advice Underside of vehicle heavily undersealed

MOT #10

MOT test number

Result

Advice General rust/corrosion to underside

Advice Brake pipe slightly corroded across rear axle (3.6.B.2c)

Advice Service brake only just meets readings

**MOT** #9 2014-12-19 13:35 **MOT** test number 449813554458 Result ✓ Passed **Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) Notice All four tyres in poor condition and sidewalls cracking Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) Notice General rust to underside and corrosion to components

CarCheck.co.uk page 6/15



**T530FFC**report date: 2024-03-29

MOT #8 2013-12-12 10:53

**MOT test number** 175726543334

**Advice** Brake pad(s) wearing thin (3.5.1g)

**Notice** Nearside and osf tyres in poor condition

**Notice** Back seats not fitted

MOT #7 2012-11-26 12:37

**MOT test number** 255251432346

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-11-11 13:00

**MOT test number** 826205211348

**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-10-26 10:45

**MOT test number** 190699190255

Result \( \sqrt{Passed} \)

Notice O/S FRONT TYRE CRACKINGON OUTER WALL

**Notice** REAR AXLE BRAKE PIPE RUSTY

Notice N/S FRONT WIPER SPLIT ON END

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #4		2009-10-26 13:58
MOT test	number	330119899483
Result		✓ Passed
Advice	Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #3		2008-09-15 15:11
MOT test	number	724059858219
Result		✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #2	2007-07-20 15:31
MOT test number	391351507202
Result	✓ Passed
MOT #1	2006-03-11 11:44
MOT test number	453810376058
Result	<b>✓</b> Passed


CarCheck.co.uk page 8/15



report date: 2024-03-29

26 April 2025

#### Tax & MOT check



**MOT** expiry date **Full MOT history** See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



T530FFC report date: 2024-03-29

Owner history

e union mestery	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this NISSAN had different number plates.	
See in this check if this Missain had different humber plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



**T530FFC**report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 13/15



T530FFC report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1999-03-22
Last registration	2024-04-15
Complete history	See info



Registration #1	1999-03-22	10 mi
Registration #2	2006-03-11	45.461 mi
Registration #3	2007-07-20	48.375 mi
Registration #4	2008-09-15	49.908 mi
Registration #5	2009-10-26	51.680 mi
Registration #6	2010-10-26	53.545 mi
Registration #7	2011-11-11	55.550 mi
Registration #8	2012-11-26	58.088 mi
Registration #9	2013-12-12	61.604 mi
Registration #10	2014-12-19	63.522 mi
Registration #11	2016-01-26	65.005 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Additional information

Fuel tank capacity	95 I
Fuel delivery	Indirect Injection
Number of doors	5
Engine number	492860

CarCheck.co.uk page 15/15