



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE V6 SIII
Colour	Grey
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	162 BHP
Max. torque	245 Nm at 4.000 rpm
Engine capacity	2.656 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.2 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.5 mpg
CO2 emission	236 g/km
CO2 label	L






Internet history

Entry 1

Date	2022-06-04
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-27
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	27
Total items failed	12

MOT #18	2023-11-28 12:56
MOT test number	106757322243
Result	✓ Passed
Next expiry date	2024-11-27

MOT #17	2022-10-18 13:35
MOT test number	673468328070
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust system corroded
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16**

2022-10-09 12:18

**MOT test number**

898376621785

**Result****✗ Failed**

- Fail** Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Brake hose damaged and likely to fail (1.1.12 (a))
- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Minor** Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))
- Fail** Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Exhaust system corroded

**MOT #15**

2021-09-29 16:28

**MOT test number**

543624188393

**Result****✓ Passed**

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14**

2021-09-29 09:43

**MOT test number**

337143113802

**Result****✗ Failed****Advice**

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Fail**

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail**

Brake performance not tested (1.2.1 (g))

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Fail**

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13**

2020-10-05 09:44

**MOT test number**

665646203255

**Result****✓ Passed****Advice**

O/S front of vehicle heavily damaged.

**Advice**

Just acceptable perishing to N/S rear tyre inner wall.

**Advice**

Surface corrosion under vehicle.

**Advice**

Handbrake just giving the required efficiency.

**Advice**

Under front of vehicle covered.

**Advice**

Heavy perishing to O/S rear tyre inner wall.

**Advice**

Exhaust system in poor condition.

**MOT #12**

2019-06-25 15:40

**MOT test number**

797288517574

**Result****✓ Passed**

**MOT #11** 2019-06-25 09:33**MOT test number** 239843014211**Result** ✗ Failed

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10** 2018-06-26 15:57**MOT test number** 106542569448**Result** ✓ Passed**MOT #9** 2017-06-20 09:35**MOT test number** 608509581532**Result** ✓ Passed

**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2017-06-19 08:59**MOT test number** 365664011255**Result** ✗ Failed

**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)



<b>MOT #7</b>	2016-06-27 08:59
<b>MOT test number</b>	731427218371
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2015-06-27 10:31
<b>MOT test number</b>	338848275127
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2014-06-17 10:22
<b>MOT test number</b>	105048064198
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2013-06-25 13:23
<b>MOT test number</b>	385526073137
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2012-06-26 14:33
<b>MOT test number</b>	215798572402
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2011-06-20 10:57
<b>MOT test number</b>	909991371161
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2010-06-18 17:00
<b>MOT test number</b>	681409660114
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-06-27
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2007-06-27	13 mi
Registration #2	2010-06-18	18.086 mi
Registration #3	2011-06-20	21.990 mi
Registration #4	2012-06-26	24.788 mi
Registration #5	2013-06-25	29.171 mi
Registration #6	2014-06-17	32.977 mi
Registration #7	2015-06-27	36.150 mi
Registration #8	2016-06-27	39.483 mi
Registration #9	2017-06-19	41.299 mi
Registration #10	2017-06-20	41.299 mi
Registration #11	2018-06-20	45.277 mi
Registration #12	2019-06-20	49.255 mi
Registration #13	2020-06-20	53.233 mi
Registration #14	2021-06-20	57.211 mi
Registration #15	2022-06-20	61.189 mi
Registration #16	2023-06-20	65.167 mi
Registration #17	2024-06-20	69.145 mi
Registration #18	2025-06-20	73.123 mi
Registration #19	2026-06-20	77.101 mi
Registration #20	2027-06-20	81.079 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1353 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G6BA6531319