



W526BAY

report date: 2024-03-28

General information

Make	MAZDA
Model	323 LXI
Colour	Red
Year of manufacture	2000
Top speed	104 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	108 Nm at 4.000 rpm
Engine capacity	1.324 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-29
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-07-23
MOT pass rate	61 %
MOT passed	17
Failed MOT tests	11
Total advice items	33
Total items failed	43

MOT #28 2021-07-23 16:15

MOT test number 466980837461

Result ✓ Passed

Next expiry date 2022-07-23

**Advice** Offside Rear Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))

**Advice** Subframe mounting repair covered in underseal all under body rears to fronts including brake pipes (5.3.6 (a) (i))

**Advice** Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security both outer sill rears inner and outers (6.2.2 (d) (i))

**Advice** Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner wng under bonnet (6.2.2 (d) (i))

MOT #27 2020-07-24 09:29

MOT test number 976622299101

Result ✓ Passed

**Advice** Brake pipe corroded, covered in grease or other material all over (1.1.11 (c))

**Advice** Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under body outer sill covered in under seal (6.2.2 (d) (i))

MOT #26 2019-04-04 09:21

MOT test number 100119454450

Result ✓ Passed

**MOT #25**

2019-04-04 09:21

**MOT test number**

905140605309

**Result****✗ Failed**

**Pass with rectification** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Pass with rectification** Offside Rear Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting outer sill back corner (6.2.2 (d) (i))

**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Pass with rectification** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #24**

2018-04-04 09:36

**MOT test number**

954055675729

**Result****✓ Passed**

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner arch (2.4.A.3)

**MOT #23**

2018-04-04 09:36

**MOT test number**

244370094913

**Result****✗ Failed**

**Pass with rectification** Nearside Rear Suspension component mounting prescribed area is excessively corroded outer sill (2.4.A.3)

**Pass with rectification** Nearside Rear Suspension component mounting prescribed area is deliberately modified which significantly reduces the original strength inner sill (2.4.A.3)

**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner arch (2.4.A.3)

**Pass with rectification** Offside Rear Suspension component mounting prescribed area is deliberately modified which significantly reduces the original strength outer sill (2.4.A.3)

**Pass with rectification** Offside Rear Suspension component mounting prescribed area is deliberately modified which significantly reduces the original strength inner sill (2.4.A.3)

**Pass with rectification** Registration plate insecure front (6.3.1b)

**MOT #22**

2017-04-12 10:09

**MOT test number**

293442258560

**Result**

✓ Passed

**Advice** Seat belt attachment fitting slightly deteriorated the vehicle is very dirty inside builders rubble all over seats and floor (5.2.3)

**Advice** Body has slight corrosion back half under body heavily under sealed (6.1.B.2)

**Advice** Offside Front Body has slight corrosion inner wing smart repair (6.1.B.2)

**MOT #21**

2017-04-12 10:09

**MOT test number**

290518581506

**Result**

✗ Failed

**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Offside Front Body has slight corrosion inner wing smart repair (6.1.B.2)

**Pass with rectification** Offside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings outer sill (6.1.B.2)

**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Seat belt attachment fitting slightly deteriorated the vehicle is very dirty inside builders rubble all over seats and floor (5.2.3)

**Pass with rectification** Nearside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings outer sill (6.1.B.2)

**Advice** Body has slight corrosion back half under body heavily under sealed (6.1.B.2)

**MOT #20**

2016-04-28 09:30

**MOT test number**

605392880645

**Result**

✓ Passed

**MOT #19** 2016-04-28 08:39**MOT test number** 147882969646**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #18** 2015-04-20 15:15**MOT test number** 729310615163**Result** ✓ Passed**Advice** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)**MOT #17** 2015-04-18 10:05**MOT test number** 366148305121**Result** ✗ Failed**Fail** Nearside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)**Advice** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)

**MOT #16**

2014-03-21 11:46

**MOT test number**

708270484066

**Result**

✓ Passed

**Notice**

Fuel tank corroded

**MOT #15**

2014-03-21 10:56

**MOT test number**

167120784099

**Result**

✗ Failed

**Notice**

Fuel tank corroded

**Fail**

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail**

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail**

Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #14**

2013-02-25 14:09

**MOT test number**

835106753055

**Result**

✓ Passed

**Notice**

O/s/r tyre starting to perish

**MOT #13**

2013-02-25 09:51

**MOT test number**

846146453034

**Result**

✗ Failed

**Fail**

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail**

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**Notice**

O/s/r tyre starting to perish

**Fail**

Nearside Stop lamp not working (1.2.1b)

**Fail**

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice**

Parking brake lever has little reserve travel (3.1.6b)

**MOT #12** 2012-02-22 16:00**MOT test number** 965993852099**Result** ✓ Passed**MOT #11** 2012-02-22 10:21**MOT test number** 515673052093**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Rear Tyre(s) incorrect because tyres with different aspect ratios are fitted on the same axle. (4.1.A.1a)
- Fail** Front brake application uneven (3.7.B.2)
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Fail** Offside Headlamp aim too high (1.8)

**MOT #10** 2011-02-28 17:13**MOT test number** 745929951029**Result** ✓ Passed

- Notice** N/s/r tyre starting to perish
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)
- Notice** Both front brake discs pitted



**MOT #9** 2010-02-11 13:57**MOT test number** 664392640079**Result** ✓ Passed**Notice** Slight damage to offside rear of vehicle**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #8** 2010-02-11 13:57**MOT test number** 724552540040**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Slight damage to offside rear of vehicle**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #7** 2009-07-16 12:29**MOT test number** 702227399102**Result** ✓ Passed**MOT #6** 2009-07-16 12:29**MOT test number** 472407999157**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #5** 2008-07-25 12:01**MOT test number** 912457208291**Result** ✓ Passed**MOT #4** 2007-07-26 16:23**MOT test number** 221917207270**Result** ✓ Passed



MOT #3	2007-07-26 12:52
MOT test number	741527807265
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage fractured (2.4.G.1)
Advice	Nearside Front Anti-roll bar linkage has slight play in a pin bearing (2.4.G.2)

MOT #2	2006-07-03 11:48
MOT test number	173954986158
Result	✓ Passed

MOT #1	2005-07-22 11:52
MOT test number	512433305255
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
24 August 2021

✕  
MOT

Expired:  
23 July 2022

Tax status	Expired at 24 August 2021
Days left	979 days too late
MOT expiry date	23 July 2022
Full MOT history	<a href="#">See MOT history</a>




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>W526BAY</b>
Plate since	2024-03-28
Current registration	<b>W526BAY</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2000-08-01
Last registration	2021-07-23
Complete history	<a href="#">See info</a>



Registration #1	2000-08-01	15 mi
Registration #2	2005-07-22	15.274 mi
Registration #3	2006-07-03	21.194 mi
Registration #4	2007-07-26	28.367 mi
Registration #5	2007-07-26	28.367 mi
Registration #6	2008-07-25	35.350 mi
Registration #7	2009-07-16	42.069 mi
Registration #8	2010-02-11	46.294 mi
Registration #9	2011-02-28	50.548 mi
Registration #10	2012-02-22	55.879 mi
Registration #11	2012-02-22	55.879 mi
Registration #12	2013-02-25	59.846 mi
Registration #13	2013-02-25	59.846 mi
Registration #14	2014-03-21	63.666 mi
Registration #15	2015-03-20	65.377 mi
Registration #16	2015-03-20	65.377 mi
Registration #17	2015-03-20	65.377 mi
Registration #18	2015-03-20	65.377 mi
Registration #19	2015-03-20	65.377 mi
Registration #20	2015-03-20	65.377 mi
Registration #21	2015-03-20	65.377 mi
Registration #22	2015-03-20	65.377 mi
Registration #23	2015-03-20	65.377 mi
Registration #24	2015-03-20	65.377 mi
Registration #25	2015-03-20	65.377 mi
Registration #26	2015-03-20	65.377 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)





Dimensions & weight

Width	1710 mm
Height	1355 mm
Length	4245 mm
Kerb weight	980 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	B3 742806