





report date: 2024-03-29

### General information

Make	FORD
Model	ESCORT RS TURBO
Colour	Grey
Year of manufacture	1990
Top speed	128 mph
0 - 60 mph	8.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	132 BHP
Max. torque	24 Nm at 2.750 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Petrol



CarCheck.co.uk page 1/14



G165ALO report date: 2024-03-29

## Internet history

#### Entry 3

Date 2021-12-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-10-22	
-----------------	--

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2	0	2	]	L-	.0	7	-3	3(	J

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

## MOT history

MOT expiry date	2023-11-15
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	42
Total items failed	26

MOT #20	2022-11-16 17:03
MOT test number	438875391039
Result	✓ Passed
Next expiry date	2023-11-15
Advice Nearside Front Suspension component mounting prescribed area is con excessive (5.3.6 (a) (i))	rroded but not considered
Advice Nearside Rear Brake pipe corroded, covered in grease or other materia	al (1.1.11 (c))
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is no (6.1.1 (c) (i))	t significantly reduced
Advice Offside Front Suspension component mounting prescribed area is correct excessive (5.3.6 (a) (i))	oded but not considered
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #19	20	21-01-29 09:37
MOT test	number	940748689016
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Slightly long travel on brake pedal	

CarCheck.co.uk page 3/14



**Advice** 

G165ALO

report date: 2024-03-29

MOT #18 2021-01-06 16:30

936933486351 **MOT** test number Result × Failed Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Nearside Headlamp insecure (4.1.1 (c)) Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Horn not working (7.7 (a) (ii)) Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) Fail Windscreen washer not working (3.5 (a)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

 MOT #17
 2020-05-29 14:29

 MOT test number
 521697496294

 Result
 X Failed

CarCheck.co.uk page 5/14

Advice Nearside Front inner sill / floor corroded (outside prescribed areas)

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Rear chassis rail corroded

**Fail** Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis rail (5.3.6 (a) (i))

Fail Nearside Front Suspension component mounting prescribed area is inadequately repaired front panel (5.3.6 (a) (i))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated cracking (6.1.7 (g) (i))

**Advice** Offside Front inner sill / floor corroded (outside prescribed areas)

**Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

**Fail** Nearside Headlamp insecure (4.1.1 (c))

**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

**Advice** Coolant leak

**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength floor (5.3.6 (a) (i))

**Fail** Offside Front Suspension component mounting prescribed area is inadequately repaired front panel (5.3.6 (a) (i))

Minor Nearside Rear Brake hose slightly chafed (1.1.12 (b) (i))



G165ALO report date: 2024-03-29

**X** Failed

MOT #16 2017-06-19 16:12

**MOT test number** 960345936865

**Advice** O/s/r brake pipes corroded

**MOT #15** 2017-06-19 15:47

MOT test number 807868312089

Fail Offside Headlamp not working on dipped beam (1.7.5a)

**Advice** O/s/r brake pipes corroded

Result

**MOT #14** 2016-06-02 15:41

MOT test number 497119752030

**Result** 
✓ Passed

**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #13 2015-03-18 16:41

**MOT test number** 939287675075

CarCheck.co.uk page 6/14



G165ALO report date: 2024-03-29

MOT #12 2015-03-18 12:33

MOT test number 915317775065

Result X Failed

**Fail** Steering wheel locking device insecure (2.1.6)

**Fail** Exhaust emissions hydrocarbon content excessive (7.3.B.1b)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

**Fail** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Notice** Engine missfire

**MOT #11** 2014-02-11 16:53

**MOT test number** 315972444054

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**Notice** Plastic sill covers fitted not allowing full inspection

**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 7/14



Advice

**G165ALO** 

report date: 2024-03-29

MOT #10	2014-02-10 12:21
MOT test number	175431844401
Result	<b>×</b> Failed
Fail Speedometer clearly inoperative (6.7.2)	
<b>Advice</b> Offside Rear Suspension component mounting prescribed area is corroded but excessive (2.4.A.3)	not considered
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice Plastic sill covers fitted not allowing full inspection	
<b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded but excessive (2.4.A.3)	ıt not considered

Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #9	2013-02-09 10:58
MOT test number	515720243036
Result	✓ Passed
MOT #8	2012-01-30 11:15
MOT test number	857390532073
Result	✓ Passed
MOT #7	2011-01-28 11:34
MOT test number	968468921045
Result	✓ Passed
MOT #6	2010-02-01 09:12
MOT test number	132332230456
Result	✓ Passed
MOT #5	2009-01-31 16:01
MOT test number	140521039478
Result	✓ Passed

CarCheck.co.uk page 8/14



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

Fail

Exhaust emissions carbon monoxide content excessive (7.3.B.1a)

Advice

Offside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

Fail

Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #3	2008-02-05 11:34
MOT test number	690146738042
Result	✓ Passed
MOT #2	2007-01-22 14:11
MOT test number	341162527038
Result	✓ Passed
Notice Nearside rear chassis rail corroded (not holed)	

MOT #1	2006-01-30 10:35
MOT test number	454220036057
Result	✓ Passed

CarCheck.co.uk page 9/14



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did check it in the premium report and see all owner registrations. Download the full report h	
********	
************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



G165ALO report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1990-02-20
Last registration	2022-11-16
Complete history	See info



Registration #1	1990-02-20	18 mi
Registration #2	2006-01-30	23.593 mi
Registration #3	2007-01-22	29.808 mi
Registration #4	2008-02-05	35.841 mi
Registration #5	2009-01-30	40.792 mi
Registration #6	2009-01-31	40.792 mi
Registration #7	2010-02-01	45.151 mi
Registration #8	2011-01-28	47.815 mi
Registration #9	2012-01-30	5.104 mi
Registration #10	2013-02-09	54.176 mi
Registration #11	2014-02-10	55.977 mi
Registration #12	2014-02-11	55.977 mi
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71,777 es

More info >



G165ALO report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	******
Video	see crash video



# Dimensions & weight

Width	1641 mm
Height	1308 mm
Length	4062 mm

## Additional information

Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	LT79072

CarCheck.co.uk page 14/14