





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | AMICA GSI |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 91 mph |
| 0 - 60 mph | 15.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 62 BHP |
|-------------------------|--------------------|
| Max. torque | 97 Nm at 3.000 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 52.3 mpg |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-01


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT #16 2023-03-20 15:24

MOT test number 236635563678

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))

Fail Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

Fail Nearside Rear Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired wheel arch (6.2.2 (d) (ii))

Fail Offside Rear Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))

MOT #15 2022-03-12 09:35

MOT test number 775436636698

Result \sqrt{Passed}

Advice Central Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))

Advice Showings signs of corrosion underneath

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Heavily undersealed underneath

CarCheck.co.uk page 3/12



report date: 2024-03-28

| MOT #14 | 2 | 2021-02-05 17:52 |
|----------|--|------------------|
| MOT test | number | 381778343305 |
| Result | | ✓ Passed |
| Advice | Underside shows signs of general corrosion | |
| Advice | Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c)) | |

| Advice Underside shows signs of general corrosion | |
|---|------------------|
| Advice Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c)) | |
| | |
| MOT #13 | 2020-02-08 08:59 |
| MOT test number | 365387727206 |
| Result | ✓ Passed |
| MOT #12 | 2019-02-08 11:59 |
| MOT test number | 852435814345 |
| Result | ✓ Passed |
| MOT #11 | 2018-02-10 11:14 |
| MOT test number | 868393729360 |
| Result | ✓ Passed |
| MOT #10 | 2017-02-15 11:33 |
| MOT test number | 524271970326 |
| Result | ✓ Passed |
| MOT #9 | 2017-02-15 08:21 |
| MOT test number | 280586027563 |
| Result | X Failed |
| Fail Offside Front Brake pipe excessively corroded (3.6.B.2c) | |

| MOT #9 | 2017-02-15 08:21 |
|---|------------------|
| MOT test number | 280586027563 |
| Result | X Failed |
| Fail Offside Front Brake pipe excessively corroded (3.6.B.2c) | |
| Fail Nearside Rear Fuel pipe leaking (7.2.3) | |

CarCheck.co.uk page 4/12



report date: 2024-03-28

| MOT #8 | 2016-02-23 09:38 |
|--|------------------|
| MOT test number | 609828292794 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2015-02-17 09:43 |
| MOT test number | 987798045050 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2015-02-17 08:49 |
| MOT test number | 458538145007 |
| Result | × Failed |
| Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) | |

| MOT #5 | 2014-02-13 09:05 |
|--|------------------|
| MOT test number | 185854244496 |
| Result | ✓ Passed |
| Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) | |

| MOT #4 | | 2013-02-27 10:05 |
|-------------------------|---|------------------|
| MOT test number | | 795598853018 |
| Result | | ✓ Passed |
| | | |
| MOT #3 | | 2013-02-27 10:05 |
| MOT test number | | 438798253001 |
| Result | | X Failed |
| Pass with rectification | Offside Rear Stop lamp not working (1.2.1b) | |

| MOT #2 | 2012-02-15 09:14 |
|-----------------|------------------|
| MOT test number | 778956342023 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #1 2011-02-19 15:09
MOT test number 525840351014

Result ✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| processor . | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | |
| Current registration | OK SIE |
| Plate since | |
| Current registration | UK NEZ |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2008-03-03 |
| Last registration | 2023-03-20 |
| Complete history | See info |



| Registration #1 | 2008-03-03 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2011-02-19 | 31.839 mi |
| Registration #3 | 2012-02-15 | 37.101 mi |
| Registration #4 | 2013-02-27 | 42.139 mi |
| Registration #5 | 2014-02-13 | 47.334 mi |
| Registration #6 | 2015-02-17 | 52.214 mi |
| Registration #7 | 2015-02-17 | 52.214 mi |
| Registration #8 | 2016-02-23 | 56.383 mi |
| Registration #9 | 2017-02-15 | 61.139 mi |
| Registration #10 | | 11.117 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 ea |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| S0569 | |

Dimensions & weight

| Width | 1525 mm |
|---------------------|---------|
| Height | 1570 mm |
| Length | 3565 mm |
| Wheel base | 2380 mm |
| Kerb weight | 1007 kg |
| Max. allowed weight | 1336 kg |

Additional information

| Fuel tank capacity | 35 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | G4HG7M300131 |

CarCheck.co.uk page 12/12