





General information

| Make | HYUNDAI |
|---------------------|-----------------------------|
| Model | 140 CRDI PREMIUM BLUE DRIVE |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 124 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 325 Nm at 2.750 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-01-31 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-02-01 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 9 |
| Failed MOT tests | 3 |
| Total advice items | 28 |
| Total items failed | 5 |

| MOT #12 | 2024-01-25 10:35 |
|--|---|
| MOT test number | 530578394648 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-01 |
| Minor Offside Rear Registration plate lamp inoperative in the o (4.7.1 (b) (i)) | case of multiple lamps or light sources |
| Advice Offside Rear Tyre slightly damaged/cracking or perishi | ng Outer sidewall (5.2.3 (d) (ii)) |
| Advice Front Registration plate deteriorated but not likely to b | e misread (0.1 (b)) |
| Advice Offside Rear Tyre worn close to legal limit/worn on edg | je Tyre tread at 2mm (5.2.3 (e)) |
| Advice Play in steering rack inner joint(s) | |
| Advice Underside of vehicle has some corrosion | |





| MOT #11 | | 2023-01-16 10:18 |
|----------|--|------------------|
| MOT test | number | 970174968504 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 205 60 16 92 v (5.2.3 $$ | (e)) |
| Advice | Offside Front Tyre has slight wear on the inner edge | |
| Advice | Nearside Front Tyre has slight damage to the outer sidewall | |
| Advice | Underside of vehicle has some corrosion | |
| Advice | Nearside Front Tyre has slight wear on the inner edge | |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| MOT #10 | | 2022-02-02 11:51 |
|----------|--|------------------|
| MOT test | number | 690426665367 |
| Result | | ✓ Passed |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Offside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Rear Registration plate insecure but not likely to fall off (0.1 (a)) | |
| Advice | Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |





| MOT #9 | 2022-02-01 10:28 |
|---|------------------|
| MOT test number | 901373341913 |
| Result | 🗙 Failed |
| Advice Offside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i)) | |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Fail Nearside Front Tyre has ply or cords exposed Inner edge worn 205/60R16 92V (5.2.3) | 3 (d) (ii)) |
| Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Rear Registration plate insecure but not likely to fall off (0.1 (a)) | |
| Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a)) | |

| MOT #8 | 2021-01-28 17:11 |
|-----------------|------------------|
| MOT test number | 919015175110 |
| Result | ✓ Passed |

| MOT #7 | 2020-03-03 17:47 |
|--|---------------------------|
| MOT test number | 569627438899 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge worn | on inner edge (5.2.3 (e)) |

| MOT #6 | 2019-03-14 14:47 |
|--|------------------|
| MOT test number | 840485786846 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge | (5.2.3 (e)) |





| MOT #5 | 2019-03-14 10:21 |
|---|------------------------|
| MOT test number | 677651922838 |
| Result | 🗙 Failed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to read (5.2.3 (d) (i)) | ch the ply or cords |
| FailOffside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingra(ii)) | ess of dirt (5.3.4 (b) |
| MOT #4 | 2018-03-09 15:29 |
| MOT test number | 479668029898 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to the legal limit 3mm - 205/60r16 92v (4.1.E. | 1) |
| | |
| MOT #3 | 2018-03-09 09:45 |
| MOT test number | 600232599196 |
| Result | 🗙 Failed |

Advice Nearside Rear Tyre worn close to the legal limit 3mm - 205/60r16 92v (4.1.E.1)

FailNearside Front Track rod end ball joint has excessive play (2.2.B.1f)

| MOT #2 | | 2017-03-08 12:52 |
|----------|--|------------------|
| MOT test | number | 829154570159 |
| Result | | 🗸 Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) | |

| MOT #1 | 2016-03-24 09:21 |
|-----------------|------------------|
| MOT test number | 322255023721 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 January 2025 | ✓ MOT Expires: 1 February 2025 |
|--|---|
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 1 February 2025 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------------|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| Damage 2 | E E H - S - A |
| Date | * |
| Category | AMP. |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| 2000000 | |
|--|-------------|
| ****** | |
| ******** | |
| | |
| 1000000 | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2013-03-31 |
| Last registration | 2024-01-25 |
| Complete history | See info |



| Registration #1 | 2013-03-31 | 28 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2016-03-24 | 62.205 mi |
| Registration #3 | 2017-03-08 | 79.781 mi |
| Registration #4 | 2018-03-09 | 98.803 mi |
| Registration #5 | 2018-03-09 | 98.803 mi |
| Registration #6 | 2019-03-14 | 115.799 mi |
| Registration #7 | 2019-03-14 | 115.799 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | |
| | | |
| Registration #10 | | 11.777 est |
| Registration #10 Registration #11 | | 11.777 est 11.777 est |
| - | | 11.227 est 11.227 est 11.227 est |
| Registration #11 | | 11.777 est 11.777 est 11.777 est 11.777 est |





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 0566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1815 mm |
| Height | 1470 mm |
| Length | 4770 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1638 kg |
| Max. allowed weight | 2120 kg |
| Additional information | |
| Fuel tank capacity | 70 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |

Engine number

D4FDDU271854