





General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 DCB
Colour	Black
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg





Internet history

Entry	1

Date Pictures 2021-06-08

13

Listing price

View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-27
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	50
Total items failed	25

МОТ #20	2024-03-28 14:01
MOT test number	934160978405
Result	✓ Passed
Next expiry date	2025-03-27
Advice Central exhaust poor	
Advice Repairs to rear chassis	
Advice Offside Rear shock mount repaired	
Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice Rear chassis has been undersealed	





MOT #19	2024-03-22 14:50
MOT test number	494900284477
Result	× Failed
Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assems significantly reduced (6.1.1 (c) (i))	ıbly is
Advice Repairs to rear chassis	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice Offside Rear shock mount repaired	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear chassis has been undersealed	
Fail Fuel system component leaking (6.1.3 (b) (i))	
Advice Central exhaust poor	





MOT #18 20	24-02-17 09:20
MOT test number	163079042404
Result	🗙 Failed
Fail Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly significantly reduced (6.1.1 (c) (i))	is
Advice Chassis has multiple repairs and is corroded in multiple places overall chassis is in vertice condition	ery poor
Fail Vehicle structure inadequately repaired such that structural rigidity is significantly reduce welding repairs not completely welded around repair plate (6.1.1 (d) (i))	ced various
Fail Nearside Front Service brake lagging in operation (1.2.1 (d))	
Fail Front Brakes imbalanced across an axle 37% (1.2.1 (b) (i))	
Fail Nearside Headlamp aim too high (4.1.2 (a))	
Fail Windscreen washer not working (3.5 (a))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Fail Rear Brakes imbalanced across an axle by more than 50% 69% (1.2.1 (b) (ii))	
Fail Offside Rear Service brake lagging in operation (1.2.1 (d))	
Fail Power steering malfunctioning steering rough and powersteering belt squealing as steer (2.1.5 (a))	ring operated

MOT #17		2023-02-21 10:49
MOT test	number	898439157398
Result		✓ Passed
Advice	Play in steering rack inner joint(s)	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	



NU10ZGR report date: 2024-03-29

MOT #16	2023-02-21 10:49	
MOT test number	485100803434	
Result	× Failed	
Advice Offside Front An	ti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Play in steering rack inner joint(s)		
Pass with rectificationRear Registration plate lamp inoperative in the case of a single lamp or all lamps(4.7.1 (b) (ii))		
MOT #15	2022-05-04 11:11	
MOT #15 MOT test number	2022-03-04 11.11	
Result	✓ Passed	

MOT #14	2022-05-04 10:08
MOT test number	727790076999
Result	🗙 Failed
Fail Offside Track rod end ball joint worn to the extent there is a serious risk	k of detachment (2.1.3 (b) (ii))

MOT #13	2021-05-08 12:48
MOT test number	485430207290
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases flexy pipe broken (6.1.2 (a))	





MOT #12	2020-03-25 17:01
MOT test number	221945417605
Result	✓ Passed
Advice Offside Front Suspension component mounting prescribed area is corroded excessive (5.3.6 (a) (i))	but not considered
Advice Offside Rear Suspension component mounting prescribed area is corroded be excessive (5.3.6 (a) (i))	out not considered
Advice Nearside Front Suspension component mounting prescribed area is corrode excessive (5.3.6 (a) (i))	d but not considered
Advice Nearside Rear Suspension component mounting prescribed area is corroded excessive (5.3.6 (a) (i))	d but not considered
Minor Registration plate lamp inoperative in the case of multiple lamps or light sou	rces (4.7.1 (b) (i))
Advice Exhaust system corroded	
MOT #11	2020-03-14 15:18
MOT test number	713666790933

MOT test number	713666790933
Result	🗙 Failed
Advice Offside Front Suspension component mounting prescribed area excessive (5.3.6 (a) (i))	a is corroded but not considered
Advice Offside Rear Suspension component mounting prescribed area excessive (5.3.6 (a) (i))	is corroded but not considered
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Minor Registration plate lamp inoperative in the case of multiple lamp	s or light sources (4.7.1 (b) (i))
Advice Exhaust system corroded	
Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Advice Nearside Front Suspension component mounting prescribed are excessive (5.3.6 (a) (i))	ea is corroded but not considered
Advice Nearside Rear Suspension component mounting prescribed are excessive (5.3.6 (a) (i))	ea is corroded but not considered
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (k	o) (i))
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Front Brake pipe excessively corroded x3 (1.1.11 (c))	





MOT #10		2019-03-09 16:36
MOT test	number	167432123030
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

МОТ #9	2019-03-09 16:36
MOT test number	673562617188
Result	🗙 Failed
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #8		2018-03-10 14:24
MOT test	number	231068687418
Result		✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	





MOT #7	2018-03-07 13:56
MOT test number	634139762582
Result	🗙 Failed
Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
FailNearside Rear Leaf spring fractured (2.4.B.1a)	
Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Fail Offside Rear Leaf spring fractured (2.4.B.1a)	

МОТ #6	2017-03-09 16:53
MOT test number	371579262475
Result	✓ Passed

MOT #5	2016-03-08 17:09
MOT test number	155225408895
Result	✓ Passed

MOT #4		2015-03-25 12:00
MOT test	number	337884885077
Result		✓ Passed
Advice (2.5.C.1a)	Nearside Outer Front constant velocity joint gaiter deteriorated, but p	preventing the ingress of dirt
Advice (2.5.C.1a)	Offside Outer Front constant velocity joint gaiter deteriorated, but pr	eventing the ingress of dirt

MOT #3		2014-04-02 15:24
MOT test	number	389952294083
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Advice (2.5.C.1a)	Offside Outer Front constant velocity joint gaiter damaged, but preventing the ing	gress of dirt
Notice	Items removed from driver's view prior to test	






MOT #2	2014-04-02 10:52
MOT test number	176132694076
Result	🗙 Failed
 Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Notice Under-trays fitted obscuring some underside components Advice Offside Outer Front constant velocity joint gaiter damaged, but preventing (2.5.C.1a) Notice Items removed from driver's view prior to test 	the ingress of dirt
MOT #1	2013-04-17 12:15
MOT test number 166017003114	
Result	🗸 Passed

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



NU10ZGR report date: 2024-03-29

Tax & MOT check







Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
	E Stand
Date	N. Sterring and a start of the
Category	ame
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-04-16
Last registration	2024-03-28
Complete history	See info



Registration #1	2010-04-16	10 mi
Registration #2	2013-04-17	30.226 mi
Registration #3	2014-04-02	40.107 mi
Registration #4	2014-04-02	40.107 mi
Registration #5	2015-03-25	51.183 mi
Registration #6	2016-03-08	62.373 mi
Registration #7	2017-03-09	79.998 mi
Registration #8	2018-03-07	98.636 mi
Registration #9	2018-03-10	98.639 mi
Registration #10	2019-03-09	110.920 mi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.117 mi
Registration #20		11.777 est







Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	73584B