





report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO GL
Colour	Blue
Year of manufacture	-
Top speed	90 mph
0 - 60 mph	15.2 seconds
Gearbox	3 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	85 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/13



LC06YBT

report date: 2024-03-28


Internet history

Entry 2

Date 2023-02-15

Pictures 4

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-06-05
Pictures	16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT #19	2022-07-08 12:22
MOT test number	651964533237
Result	✓ Passed
Next expiry date	2023-07-23
Advice Front body damage poorly repaired, head light bracket broken	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Exhaust system poor conditon	

MOT #18		2021-06-30 16:05
MOT test	number	552997800708
Result		✓ Passed
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7	' (g) (i))

CarCheck.co.uk page 3/13



MOT #17 2021-06-30 10:06

MOT test number 713635202289

Result X Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #16 2020-06-24 14:20

MOT test number 951226180877

MOT #15 2020-06-24 14:20

MOT test number 924555157014

Result ★ Failed

Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14 2019-07-08 10:58

MOT test number 143482216838

Result

Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



LC06YBT

report date: 2024-03-28

MOT #13 2018-06-28 14:37 605617356843 **MOT** test number Result ✓ Passed **MOT #12** 2017-07-24 10:33 **MOT** test number 225932390959 Result ✓ Passed **Advice** Exhaust has a minor leak of exhaust gases (7.1.2) **Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Oil leak **Advice**

MOT #11 2017-07-12 08:39 **MOT** test number 474037797103 Result × Failed Fail Nearside Headlamp insecure (1.7.3) **Advice** Oil leak Fail Nearside Registration plate lamp not working (1.1.C.1d) Advice Exhaust has a minor leak of exhaust gases (7.1.2) **Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1) Fail Offside Front position lamp(s) not working (1.1.A.3b)

MOT #10

MOT test number

959951406392

Result

Advice Exhaust corroded

CarCheck.co.uk page 5/13



LC06YBT

report date: 2024-03-28

MOT #9	2016-05-28 11:54
MOT test number	452686722778
Result	≍ Failed
Pass with rectification Nearside Stop lamp not working (1.2.1b)	
Advice Exhaust corroded	

MOT #8	2015-06-09 08:36
MOT test number	839640965143
Result	✓ Passed
MOT #7	2014-06-11 08:51
MOT test number	479532564153
Result	✓ Passed
MOT #6	2013-06-12 08:39
MOT test number	928453863136
Result	✓ Passed
MOT #5	2012-06-13 08:50
MOT test number	385445662159
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2011-06-16 08:58
MOT test number	289767561186
Result	✓ Passed

CarCheck.co.uk page 6/13



MOT #3

Result

LC06YBT report date: 2024-03-28

2010-06-16 11:48

X Failed

MOT test number 933567060100

Result ✓ Passed

Advice Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #2 2010-06-14 15:20

MOT test number 113925260180

Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Offside Real Shock absorber has a serious hala leak (2.7.5)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Rear Stop lamp not working (1.2.1b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1 2009-06-16 11:06

MOT test number 552637069188

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra SUZUKI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when miscory	
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	UK SIFE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-05-26
Last registration	2022-07-08
Complete history	See info



Registration #1	2006-05-26	18 mi
Registration #2	2009-06-16	2.680 mi
Registration #3	2010-06-14	14.458 mi
Registration #4	2010-06-16	14.510 mi
Registration #5	2011-06-16	28.779 mi
Registration #6	2012-06-13	37.136 mi
Registration #7	2013-06-12	48.465 mi
Registration #8	2014-06-11	33.297 mi
Registration #9	2015-06-09	67.114 mi
Registration #10	2016-05-28	75.004 mi
Registration #11	2016-05-28	75.004 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1475 mm
Height	1455 mm
Length	3495 mm
Wheel base	2360 mm
Kerb weight	815 kg
Max. allowed weight	1165 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	F10DN 3208428

CarCheck.co.uk page 13/13