



N432HAB

report date: 2024-03-29

General information

Make	MAZDA
Model	BONGO
Colour	Black
Year of manufacture	1996
Gearbox	-

Engine & fuel consumption

Engine capacity	2.490 cc
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-20
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-09
MOT pass rate	57 %
MOT passed	16
Failed MOT tests	12
Total advice items	98
Total items failed	15

MOT #28	2023-12-09 13:25
MOT test number	621865573522
Result	✓ Passed
Next expiry date	2024-12-09
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))

MOT #27	2023-12-05 10:04
MOT test number	407373914648
Result	✗ Failed
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sills. both sides (6.1.1 (c) (i))
MAJOR	Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))

**MOT #26** 2022-12-10 08:42**MOT test number** 549151333831**Result** ✓ Passed**MOT #25** 2022-12-06 17:24**MOT test number** 768225413163**Result** ✗ Failed

**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced BOTH SIDES , corroding (6.1.1 (c) (i))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Front Play in steering rack inner joint(s)

**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #24** 2022-01-11 11:56**MOT test number** 543565747916**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Non obligatory mirror damaged

**Advice** Offside Front fog lamp not working



MOT #23	2022-01-11 11:56
MOT test number	172059626316
Result	✗ Failed
Advice	Nearside Non obligatory mirror damaged
Advice	Offside Front fog lamp not working
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #22	2020-11-11 09:12
MOT test number	215410696811
Result	✓ Passed

MOT #21	2020-08-12 07:32
MOT test number	270472496234
Result	✓ Passed

**MOT #20**

2020-06-24 09:41

**MOT test number**

197142526498

**Result****✗ Failed**

**MAJOR** Offside Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill x2 (6.2.2 (d) (i))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Outer sill (5.3.6 (a) (i))

**MAJOR** Offside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill x2 (6.2.2 (d) (i))

**Advice** Underside + body corroded in places

**MAJOR** Front Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced Crossmember (6.1.1 (c) (i))

**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner sill (6.2.2 (d) (i))

**MOT #19**

2019-05-21 10:01

**MOT test number**

244968551046

**Result****✓ Passed**

**Advice** Rear n/s o/s rear tyres cracking

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #18** 2019-05-16 09:59**MOT test number** 697551352038**Result** ✗ Failed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))**Advice** Rear n/s o/s rear tyres cracking**MOT #17** 2018-05-21 10:09**MOT test number** 653885422157**Result** ✓ Passed**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Central Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #16** 2018-05-10 12:12**MOT test number** 114032726589**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter split (2.2.D.2d)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)**Advice** Central Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)



MOT #152017-07-04 09:49

MOT test number110533402917

Result

✓ Passed

- Advice

Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice

Offside Front inner sill corroded
- Advice

Offside Front Inner sill corroded
- Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice

Offside Outer sill corroded
- Advice

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)





## MOT #14

2017-06-28 12:15

### MOT test number

820655036935

### Result

✗ Failed

**Fail** Offside Rear Inner Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)

**Advice** Offside Outer sill corroded

**Fail** Offside front brake binding (3.7.B.1)

**Fail** Offside Rear Inner Suspension component mounting prescribed area is excessively corroded arch (2.4.A.3)

**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Offside Front inner sill corroded

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Front Inner sill corroded

**Fail** Nearside Rear Inner Suspension component mounting prescribed area is excessively corroded arch (2.4.A.3)

**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**Fail** Rear fog lamp not working (1.3.2b)

## MOT #13

2016-05-05 14:58

### MOT test number

706941794539

### Result

✓ Passed

**Advice** Surface corrosion all brake discs

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)

**Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive crossmember (2.4.A.3)

**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive both inner sills (2.4.A.3)



**MOT #12**

2016-04-29 15:58

**MOT test number**

802431955278

**Result****✗ Failed**

- Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)
- Advice** Surface corrosion all brake discs
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive crossmember (2.4.A.3)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive both inner sills (2.4.A.3)

**MOT #11**

2014-10-01 09:20

**MOT test number**

859934574213

**Result****✓ Passed**

- Advice** Nearside Headlamp damaged but light output not reduced (1.7.5a)
- Notice** Corrosion offside rear sill outside prescribed area
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #10**

2014-09-30 14:30

**MOT test number**

696483474210

**Result****✗ Failed**

- Advice** Nearside Headlamp damaged but light output not reduced (1.7.5a)
- Notice** Corrosion offside rear sill outside prescribed area
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #9** 2013-11-18 15:36**MOT test number** 146152823305**Result** ✓ Passed

**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Corrosion offside rear sill

**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2013-11-08 10:27**MOT test number** 809322713355**Result** ✗ Failed

**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Corrosion offside rear sill

**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Inner Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**Advice** Offside Inner Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2012-10-19 16:15**MOT test number** 716973592287**Result** ✓ Passed

**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)



**MOT #6** 2012-10-06 10:55**MOT test number** 929720582253**Result** ✗ Failed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Rear fog lamp not working (1.3.2b)**MOT #5** 2011-10-07 15:55**MOT test number** 217270981269**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #4** 2011-09-29 12:13**MOT test number** 658172271205**Result** ✗ Failed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Fail** Nearside front parking brake recording little or no effort (3.7.B.6a)**MOT #3** 2010-10-02 12:05**MOT test number** 482095270247**Result** ✓ Passed



MOT #2	2009-09-28 16:38
MOT test number	472411379266
Result	✓ Passed
<div>NoticeBoth Headlamps Starting To Deteriate</div>	

MOT #1	2008-07-17 13:20
MOT test number	213549798479
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
9 December 2024

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	9 December 2024
Full MOT history	<a href="#">See MOT history</a>






Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	29
First mileage registration	2008-07-17
Last registration	2023-12-09
Complete history	<a href="#">See info</a>



Registration #1	2008-07-17	72.838 mi
Registration #2	2009-09-28	124.648 mi
Registration #3	2010-10-02	128.897 mi
Registration #4	2011-09-29	131.016 mi
Registration #5	2011-10-07	131.032 mi
Registration #6	2012-10-06	133.362 mi
Registration #7	2012-10-19	133.381 mi
Registration #8	2013-11-08	140.931 mi
Registration #9	2013-11-18	141.021 mi
Registration #10	2014-09-30	92.920 mi
Registration #11	2014-10-01	92.920 mi
Registration #12	2016-04-29	94.772 mi
Registration #13	2016-05-05	94.773 mi
Registration #14	2017-06-28	96.211 mi
Registration #15	2017-07-04	96.212 mi
Registration #16	2019-05-29	95.557 mi
Registration #17	2019-05-29	95.557 mi
Registration #18	2019-05-29	95.557 mi
Registration #19	2019-05-29	95.557 mi
Registration #20	2019-05-29	95.557 mi
Registration #21	2019-05-29	95.557 mi
Registration #22	2019-05-29	95.557 mi
Registration #23	2019-05-29	95.557 mi
Registration #24	2019-05-29	95.557 mi
Registration #25	2019-05-29	95.557 mi
Registration #26	2019-05-29	95.557 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Additional information

Engine number	NOT KNOWN
---------------	-----------