



report date: 2024-03-28

General information

Make	SUZUKI
Model	WAGON-R+ JLX PLUS
Colour	Green
Year of manufacture	2006
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





MOT history

MOT expiry date	2020-10-10
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	19
Total items failed	18

MOT #122021-07-12 11:27

MOT test number227920446776

Result	Failed
Fail	Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Rear Seat belt not functioning as intended (7.1.2 (c))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Offside Rear Seat belt not functioning as intended (7.1.2 (c))
Fail	Offside Front Obligatory mirror does not provide a view to the rear (3.3 (c))

**MOT #11**

2021-05-11 08:02

MOT test number

414932241055

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Seat belt missing (7.1.2 (a))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Front Obligatory mirror does not provide a view to the rear (3.3 (c))

MOT #10

2019-04-01 17:02

MOT test number

667533245999

Result

✓ Passed

- Advice** Drivers seat slightly insecure

MOT #9

2018-04-11 14:43

MOT test number

315281053958

Result

✓ Passed

- Advice** Vehicle under-body has surface rust
- Advice** O/s front seat has been modified
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (3.5.1i)
- Advice** Exhaust system corroded
- Advice** Vehicle suspension components corroded

**MOT #8**

2018-04-11 13:23

MOT test number

542316923306

Result

✗ Failed

Advice Vehicle under-body has surface rust**Advice** O/s front seat has been modified**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Exhaust system corroded**Advice** Front brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (3.5.1i)**Advice** Vehicle suspension components corroded**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7**

2015-07-09 09:04

MOT test number

276170595187

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** All 4 tyres perished**Notice** Exhaust corroded**Notice** Abs rings corroded**MOT #6**

2014-07-17 10:14

MOT test number

315598894103

Result

✓ Passed

**MOT #5** 2013-03-25 08:42**MOT test number** 186534783043**Result** ✓ Passed**MOT #4** 2012-02-24 10:30**MOT test number** 108995052476**Result** ✓ Passed**Notice** Vehicle totally adapted for disability purposes**MOT #3** 2012-02-16 14:51**MOT test number** 718037942045**Result** ✗ Failed**Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Notice** Vehicle totally adapted for disability purposes**MOT #2** 2011-02-11 13:51**MOT test number** 978952041047**Result** ✓ Passed**MOT #1** 2010-02-24 11:32**MOT test number** 330655150020**Result** ✓ Passed**Notice** This is a disable motorbilty car o/s front seat locks into a special locking frame.This seat locks from going front to back but can slide from side to side. The chair does come out for wheel chair to be locked in place



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2006-10-13
Last registration	2021-07-12
Complete history	See info



Registration #1	2006-10-13	17 mi
Registration #2	2010-02-24	2.969 mi
Registration #3	2011-02-11	4.339 mi
Registration #4	2012-02-16	5.199 mi
Registration #5	2012-02-24	5.199 mi
Registration #6	2013-03-25	6.007 mi
Registration #7	2014-07-17	6.010 mi
Registration #8	2015-05-20	17.000 mi
Registration #9	2016-05-20	17.000 mi
Registration #10	2017-05-20	17.000 mi
Registration #11	2018-05-20	17.000 mi
Registration #12	2019-05-20	17.000 mi
Registration #13	2021-07-12	17.000 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	M13A-1809534