





### General information

| Make                | VOLVO          |
|---------------------|----------------|
| Model               | V50 D S        |
| Colour              | Grey           |
| Year of manufacture | 2007           |
| Top speed           | 130 mph        |
| 0 - 60 mph          | 8.9 seconds    |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 134 BHP             |
|-------------------------|---------------------|
| Max. torque             | 340 Nm at 2.000 rpm |
| Engine capacity         | 1.998 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 37.7 mpg            |
| Consumption extra urban | 62.8 mpg            |
| Consumption combined    | 50.4 mpg            |
| CO2 emission            | 153 g/km            |
| CO2 label               | G                   |





# MOT history

| MOT expiry date    | 2021-11-03 |
|--------------------|------------|
| MOT pass rate      | 69 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 5          |
| Total advice items | 33         |
| Total items failed | 8          |

| MOT #16   | 2020-11-02 08:58 |
|---|------------------|
| MOT test number   | 459498933978     |
| Result  | ✓ Passed         |
| Next expiry date  | 2021-11-03       |
| Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |                  |

| MOT #15                 |   | 2020-11-02 08:58 |
|-------------------------|---|------------------|
| MOT test number         |   | 797212384089     |
| Result                  |   | 🗙 Failed         |
| Pass with rectification | Headlamp aim too low Both Sides (4.1.2 (a))                     |                  |
| Advice Nearside Rear A  | nti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) |                  |

| MOT #14  |   | 2019-10-17 09:42 |
|----------|---|------------------|
| MOT test | number  | 638977749907     |
| Result   |   | ✓ Passed         |
| Advice   | Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))  |                  |
| Advice   | Front Registration plate deteriorated but not likely to be misread (0.1 (b))      |                  |
| Advice   | Nearside Front Shock absorbers light misting of oil or has limited damping effect | (5.3.2 (b))      |





| MOT #13  | 2019-10-17 07:19 |
|--|------------------|
| MOT test number  | 596856950405     |
| Result   | 🗙 Failed         |
| <b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))      |                  |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))      |                  |
| Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))  |                  |
| <b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))       |                  |
| Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect | t (5.3.2 (b))    |

| MOT #12    |   | 2018-11-03 13:13 |
|------------|---|------------------|
| MOT test n | umber   | 505421651159     |
| Result     |   | ✓ Passed         |
|            | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))<br>Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
|            | onside from fyre worn close to regul innig worn on edge (5.2.5 (c))   |                  |

| MOT #11         | 2017-10-10 14:53 |
|-----------------|------------------|
| MOT test number | 956136718754     |
| Result          | ✓ Passed         |

| MOT #10                     |   | 2016-10-24 15:26     |
|-----------------------------|---|----------------------|
| MOT test                    | number  | 465612611477         |
| Result                      |   | ✓ Passed             |
| Advice                      | Cant check rear seat belts due to child seat fitted                                   |                      |
| Advice                      | Outer rear brake pads getting low   |                      |
| Advice                      | Exhaust silencer outer skin rotting   |                      |
| <b>Advice</b><br>50% (1.1.4 | Nearside Rear Upper Rear position lamp(s) has light sources not illuminating<br>4.3b) | g, but not more than |





| MOT #9   |   | 2016-10-24 15:26           |
|--|---|----------------------------|
| MOT test number  |   | 965612323421               |
| Result   |   | 🗙 Failed                   |
| Advice Nearside Rear U<br>50% (1.1.A.3b)                             | pper Rear position lamp(s) has light sources not illumi                 | inating, but not more than |
| Advice Cant check rear   | seat belts due to child seat fitted                                     |                            |
| Advice Outer rear brake  | pads getting low  |                            |
| Pass with rectificationilluminating (1.1.A.3b)AdviceExhaust silencer | Nearside Front Front position lamp(s) has less than souter skin rotting | 50% of the light sources   |

| MOT #8   |   | 2015-10-26 14:49 |
|----------|---|------------------|
| MOT test | number  | 727589945295     |
| Result   |   | ✓ Passed         |
| Advice   | Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)                      |                  |
| Advice   | Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.      | .la)             |
| Advice   | Offside Rear tyre excessively stepped   |                  |
| Advice   | Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)                       |                  |
| Advice   | Nearside Rear tyre bold on inner edge close to cords                                |                  |
| Advice   | Nearside Rear child seat fitted unable to carry out full inspection to adult seatbe | lt               |

| МОТ #7   | 2014-11-04 16:36 |
|--|------------------|
| MOT test number                                | 857798304353     |
| Result   | Passed           |
| Notice Exhaust badly corroded but not blowing. |                  |





| MOT #6  | 2013-10-15 12:18 |
|---|------------------|
| MOT test number   | 327108583250     |
| Result  | ✓ Passed         |
| <b>Notice</b> Child seat fitted not allowing full inspection of adult belt          |                  |
| MOT #5  | 2012-10-23 10:48 |
| MOT test number   | 475357392201     |
| Result  | ✓ Passed         |
| <b>Notice</b> Rear exhaust heatshield is insecure.                                  |                  |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |                  |
| <b>Notice</b> Child seat fitted not allowing full inspection of adult belt          |                  |

| MOT #4  | 2012-10-23 10:48   |  |
|---|--|--|
| MOT test number   | 846237692270   |  |
| Result  | × Failed   |  |
| Pass with rectification   | Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |  |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |  |  |
| <b>Notice</b> Rear exhaust heatshield is insecure.                                  |  |  |
| Pass with rectification   | Offside Rear Lower Rear position lamp(s) not working (1.1.A.3b)                  |  |
| Notice Child seat fitted not allowing full inspection of adult belt                 |  |  |

| MOT #3          | 2011-10-28 11:28 |
|-----------------|------------------|
| MOT test number | 415431801496     |
| Result          | ✓ Passed         |





| MOT #2                  | 2011-10-28 11:28   |
|-------------------------|--|
| MOT test number         | 225641001328   |
| Result                  | × Failed   |
| Pass with rectification | Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a) |
| Pass with rectification | Nearside Headlamp aim beam image kick up to the offside (1.8)              |

| MOT #1   | 2010-10-13 15:14 |
|--|------------------|
| MOT test number  | 880486280200     |
| Result   | ✓ Passed         |
| Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3) |                  |





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |          |
|----------|----------|
| Date     | FEIDO    |
| Category | 4 ARAPE  |
| Туре     |          |
| Damage 2 | AMPL     |
|          | F Stores |
| Date     | 1.E      |
| Category | ante     |
| Туре     |          |

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.11.111 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 11 711 |





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ***********  |             |
| ********   |             |
| *******  |             |
| **********   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLVO had different number plates.   |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2007-10-31 |
| Last registration          | 2020-11-02 |
| Complete history           | See info   |



| Registration #1  | 2007-10-31 | 16 mi      |
|------------------|------------|------------|
| Registration #2  | 2010-10-13 | 38.624 mi  |
| Registration #3  | 2011-10-28 | 46.587 mi  |
| Registration #4  | 2012-10-23 | 52.075 mi  |
| Registration #5  | 2013-10-15 | 60.433 mi  |
| Registration #6  | 2014-11-04 | 72.427 mi  |
| Registration #7  | 2015-10-26 | 84.295 mi  |
| Registration #8  | 2016-10-24 | 98.018 mi  |
| Registration #9  |            | 11.777 est |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 mi  |
| Registration #14 |            | 11.777 esi |
| Registration #15 |            | 11.777 mi  |





### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1770 mm          |
| Height                            | 1452 mm          |
| Length                            | 4468 mm          |
| Wheel base                        | 2640 mm          |
| Kerb weight                       | 1457 kg          |
| Max. allowed weight               | 1940 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 52               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 4                |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12     |

| Number of axles | 2      |
|-----------------|--------|
| Engine number   | 130531 |